



CYCLE &amp; CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD  
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel 65684555 Fax: 65651240



Co Reg No : 199405410K

## ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	/Hagley Nigel Tak-King
	Reg No/Reg Date	SLM8806D / 17/04/201
	Date In/Mileage	/ 85314
	Chassis No	KNAFX411MH5696968
	Engine No	G4FGGH667636
	Make/Model	KIA/CERATO K3 1.6 A EX
	Colour/Trim	MST METAL STREAM / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	30/03/2021/ 13:11	QUD	247 / DonBong	31335	Qty	Unit Price	Disc% Amount
Description of Goods / Services								
E PNT88000								2000.00
RENEW ACCIDENT DAMAGED PART ON FRONT SUPPORT PANEL, 3-5 X 400 add repair white house								
FRONT BONNET, RH FRONT FENDER, REPAIR RH FRONT DOOR,								100.00
REPAIR LH FRONT FENDER								
E PNT88000								80.00
REMOVE AND INSTALL RADIATOR AND A/CON CONDENSER								
M SUNDRY								
TOP UP A/CON GAS AND CHECK A/CON SYSTEM								2100.00
E PNT98000								
PAINT WORK SPRAY FRONT BONNET, FRONT BUMPER, RH FRONT FENDER, 4 X 350 add spray white								
RH FRONT DOOR, LH FRONT FENDER AND AFFECTED PORTION								80.00
M SUNDRY								30.00
APPLY BODY SEALANT								
A 54900099								80.00
CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM								
M SUNDRY								120.00
PERFORM RUST PREVENTION								
A 10028901								400.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								
USING HI-SCAN PRO TEST								
A 33900099								120.00
REPLACE FRT U/CARRIAGE DAMAGES								
A WHEELALIGNMENTBP								400.00
To Conduct Computerize Full Wheel Alignment								
M SUNDRY								30.00
SUPPLY RH FRONT SPORT RIM SSW266								
M SUNDRY								50.00
LABOUR RENEW RH FRONT SPORT RIM INCLUDING BALANCING								
M SUNDRY								
SUNDRIES						1.00	675.00 20.00	540.00
M CARRIER ASSY-FRONT END MODULE / BR						1.00	125.00 20.00	100.00
M RESERVOIR & PUMP ASSY-WASHER / BR						1.00	1707.00 20.00	1365.60
M LAMP ASSY-HEAD, RH / BR								

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD  
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

## ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /Hagley Nigel Tak-King Reg No/Reg Date SLM8806D / 17/04/201 Date In/Mileage / 85314 Chassis No KNAFX411MH5696968 Engine No G4FGGH667636 Make/Model KIA/CERATO K3 1.6 A EX Colour/Trim MST METAL STREAM / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	30/03/2021/ 13:11	QUD	247 / DonBong	31335			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
					1.00	34.00	20.00	27.20
M HINGE ASSY-HOOD,RH	?	X AN			1.00	34.00	20.00	27.20
M HINGE ASSY-HOOD,LH	?	X AN			1.00	1384.00	20.00	1107.20
M PANEL ASSY-HOOD	00				1.00	141.00	20.00	112.80
M PAD-HOOD INSULATING	X ANI				1.00	35.00	20.00	28.00
M ROD ASSY-HOOD STAY	X ANI				1.00	65.00	20.00	52.00
M LATCH ASSY-HOOD	X ANI				1.00	28.00	20.00	22.40
M INSULATOR-FENDER RH	?	X AN			1.00	435.00	20.00	348.00
M PANEL-FENDER,RH	00				1.00	13.00	20.00	10.40
M BRACKET-FR BUMPER SIDE MTG,LH	X ANI				1.00	13.00	20.00	10.40
M BRACKET-FR BUMPER SIDE MTG,RH	OR				1.00	496.00	20.00	396.80
M RAIL ASSY-FR BUMPER	X ANI				1.00	114.00	20.00	91.20
M STIFFNER-FR BPR LWR	X ANI				1.00	84.00	20.00	67.20
M ABSORBER-FRONT BUMPER ENERGY	X ANI				1.00	91.00	20.00	72.80
M MOULDING-FRONT BUMPER A/INTAKE	?	X AN			1.00	29.00	20.00	23.20
M STRIP ASSY-FR BUMPER UPR	X ANI				1.00	54.00	20.00	43.20
M GARNISH-RADIATOR GRILLE,UPR	X ANI				1.00	328.00	20.00	262.40
M GRILLE ASSY-RADIATOR	?	X AN			2.00	1.00	20.00	1.60
M RETAINER-BUMPER SIDE MTG	X ANI				1.00	633.00	20.00	506.40
M COVER-FR BUMPER	OR				1.00	55.00	20.00	44.00
M LIP ASSY-FRONT BUMPER	?	X AN			1.00	6.00	20.00	4.80
M DUCT ASSY-AIR CURTAIN,RH	?	X AN			1.00	33.00	20.00	26.40
M AIR DUCT-FR BUMPER,RH	?	X AN			1.00	241.00	20.00	192.80
M LAMP ASSY-FRONT FOG,RH	?	X AN			1.00	32.00	20.00	25.60
M ORNAMENT-KIA NO.115	AK				1.00	380.00	20.00	304.00
M ARM COMPLETE-FR LWR,RH	BT				1.00	23.00	20.00	18.40
M STAY RH	?	X AN			1.00	1330.00	20.00	1064.00
M CROSSMEMBER COMPL	?	BT			1.00	280.00	20.00	224.00
M STRUT ASSY-FR,RH	?	BT			1.00	54.00	20.00	43.20
M BEARING-STRUT	?	X AN			1.00	42.00	20.00	33.60
M PAD-FRONT SPRING,UPR	?	X AN			1.00	93.00	20.00	74.40
M INSULATOR ASSY-STRUT	?	X AN			1.00	72.00	20.00	57.60
M LINK-STABILIZER	BT				1.00	832.00	20.00	665.60
M GEAR ASSY-STEERING	?	X AN						

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD  
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

## ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /Hagley Nigel Tak-King Reg No/Reg Date SLM8806D / 17/04/201 Date In/Mileage / 85314 Chassis No KNAFX411MH5696968 Engine No G4FGGH667636 Make/Model KIA/CERATO K3 1.6 A EX Colour/Trim MST METAL STREAM / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAI00000	Credit	30/03/2021/ 13:11	QUD	247 / DonBong	31335			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M HUB ASSY-FR WHEEL			X	nn	1.00	150.00	20.00	120.00
M BEARING-FRONT WHEEL HUB			X	nn	1.00	131.00	20.00	104.80
M RING-SNAP			X	nn	1.00	11.00	20.00	8.80
M KNUCKLE-FRONT AXLE, RH			X	nn	1.00	350.00	20.00	280.00

# Estimate

SURVEYOR NAME: Steve (LKK) 30/3/21, 2:30pm  
 SURVEYOR SIGNATURE: OO-MAAL  
 DATE: EXPRS - ?  
 REMARKS: P/P, My Blay  
11 days

LKK Auto Consultants hence notify  
the Reparer of the following:

- Confirm & accepted by \_\_\_\_\_
- Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Authorized signatory and company stamp

	Nett	14,098.00
7% GST on	14098.00	986.86
Total Payable		15,084.86

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.