

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21004066/KPA3Q2
Date: 02/09/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210027879
Claimant Vehicle No :	GBH8999A	Insured Vehicle No :	SMY6860J
Date of Loss:	25/03/2021	Nature of Claim:	TP
		Claim No:	0796880487SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBH8999A	Engine No:	1KD2610364
Make & Model:	TOYOTA DYNA 150, 3.0 D (M)	Chassis No:	JTFAT35Y00K206412
Reg. Date:	07/09/2016 (Man. Year: 2016)	Odometer:	133574 km
Colour:	Silver		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195 R15X8	Rear Tyre Size:	155 R12X8 (D)
Front Left Side:	Double Star 8 mm	Rear Left Side:	Double Star 5/5 mm
Front Right Side:	Double Star 8 mm	Rear Right Side:	Double Star 5/5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,818.25	2,444.50	15,373.75	86.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,430.00	1,115.00	3,315.00	74.83
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,248.25	3,559.50	18,688.75	84.00
Approved Total (Overridden) (S\$)		2,800.00		

	(S\$)	22,248.25	2,800.00	19,448.25	87.41
+ GST 7.00/7.00% (S\$)		1,557.38	196.00	1,361.38	87.41
Nett Amount (S\$)		23,805.63	2,996.00	20,809.63	87.41
+ Loss of Use (4.0 x S\$120.00/day) (S\$)			480.00		
+ Doc/Search Fee (S\$)			2.00		
Nett Liability (S\$)			3,478.00		

INSPECTION

Date of Assignment: 30/03/2021

Date Inspected: 05/04/2021

Inspected At:

MBM Wheelpower Pte Ltd (Sin Ming)
 176 Sin Ming Drive #01-15, Sin Ming AutoCare
 Singapore 575721

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SIDE BOARD RH	Repair	1,043.00 FL	*- FL
2	1		*SIDE BOARD HINGE RH	Repair	500.00 FL	*- FL
3	1		*SIDE BOARD LOCK RH	Distorted	176.00 FL	*176.00 FL
4	1		*POWER TAIL GATE (LOCAL REPAIR)	Dented	12,000.00 FS	*1,500.00 FS
5	1		*POWER TAIL GATE CHAIN LOCKER LH	Repair	412.00 FS	*- FS
6	1		*POWER TAIL GATE CHAIN LOCKER RH	Repair	412.00 FS	*- FS
7	1		*TAIL LAMP HOLDER LH	Repair	564.00 FS	*- FS
8	1		*TAIL LAMP HOLDER RH	Bent	564.00 FS	*564.00 FS
9	1		*TAIL LAMP LH	Serviceable	287.00 FS	*- FS
10	1		*TAIL LAMP RH	Serviceable	287.00 FS	*- FS
11	1		*HYDRAULIC OIL (50%)	Necessary	153.00 FS	*76.50 FS
12	1		*STICKER -SIDE BOARD UNIQUE MOTORSPORTS PTE LTD LH	Not Necessary	160.00 FS	*- FS
13	1		*STICKER -SIDE BOARD UNIQUE MOTORSPORTS PTE LTD RH	Necessary	160.00 FS	*160.00 FS
14	1		*STICKER -POWER TAILGATE UNIQUE MOTORSPORTS	Not Necessary	130.00 FS	*- FS
15	1		*STICKER -POWER TAILGATE 70KM/H	Necessary	50.00 FS	*12.00 FS
16	1		*STICKER -POWER TAILGATE BREAKDOWN HOTLINE 87818999	Not Necessary	50.00 FS	*- FS
17	1		*SIDE RAILING LH	Repair	250.00 FS	*- FS
18	1		*SIDE RAILING RH	Repair	250.00 FS	*- FS
19	1		*CHECKER PLATE -SIDE BOARD RH	Repair	800.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	18,248.00	2,488.50
- List Item Discount on L Items 25.00/25.00% (\$)	429.75	44.00
Total Parts (\$)	17,818.25	2,444.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & REFIT POWER TAILGATE	New	2,300.00	700.00
2	TO REMOVE & REFIT TAIL LAMP HOLDER	New	250.00	120.00
3	TO REMOVE & REFIT POWER TAILGATE CHAIN LOCKER	New	250.00	0.00
4	TO REMOVE & REFIT SIDE BOARD STICKER	New	100.00	30.00
5	TO REMOVE & REFIT SIDE BOARD CHECKER PLATE TO FACILITATE REPLACEMENT	New	150.00	0.00
6	TO REMOVE & REFIT POWER TAILGATE HOSES & REFILL HYDRAULIC OIL	New	180.00	0.00
7	TO REMOVE & REFIT CENTER TAILGATE EXTENSION TO FACILITATE REPLACEMENT	New	150.00	0.00
8	TO CHECK & RECONNECT ALL NECESSARY WIRING	New	50.00	15.00
9	TO SPRAY PAINT ON THE AFFECTED AREAS	New	1,000.00	250.00
			Gross Labour Cost (\$\$)	1,115.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >