

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

LOON YEOW WAI
BLK 443 JURONG WEST AVE 1 #05-736
SINGAPORE 640443

Contact : 91838736

TP chin
Xiao Chen

ESTIMATE

Repair Code : CLM15215

Date in : 27/03/2021

Vehicle Num. : SJN9426D

Model : HONDA CITY LX 1.5 I-VTEC AUTO

Chassis/Eng# : MRHGM26709P020220/L15A71801870

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
AIRCON CONDENSER Bent	1	445.50	✓ 445.50
AIRCON CONDENSER DISCHARGE HOSE } Bent	1	103.20	✓ 103.20
AIRCON CONDENSER LIQUID PIPE	1	107.95	✓ 107.95
AIRCON FAN BLADE New	1	44.40	x 44.40
AIRCON FAN COWLING Cracked	1	83.50	✓ 83.50
AIRCON FAN MOTOR Damaged	1	195.00	✓ 195.00
AIRCON SUCTION HOSE Not new	1	103.85	x 103.85
ALTERNATOR ASSY Cracked	1	677.80	✓ 677.80
FRONT BONNET Distorted	1	455.62	✓ 455.62
FRONT BONNET HINGES L/R Bent	2	46.20	✓ 92.40
FRONT BONNET LOCK Damaged	1	142.40	✓ 142.40
FRONT BUMPER Distorted	1	505.80	✓ 505.80
FRONT BUMPER AIR GUIDE GARNISH New	1	15.20	x 15.20
FRONT BUMPER REINFORCEMENT Distorted	1	179.50	✓ 179.50
FRONT FENDER L/R RH Buckled	2	297.60	29760 595.20
FRONT GRILLE Cracked	1	98.10	✓ 98.10
FRONT GRILLE 'H' LOGO New	1	25.80	✓ 25.80
FRONT GRILLE OUTER GARNISH Cracked	1	166.85	✓ 166.85

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

LOON YEOW WAI
BLK 443 JURONG WEST AVE 1 #05-736
SINGAPORE 640443

Contact : 91838736

ESTIMATE

Repair Code : CLM15215

Date in : 27/03/2021

Vehicle Num. : SJN9426D

Model : HONDA CITY LX 1.5 I-VTEC AUTO

Chassis/Eng# : MRHGM26709P020220/L15A71801870

FRONT HEADLAMP L/R	LH cruld, RH Smashed	2	356.50	✓	713.00
FRONT HEADLAMP LOWER BRACKET L/R	RH cruld	2	30.20	30.20	60.40
FRONT RH FENDER QUARTER GARNISH	new	1	40.50	X	40.50
FRONT SUPPORT PANEL	Buckled	1	371.80	✓	371.80
FRONT WIPER GARNISH COVER L/R	new	2	16.00	X	32.00
RADIATOR ASSY (A)	cracked	1	1272.60	✓	1,272.60
RADIATOR FAN BLADE	new	1	56.90	X	56.90
RADIATOR FAN COWLING	cruld	1	98.23	✓	98.23
RADIATOR FAN MOTOR	Damaged	1	321.20	✓	321.20
RADIATOR SPARE TANK	new	1	46.50	X	46.50
REAR BOOTLID	Repair	1	407.75	X	407.75
REAR BOOTLID 'CITY' EMBLEM		1	17.85	✓	17.85
REAR BOOTLID 'H' LOGO		1	19.50	✓	19.50
REAR BOOTLID 'I-VTEC' EMBLEM		1	24.45	✓	24.45
REAR BOOTLID GUIDE RUBBER PROTECTOR L/R		2	8.50	X	17.00
REAR BOOTLID INNER TRIM COVER		1	79.80	X	79.80
REAR BOOTLID MECHANISM LOCK		1	62.50	X	62.50
REAR BOOTLID RUBBER SEAL		1	81.85	X	81.85

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

LOON YEOW WAI

BLK 443 JURONG WEST AVE 1 #05-736

SINGAPORE 640443

Contact : 91838736

ESTIMATE

Repair Code : CLM15215

Date in : 27/03/2021

Vehicle Num. : SJN9426D

Model : HONDA CITY LX 1.5 I-VTEC AUTO

Chassis/Eng# : MRHGM26709P020220/L15A71801870

REAR BUMPER	<i>Deformed</i>	1	510.05	✓	510.05
REAR BUMPER SIDE CLIPS L/R	<i>new</i>	4	8.20	✓	32.80
REAR BUMPER SIDE RETAINER L/R	<i>new</i>	2	15.80	✓	31.60
REAR END PANEL	<i>Dented</i>	1	366.90	✓	366.90
REAR END PANEL INNER TOP GARNISH	<i>Deformed</i>	1	73.30	✓	73.30
REAR SPARE TYRE INNER TOP BOARD COVER	<i>new</i>	1	77.80	+	77.80
REAR TAILLAMP GASKET SEAL L/R	<i>new</i>	2	11.90	✓	23.80
REAR TAILLAMP L/R	<i>cracked</i>	2	226.20	✓	452.40
Subtotal before discount					9,330.55
Percentage discount 20%					1,866.11
Sub-total 1					7,464.44
FRONT BUMPER CLIPS - SET	<i>new</i>	1	50.00	30	50.00
FRONT GRILLE CLIPS - SET		1	50.00	30	50.00
FRONT NUMBER PLATE	<i>Dented</i>	1	50.00	30	50.00
FRONT NUMBER PLATE HOLDER	<i>Deformed</i>	1	50.00	30	50.00
FRONT RH FENDER QUARTER GARNISH CLIPS - SET	<i>Not new</i>	1	20.00	X	20.00
FRONT WEEKEND SEAL BRACKET	<i>new</i>	1	80.00	20	80.00
REAR BOOTLID INNER TRIM COVER CLIPS - SET	<i>Not new</i>	1	50.00	X	50.00

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

LOON YEOW WAI
BLK 443 JURONG WEST AVE 1 #05-736
SINGAPORE 640443

Contact : 91838736

ESTIMATE

Repair Code : CLM15215

Date in : 27/03/2021

Vehicle Num. : SJN9426D

Model : HONDA CITY LX 1.5 I-VTEC AUTO

Chassis/Eng# : MRHGM26709P020220/L15A71801870

REAR BUMPER CLIPS - SET <i>New</i>	1	50.00	<i>30</i>	50.00
REAR BUMPER REVERSE SENSOR - SET <i>Damaged</i>	1	250.00	<i>200</i>	250.00
REAR END PANEL INNER TOP GARNISH CLIPS - SET <i>New</i>	1	20.00	<i>10</i>	20.00
REAR NUMBER PLATE <i>3 years</i>	1	50.00	<i>400</i>	50.00
REAR NUMBER PLATE HOLDER	1	50.00	<i>X</i>	50.00
REAR TAILLAMP CLIPS L/R - SET <i>all</i>	2	20.00	<i>20</i>	40.00
Subtotal before discount				810.00
Percentage discount 0%				0.00
Sub-total 2				810.00
Parts-total				8,274.44

LABOUR

To remove, change air con parts, vacuums, refill air con gas.

To remove, reinstall electrical wiring harness, check lighting, resetting headlamp focussing and rewire for parking sensor.

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare tyre panel and rear bumper.

To re-spray painting on the front bonnet, front support panel, front fender (L/R), front bumper and front doors (L/R).

To remove and reinstall exhaust pipe.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

Labour Total

Parts & Labour Total

5,530.00

13,804.44

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*** This is a computer-generated document which requires no signature. ***

page 4

8.6K

12 Days

total: 10802.32

H/S: 8.6K.