

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Busk Reg No: 199502604-E GST No: 19-9502604-E

SM/SMT34T/2103029

29th March 2021

The Manager
Motor Claim Department
MS First Capital Insurance Ltd
36 Robinson Rd
#16-01 City House
Singapore 068877

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Authorised
1/4/21

2/12/21

4-5 days

the photo is for painting

Date of Accident : 27th March 2021

Location : Bukit Timah Road Slip Road to Farrer Road

Third Party Claim Vehicle No : GBF 6882 B

Repair Cost For Vehicle No : SMT 34 T Porsche Panamera

Estimate Supply of Parts & Labours

No.	Particulars	Qty	Price	Amounts
1	Rear boot cover <i>DD/leaf</i>	1	4,485.00	\$ 4,485.00 ✓
2	Rear boot cover spoiler <i>11</i>	1	1,125.00	\$ 1,125.00 X
3	Rear boot windscreen with moulding <i>11</i>	1	2,220.00	\$ 2,220.00 X
4	Rear boot emblem "Porsche" <i>11</i>	1	260.00	\$ 260.00 ✓
5	Rear bumper fascia <i>DD</i>	1	2,700.00	\$ 2,700.00 ✓
6	Rear bumper clips <i>11</i>	1set	40.00	\$ 40.00 ✓
7	Rear bumper side retainer L&RH <i>11</i>	2	78.00	\$ 156.00 X
8	Rear bumper towing cover <i>DD</i>	1	57.00	\$ 57.00 ✓
9	Rear bumper reinforcement beam	1	1,200.00	\$ 1,200.00 ?
10	Rear bumper lower lip <i>DD</i>	1	1,200.00	\$ 1,200.00 ✓
11	Rear bumper lower lip parking sensor L&RH	2	270.00	\$ 540.00 ?
12	Rear bumper reflector RH <i>CM</i>	1	87.00	\$ 87.00 ✓
13	Exhaust silencer RH <i>11</i>	1	3,300.00	\$ 3,300.00 X
14	Exhaust muffler RH <i>leaf</i>	1	870.00	\$ 870.00 ✓
				<u>\$18,240.00</u>

SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SMT34T/2103029

29th March 2021

Balance b/f \$18,240.00

Labour Charges :-

	<u>Amounts</u>
Remove & refix rear windscreen glass	\$ 250.00 150
Remove & refix rear bot inner furnisher, garnish, trimming, trunk lid board, rear boot central locking, mechanism lock, all affected parts & etc	\$ 350.00 200
Remove & refix, knocking, straighten & re-align rear bumper, rear trunk lid cover, all affected parts & etc	\$ 1,800.00 1000
Spray painting on damage parts	\$ 1,200.00 900
Tuff-kote on damage parts	\$ 80.00 30
Diagnostic & reset after repairs	\$ 380.00 200
Check all lighting & wiring after repairs	\$ 120.00 20

Labour Charge \$ 4,180.00

Total Amount \$22,420.00

GST will be reflected in the final bills.

Notes : -Please inform us within 14 days, from the date of this letter, in the event that the owner/driver is in breach of its policy with your company, failing which we shall hold your company liable for all costs of repairs, loss of use and storage.