

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

NEYASHAN .
 BLK 25 TANGLIN HALT ROAD #04-38
 SINGAPORE 140025

Contact : 98584251, 87484317

ESTIMATE

Repair Code : CLM15216

Date in : 29/03/2021

Vehicle Num. : SJM4517M

Model : MITSUBISHI LANCER 1.6 M

Chassis/Eng# : JMYSNCS3A8U007556/4G18JT5758

TP AXA
 Jasper

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BOOTLID <i>Dented</i>	1	652.30	✓ 652.30
REAR BOOTLID 'GLX' EMBLEM	1	35.20	✓ 35.20
REAR BOOTLID 'LANCER' EMBLEM	1	39.60	✓ 39.60
REAR BOOTLID LOGO	1	50.10	✓ 50.10
REAR BOOTLID MECHANISM LOCK <i>Damaged</i>	1	76.60	✓ 76.60
REAR BOOTLID NUMBER PLATE GARNISH <i>Cracked</i>	1	216.70	✓ 216.70
REAR BOOTLID RUBBER STOPPER L/R <i>Not new</i>	2	15.00	X 30.00
REAR BOOTLID WEATHER STRIP SEAL <i>cut</i>	1	165.00	✓ 165.00
REAR BUMPER <i>Deformed</i>	1	772.20	✓ 772.20
REAR BUMPER BEAM <i>Best</i>	1	184.80	✓ 184.80
REAR BUMPER SIDE RETAINER L/R <i>new</i>	2	55.00	✓ 110.00
REAR END PANEL <i>Dented</i>	1	547.80	✓ 547.80
REAR END PANEL INNER TOP GARNISH <i>Deformed</i>	1	191.00	✓ 191.00
REAR EXHAUST RUBBER MOUNTING <i>Not new</i>	3	28.00	X 84.00
REAR FENDER INNER TRIM GARNISH L/R <i>torn</i>	2	233.20	✓ 466.40
REAR SPARE TYRE PANEL <i>Repis</i>	1	940.00	X 940.00
REAR SPARE TYRE PANEL TOP BOARD COVER <i>torn</i>	1	355.30	165 X 355.30
REAR TAILLAMP L/R <i>Cracked</i>	2	421.00	668 X 842.00

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200714616M

GST Registration No. : 200714616M

NEYASHAN .

BLK 25 TANGLIN HALT ROAD #04-38

SINGAPORE 140025

Contact : 98584251, 87484317

ESTIMATE

Repair Code : CLM15216

Date in : 29/03/2021

Vehicle Num. : SJM4517M

Model : MITSUBISHI LANCER 1.6 M

Chassis/Eng# : JMYSNCS3A8U007556/4G18JT5758

REAR TAILLAMP PANEL L/R	NEW	4340.70	2	83.60	X	167.20
Subtotal before discount						5,926.20
Percentage discount 10%						592.62
Sub-total 1						5,333.58
REAR BOOTLID NUMBER PLATE GARNISH CLIPS - SET	NEW		1	50.00	10	50.00
REAR BOOTLID REVERSE CAMERA	Not Nec		1	400.00	X	400.00
REAR BUMPER CLIPS - SET	NEW		1	50.00	30	50.00
REAR BUMPER LOWER LID SPOILER	Behind		1	1500.00	850	1,500.00
REAR BUMPER REVERSE SENSOR - SET	Damaged		1	250.00	200	250.00
REAR END PANEL INNER TOP GARNISH CLIPS - SET	NEW		1	30.00	10	30.00
REAR EXHAUST GASKET	NEW		1	35.00	X	35.00
REAR EXHAUST PIPE	Bent		1	1800.00	800	1,800.00
REAR FENDER INNER TRIM GARNISH CLIPS L/R - SET	NEW	1980	2	40.00	60	80.00
REAR SPARE TYRE PANEL INSULATOR MAT	NEW		1	280.00	X	280.00
REAR TAILLAMP CLIPS L/R - SET	NEW		2	30.00	20	60.00
Subtotal before discount						4,535.00
Percentage discount 0%						0.00
Sub-total 2						4,535.00
Parts-total						9,868.58

*** This is a computer-generated document which requires no signature.***

page 2

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

NEYASHAN .
 BLK 25 TANGLIN HALT ROAD #04-38
 SINGAPORE 140025

Contact : 98584251, 87484317

ESTIMATE

Repair Code : CLM15216
 Date in : 29/03/2021
 Vehicle Num. : SJM4517M
 Model : MITSUBISHI LANCER 1.6 M
 Chassis/Eng# : JMYSNCS3A8U007556/4G18JT5758

LABOUR

- To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.
- To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)
- To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.
- To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.
- To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.
- To apply anti-rust chemical on repaired and replaced panel.

Labour Total

Parts & Labour Total

✓ 60.00

60 120.00

1000 1,300.00

80 120.00

1100 1,600.00

60 100.00

3,300.00

13,168.58

2360

total: 8246.63
 2/s: 66K

*** This is a computer-generated document which requires no signature.***

page 3

66K 0907

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: