

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG21004111/AVCE2

**Date:** 03/08/2021

### REFERENCE

Insured/Claimant: JEFFREY NG LENG PING Policy No: 2100451771-05  
Date of Loss: 29/03/2021 Nature of Claim: OD Claim No: 4388057659SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLB2328P**  
Make & Model: AUDI A6, 1.8 TFSI S-tronic (A) Engine No: CYG008095  
Reg. Date: 26/02/2016 (Man. Year: 2015) Chassis No: WAUZZZ4G7GN048419  
Colour: Silver Odometer: 58428 km  
Engine Capacity: 1798 cc  
Market Value/New Car Price: S\$90,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 225/55 R17 Rear Tyre Size: 225/55 R17  
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm  
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	11,609.00	2,522.32	9,086.68	78.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,692.00	3,082.00	5,610.00	64.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>20,301.00</b>	<b>5,604.32</b>	<b>14,696.68</b>	<b>72.39</b>
<b>- Excess (S\$)</b>	<b>800.00</b>	<b>800.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>19,501.00</b>	<b>4,804.32</b>	<b>14,696.68</b>	<b>75.36</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,365.07</b>	<b>336.30</b>	<b>1,028.77</b>	<b>75.36</b>
<b>Nett Amount (S\$)</b>	<b>20,866.07</b>	<b>5,140.62</b>	<b>15,725.45</b>	<b>75.36</b>

### INSPECTION

Date of Assignment: 31/03/2021  
Date Inspected: 30/03/2021 Inspected At: Premium Automobiles Pte Ltd (UBI)  
55 Ubi Road 1  
Singapore 408699  
Estimated Period of Repair: 5.0 days

**Adjuster:** ADRIAN LING

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDOW	Shattered	1,174.00 FS	*939.20 FS
2	1		*PRIMER	Necessary	20.00 FS	*15.76 FS
3	2		*REAR LID	Repair	3,174.00 FS	*- FS
4	1		*REAR LID BRACKET	Not Necessary	34.00 FS	*- FS
5	1		*REAR LID SEAL RING	Not Necessary	7.00 FS	*- FS
6	1		*CUP RIVERT	Not Necessary	2.00 FS	*- FS
7	1		*REAR BOOT ADHESIVE	Not Necessary	19.00 FS	*- FS
8	1		*AUDI EMBLEM	Necessary	138.00 FS	*110.00 FS
9	1		*A6 EMBLEM	Necessary	99.00 FS	*79.04 FS
10	1		*TFSI EMBLEM	Necessary	99.00 FS	*79.04 FS
11	2		*TAIL LIGHT - LH / RH	Not Necessary	2,516.00 FS	*- FS
12	2		*TAIL LIGHT TRIM - LH / RH	Not Necessary	60.00 FS	*- FS
13	2		*C PILLAR UPPER TRIM - LH / RH	Not Necessary	470.00 FS	*- FS
14	1		*D PILLAR TRIM - LH / RH	N/S Deformed	470.00 FS	*187.60 FS
15	1		*REAR SHELF PANEL TRIM	Deformed	1,065.00 FS	*852.00 FS
16	2		*LOUDSPEAKER TRIM	Not Necessary	598.00 FS	*- FS
17	1		*CHILD SEAT ANCHOR COVER	Not Necessary	15.00 FS	*- FS
18	1		*ROOF CHROME MOLDING - LH	Not Necessary	508.00 FS	*- FS
19	1		*ROOF CHROME TRIM	Not Necessary	366.00 FS	*- FS
20	1		*REAR BRAKE LIGHT	Not Necessary	234.00 FS	*- FS
21	1		*REAR WINDSCREEN SEALANT	Necessary	250.00 FS	*250.00 FS
22	1		*SUNDRIES	Necessary	200.00 FS	*9.68 FS
23	1		*REAR SHELF END OVER	Not Necessary	91.00 FS	*- FS

F=Franchise part. S=SpcNett.

**Total Parts (\$\$)      11,609.00      2,522.32**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND TRANSFER REAR LIDS CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS	New	280.00	0.00
2	TO RENEW REAR WINDSCREEN	New	480.00	480.00
3	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN	New	400.00	400.00
4	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN	New	200.00	150.00
5	TO REMOVE AND RENEW TRIM FOR REAR SHELF PANEL LOUDSPEAKER TRIMS, C-PILLAR TRIMS AND D-PILLAR TRIMS	New	480.00	480.00
6	TO REMOVE AND REINSTALL ROOFTOP PANEL ANTENNA TO FACILITATE RESPRAYING FOR ROOFTOP	New	280.00	0.00
7	TO CARRY OUT CLEAN UP INTERIOR FOR REAR WINDSCREEN SCATTERED	New	280.00	280.00
8	TO DISMANTLE AND RENEW REAR LID. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	1,200.00	0.00
9	TO RESPRAY REAR LID, LHS REAR FENDER, RHS REAR FENDER, ROOFTOP PANEL AND BOTH ROOF CHANNELS	New	4,900.00	1,100.00
10	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
			<b>Gross Labour Cost (S\$)</b>	<b>3,082.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >