



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0263/2021/HR
DATE : 30-Mar-21
WIP : 21251

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 30/3/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR. JEFFREY NG LENG PING
ADDRESS : 193 LORONG 4 TOA PAYOH
#11-658
SINGAPORE 310193
TELEPHONE : HP +65 82232020
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2100451771-05
VEHICLE NO : **SLB 2328 P**
MODEL CODE : A6 1.8 TFSI S TRONIC
MODEL YEAR : 26/2/2016
ENGINE NO : CYG 008095
CHASSIS NO : WAUZZZ467GN048419
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 29-Mar-21
PLACE OF ACCIDENT : LOR 4 TOA PAYOH OPEN SPACE CARPARK



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLB 2328 P

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS.	S/N \$	280.00	x
2	TO RENEW REAR WINDSCREEN.	S/N \$	480.00	✓
3	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN.	S/N \$	400.00	✓
4	TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN.	S/N \$	200.00	150
5	TO REMOVE AND RENEW TRIM FOR REAR SHELF PANEL, LOUDSPEAKER TRIMS, C-PILLAR TRIMS AND D-PILLAR TRIMS.	S/N \$	480.00	✓
6	TO REMOVE AND REINSTALL ROOFTOP PANEL ANTENNA TO FACILITATE RESPRAYING FOR ROOFTOP.	S/N \$	280.00	x
SUB LABOUR CHARGES			\$ 2,120.00	



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLB 2328 P

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO CARRY OUT CLEAN UP INTERIOR FOR REAR WINDSCREEN SCATTERED.	S/N \$ 280.00	✓
8	TO DISMANTLE AND RENEW REAR LID. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,200.00	✗
9	TO RESPRAY REAR LID, LHS REAR FENDER, RHS REAR FENDER, ROOFTOP PANEL AND BOTH ROOF CHANNELS.	\$ 4,900.00	1100
10	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 8,692.00	



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLB 2328 P

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
1	REAR WINDOW <i>shattered</i>	1	\$ 1,174.00	✓
2	PRIMER <i>neu</i>	1	\$ 20.00	✓
3	REAR LID <i>Repair</i>	2	\$ 3,174.00	+
4	REAR LID BRACKET	1	\$ 34.00	+
5	REAR LID SEAL RING	1	\$ 7.00	+
6	CUP RIVERT	1	\$ 2.00	+
7	REAR BOOT ADHESIVE	1	\$ 19.00	+
8	"AUDI" EMBLEM	1	\$ 138.00	✓
9	"A6" EMBLEM	1	\$ 99.00	✓
10	"TFSI" EMBLEM	1	\$ 99.00	✓
11	TAIL LIGHT - LH / RH <i>neu</i>	2	\$ 2,516.00	+
12	TAIL LIGHT TRIM - LH / RH <i>neu</i>	2	\$ 60.00	+
13	C PILLAR UPPER TRIM - LH / RH <i>neu</i>	2	\$ 470.00	+
14	D PILLAR TRIM - LH / RH <i>Dehnd LH</i>	2	\$ 470.00	235
15	REAR SHELF PANEL TRIM <i>dehnd</i>	1	\$ 1,065.00	✓
16	REAR SHELF END OVER <i>neu</i>	1	\$ 91.00	+
17	LOUDSPEAKER TRIM	2	\$ 598.00	?
18	CHILD SEAT ANCHOR COVER <i>neu</i>	1	\$ 15.00	+
19	ROOF CHROME MOLDING - LH <i>neu</i>	1	\$ 508.00	+
20	ROOF CHROME TRIM <i>neu</i>	1	\$ 366.00	+
SUB TOTAL SPARE PARTS		:	\$ 10,925.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLB 2328 P

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
21	REAR BRAKE LIGHT <i>new</i>	1	\$ 234.00	<i>+</i>
22	REAR WINDSCREEN SEALANT <i>new</i>	S/N	\$ 250.00	<i>✓</i>
23	SUNDRIES <i>?</i>		\$ 200.00	<i>?</i>
TOTAL SPARE PARTS		:	\$ 11,609.00	
TOTAL LABOUR CHARGES		:	\$ 2,120.00	
GRAND TOTAL		:	\$ 13,729.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Lij*
SURVEYED DATE : *30/03/21*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *AKP Authorised, 05 Days.*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT