

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0253/2021/HR
DATE : 26-Mar-21
WIP : 20872

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 30/3/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian

3 days - ok - John

25-May-21

OWNER'S NAME : MR. NG RUI ZHI
ADDRESS : 219 BISHAN ST 23
#12-287
SINGAPORE 570219
TELEPHONE : HP +65 97531539
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1900114746
VEHICLE NO : **SMM 4965 S**
MODEL CODE : A4 SEDAN 2.0 TFSI S TRONIC
MODEL YEAR : 28/6/2019
ENGINE NO : CVK 079993
CHASSIS NO : WAUZZZF41KN011524
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 17-Mar-21
PLACE OF ACCIDENT : NEAR JALAN BUKIT MERAH, MSCP

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMM 4965 S

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	360.00	\$ 360.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHTS'S CONTROL UNIT AND POWER MODULE.	S/N \$	350.00	\$ 250.00
3	TO DISMANTLE AND RENEW FRONT BUMPER,LHS FRONT FENDER AND LHS HEADLIGHT. REORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	1,050.00	\$ 500.00
4	TO RESPRAY FRONT BUMPER.	\$	900.00	\$ 550.00
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$	2,852.00	\$ 1,852.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMM 4965 S

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER	1	\$ 1,787.00	\$	1,429.60
2	FRONT BUMPER FIXING PARTS	1	\$ 587.00		
3	FRONT BUMPER SECURING STRIP	2	\$ 71.00		
4	FRONT BUMPER LOWER GRILLE - CENTER	1	\$ 196.00		
5	FRONT BUMPER LOWER CLOSING ELEMENT - CENTER	1	\$ 210.00	\$	167.60
6	FRONT BUMPER AIR GUIDE - LH	1	\$ 63.00		
7	FRONT RADIATOR GRILLE	1	\$ 1,332.00		
8	FRONT BUMPER AIR GUIDE GRILLE - LH	1	\$ 135.00	\$	108.00
9	FRONT BUMPER CARRIER	1	\$ 845.00		
10	FRONT BUMPER FOAM FILLER PIECE	1	\$ 124.00	\$	99.20
11	FRONT BUMPER REINFORCEMENT COVER	1	\$ 127.00		
12	FRONT BUMPER GUIDE SECTION - LH	1	\$ 36.00		
13	"CAUTION" STICKER	1	\$ 14.00		
14	AIR CONDITIONER STICKER	1	\$ 8.00		
15	FRONT BUMPER LOCK CARRIER BRACKET	1	\$ 137.00		
16	FRONT BUMPER SUPPORT - LH / RH	2	\$ 58.00		
17	FRONT PARKING AID SENSOR	1	\$ 244.00		
18	FRONT PARKING AID SENSOR SEAL RING	4	\$ 14.00		
19	FRONT HIGH TONE HORN - LH	1	\$ 126.00		
20	FRONT HIGH TONE HORN SPRING SHACKLE - LH	1	\$ 29.00		
SUB TOTAL SPARE PARTS		:	\$ 6,143.00	\$	1,804.40

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMM 4965 S

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		<i>c/f</i>		\$	1,804.40
21	HEADLIGHT - LH	1	\$ 7,693.00	\$	6,154.40
22	HEADLIGHT LIFT CYLINDER - LH	1	\$ 210.00		
23	FRONT RADIATOR OUTER AIR DUCT - LH	1	\$ 28.00		
24	FRONT RADIATOR INNER AIR DUCT - LH	1	\$ 12.00		
25	FRONT RADIATOR UPPER AIR DUCT - LH	1	\$ 16.00		
26	FRONT NUMBER PLATE	S/N	\$ 60.00		
27	SUNDRIES		\$ 200.00		
TOTAL SPARE PARTS			\$ 14,362.00	\$	7,958.80
TOTAL LABOUR CHARGES			\$ 2,852.00	\$	1,852.00
GRAND TOTAL			\$ 17,214.00	\$	9,810.80

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.
 bl-22/03/21



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT