



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
INDIA INTERNATIONAL INSURANCE PL 64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Ref: CS3/III19008177/T1qf3e2-1 Date: 09/04/2021 Code: III2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 8021B	Veh. Inspected	SLA 4387K
Policy No.	MCOM0015	Coverage (\$)	0.00
Claim No.	MCT19050179	Excess (\$)	0.00
Assign From	DERRICK TAN	Assign Date	31/03/2021
2. Vehicle Particulars & Condition			
Make & Model	HYUNDAI TUCSON	c.c	1999
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	KMHJ3813MGU183482	Colour	BROWN
Odometer	71016 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	225/55 R18	NEXEN	6 mm
L/H Front Tyre	225/55 R18	NEXEN	6 mm
R/H Rear Tyre	225/55 R18	NEXEN	6 mm
L/H Rear Tyre	225/55 R18	NEXEN	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	07/05/2019	Inspection Date	09/05/2019
Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	