



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO21004125/T1Uqf3n2	
			Date: 22/09/2021	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLZ 8159U	Veh. Inspected	GBH 3571H	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD2100929/RE	Excess (\$)	0.00	
Assign From	IRENE HENRY	Assign Date	30/03/2021	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA DYNA	c.c	2982	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	JTFAT35Y50K209970	Colour	SILVER	
Odometer	150174 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/75 R15	KENDA	6 mm	
L/H Front Tyre	195/75 R15	KENDA	6 mm	
R/H Rear Tyre	195/75 R15 (D)	KENDA	6/6 mm	
L/H Rear Tyre	195/75 R15 (D)	KENDA	6/6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	24/03/2021	Inspection Date	01/04/2021	
Survey held at	56 LOYANG WAY #04-04			
Repairer	AP AUTOMOTIVE SERVICES PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	