

LKK HSI 2010

NOT Allowed
 31/3/21
 4/5/1550/
 3 days.

FASTECH AUTO PTE LTD
 BLK 1 KAKI BUKIT AVE 6
 #01-48 AUTOBAY
 SINGAPORE 417883

VEHICLE No: EQ 26C

1PC	REAR BUMPER	R		\$788.20 X
1PC	REAR BUMPER SIDE RH	De	185.20	\$295.00 ✓
1SET	REAR BUMPER CLIPS	new		\$50.00 ✓
1PC	REAR BUMPER SIDE REAINER RH	11		\$62.50 X
1PC	REAR FENDER RH	R		\$981.00 X
1PC	REAR FENDER OUTER PROTECTOR RH	Torn	199.10	\$366.20 ✓
1PC	REAR SPORT RIM RH	R		\$1,000.00 X
1PC	REAR WHEEL HUB BEARING RH	11		\$450.00 X
				\$3,992.90

(202)

TO CHECK WIRING	\$50.00 20
TO DISMANTLE & REFIX RERA REVERSE SENSOR	\$80.00 50
TO DISMANTLE & REFIX CUSHION UPHOLSTERY	\$120.00 80
TO CONDUCT WHEEL ALIGNMENT	\$100.00 60
TO DISMANTLE & REFIX REAR UNDER CARRIAGE	11 \$150.00 X
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$680.00 600
TO PUTTY & SPRAY PAINTING	\$1,080.00 80
TOTAL	\$6,252.90

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2-434-30
 202
 P-347-44
 L-1610
 1957-44
 202
 1565.