

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd.
8 Temasek Boulevard
#04-01 Suntec Tower Three
Singapore 038988

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 21 Jul 2021

Preliminary Advice

Insured Vehicle No	: XD4437S	Accident Date	: 15/03/2021
TP Vehicle No	: XD8371X	Assignment Date	: 31/03/2021
Make	: SHACMAN SX418FJU361RC	Est. Duration of Repair	: 5
Date of Inspection	: 28/04/2021		
Inspection At	: RYDER AUTO PTE LTD (HQ) 2 KAKI BUKIT AVE 2, #02-19 AUTOHUB @ KAKI BUKIT SINGAPORE 417921		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	18,405.06
Revised Amount	:S\$	11,876.71
Check Items (Estimated)	:S\$	0.00
Total	:S\$	11,876.71
Lump Sum Repair	:S\$	9,500.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :