

RICO60

AUTO SERVICES

Rico 60 Auto Services Pte Ltd
Blk 8 , Kaki Bukit Avenue 4 , #02-24
Premier @ Kaki Bukit Singapore 415875
Email: claims@rico60.com
Tel: 6286 6060 Fax : 6286 7060

RICO Office Use Only

Parts -25%	
SN	
Labour	
TOTAL	
LUMSUM	
ERV	

TO: CHINA TAIHING

Vehicle No : GBK 9197 A

Make & Model : TOYOTA DYNA

DATE: 22/3/2021

No.	DESCRIPTION - PARTS	QTY	UNIT PRICE	PRICE
1	FRONT DOOR RH	1	\$ 1,794.20	\$ Ry 1,794.20
2	FRONT DOOR OUTER MOULDING RH	1	\$ 159.80	\$ xm 159.80
3	FRONT DOOR OUTER HANDLE RH	1	\$ 277.50	xm
4	FRONT DOOR HINGE RH	2	\$ 120.00	\$ xm 240.00
5	FRONT DOOR CHECKER RH	1	\$ 136.50	\$ xm 136.50
6	FRONT DOOR INNER LOCK RH	1	\$ 396.40	\$ xm 396.40
7	FRONT DOOR LOCK CATCH RH	1	\$ 46.00	\$ xm 46.00
8	FRONT DOOR WEATHERSTRIP RH	1	\$ 198.00	\$ xm 198.00
9	FRONT DOOR REGULATOR MOTOR RH	1	\$ 475.90	\$ xm 475.90
10	FRONT DOOR REGULATOR GEAR RH	1	\$ 321.00	\$ xm 321.00
11	FRONT DOOR FRAME WEATHERSTRIP RH	1	\$ 254.00	\$ xm 254.00
12	FRONT DOOR SIDE RUBBER RH	1	\$ 100.00	\$ xm 100.00
13	FRONT DOOR BOTTOM RUBBER RH	1	\$ 100.00	\$ xm 100.00
14	FRONT DOOR LOWER STEP GARNISH RH 241.40	1	\$ 498.70	\$ cut 498.70
15	CABIN REAR PILLAR RH	1	\$ 693.50	\$ Ry 693.50
16	CABIN REAR PILLAR EMBLEM (D4D)	1	\$ 96.80	\$ ry 96.80
17	FRONT MUDGUARD RH 225	1	\$ 374.20	\$ cut 374.20
18	FRONT ABSORBER RH	1	\$ 207.70	\$ xm 207.70
19	FROTN ABSORBER TOP MOUNTING RH	1	\$ 90.00	\$ xm 90.00
20	FRONT UPPER ARM RH	1	\$ 1,720.50	\$ xm 1,720.50
21	FRONT LOWER ARM RH	1	\$ 1,029.60	\$ xm 1,029.60
22	FRONT KNUCKLE ARM RH 421	1	\$ 518.70	\$ xm 518.70
23	FRONT WHEEL BEARING RH	1	\$ 128.70	\$ xm 128.70
24	AIR CLEANER BOX ASSY 494.70	1	\$ 876.40	\$ cut 876.40
25	RADIATOR SPARE TANK 140.90	1	\$ 224.50	\$ cut 224.50
26	SIDE GATE RH 1325.40	1	\$ 1,898.60	\$ cut 1,898.60

SPECIAL NETT		\$ 6,030.00
LABOUR		PRICE
PANEL BEATING, REMOVAL AND REPLACING PARTS	900	\$ 1,600.00
TO SPRAY PAINT AFFECTED AREA	900	\$ 1,800.00
TO SPRAY TUFF COAT		\$ 30 600.00
WIRING, BULB CHECKING		\$ 30 600.00
REMOVE AND REFIX UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR		\$ 400.00
REMOVE & REINSTALL FRONT DOOR MECHANISIM PART		\$ 200.00
REMOVE & REINSTALL REAR DIESEL TANK		\$ 200.00
REMOVE AND INSTALL REAR UNDER CARRIAGE	part ?	\$ 600.00
REMOVE AND INSTALL FRONT UNDER CARRIAGE	part ?	\$ 600.00
TO CHECK FOUR WHEEL ALIGHMENT	report ?	\$ 200.00
LABOUR TOTAL		\$ 6,800.00

Total Parts Cost	\$ 18,838.13
Total Labour Cost	\$ 6,800.00
Total Repair Cost	\$ 25,638.13

APPROVED DETAILS
 NO. OF WORKING DAYS
 PART BY PART OR LUMP SUM
 DATE & TIME OF SURVEY
 SURVEYED BY
 CONTACT NUMBER
 FAX NUMBER

Tanphn 97495745 4397.77
 WP 21/3/21 @ 12pm 1160
 1/3 Resurvey after repair 2110
 Tanphn @ 1/11 auto-con 7667.77
 7 days 1/5 \$6100.
 7 days #

LKK Auto Consultants hence notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company
 Acknowledged by Repairer
 Signature:
 Date: