

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Tan Kah Leong

Date: 24 Aug 2021

Preliminary Advice

| | | | |
|--------------------|--|-------------------------|--------------|
| Insured Vehicle No | : SLM9408M | Accident Date | : 19/03/2021 |
| TP Vehicle No | : GBK9197A | Assignment Date | : 31/03/2021 |
| Make | : TOYOTA DYNA 150 | Est. Duration of Repair | : 7 |
| Date of Inspection | : 31/03/2021 | | |
| Inspection At | : RICO 60 AUTO SERVICES PTE LTD (HQ) 8, KAKI BUKIT AVENUE 4, #02-24, PREMIER @ KAKI BUKIT SINGAPORE 415875 | | |

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

| | | |
|-----------------------------|------|-----------|
| Repairer's Estimate (Gross) | :S\$ | 25,638.13 |
| Revised Amount | :S\$ | 7,667.78 |
| Check Items (Estimated) | :S\$ | 0.00 |
| Total | :S\$ | 7,667.78 |

| | | |
|-----------------|------|--|
| Lump Sum Repair | :S\$ | |
|-----------------|------|--|

Total Loss Consideration

| | | |
|--------------------|------|--|
| New for Old Value | :S\$ | |
| Pre-Accident Value | :S\$ | |
| COE / PARF Rebate | :S\$ | |
| Salvage Value | :S\$ | |
| Margin for Repair | :S\$ | |

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.