

ASS. REC. BY: Taufikh

REF: CS/CTI 21004147/7.19.83

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

CD: (TP) / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. SNM21D201599/C02

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$86K.

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: 7 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS WP

Date: \_\_\_\_\_ Person Contacted: Hu Xiong Vehicle: IN / OUT

Veh No: GBR 9197A Yr Regn: 2021 Jan.

Type: M.Gar / M.Cycle / Bus / Van / Lorry / (Taxi) / Prime Mover / Truck / Trailer or \_\_\_\_\_

Make: Toyota Dynia C.C. 2982

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 4915 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: STF 17T 35Y 80K 216265

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or \_\_\_\_\_

Brake: Inorder / Jammed / Leaked / Burnt or \_\_\_\_\_

Modi: (NI) / S/Rim / STD A/Rim or \_\_\_\_\_

Tyre Size: F: 195/75R15

R: 155/R12 (D)

(BS) DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or \_\_\_\_\_

Front		Rear	
R/Bal. <u>7</u> mm		R/Bal. <u>3/2</u> mm	
L/Bal. <u>2</u> mm		L/Bal. <u>3/3</u> mm	
D.O.A. _____		D.O.I. <u>31/3/21</u>	

Survey held at Kilo 60

Des. of Damages: Frt / Rear / (O/S) / NIS / (U/C) / Rooftop or \_\_\_\_\_

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
24/08/21@1.12pm	revised to Tan Kah Leong via Merimen.
23/08/21@2.34pm	Taufikh finalised with Xiong LS \$6100, 7 days. (Red \$19538.13, 76%)

Date/Time, File Pass to?  : Prell. Report

1) 24/08 Typist  : Final Report

Date/Time, File Return to? \_\_\_\_\_

2) \_\_\_\_\_

Report Format: MER-TP

Lump Sum 6100

Days Of Repair: 7

Resurvey No. of Trip: 2

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_ \$ + RS. \$1

Photos \_\_\_\_\_

Others \_\_\_\_\_


TOTAL \_\_\_\_\_

Add Fee:  : Site Insp (\$ \_\_\_\_\_)

: Interview (\$ \_\_\_\_\_)

: Tech. Invs (\$ \_\_\_\_\_)

: Weekend (\$ \_\_\_\_\_)



Rico 60 Auto Services Pte Ltd  
 Blk 8 , Kaki Bukit Avenue 4 , #02-24  
 Premier @ Kaki Bukit Singapore 415875  
 Email: claims@rico60.com  
 Tel: 6286 6060 Fax : 6286 7060

**RICO Office Use Only**

Parts -25%	
SN	
Labour	
TOTAL	
LUMSUM	
ERV	

TO: CHINA TAIPING
Vehicle No : GBK 9197 A
Make & Model : TOYOTA DYNA
DATE: 22/3/2021

No.	DESCRIPTION - PARTS	QTY	UNIT PRICE	PRICE
1	FRONT DOOR RH	1	\$ 1,794.20	\$ <i>Ry</i> 1,794.20
2	FRONT DOOR OUTER MOULDING RH	1	\$ 159.80	\$ <i>x</i> 159.80
3	FRONT DOOR OUTER HANDLE RH	1	\$ 277.50	<i>x</i>
4	FRONT DOOR HINGE RH	2	\$ 120.00	\$ <i>x</i> 240.00
5	FRONT DOOR CHECKER RH	1	\$ 136.50	\$ <i>x</i> 136.50
6	FRONT DOOR INNER LOCK RH	1	\$ 396.40	\$ <i>x</i> 396.40
7	FRONT DOOR LOCK CATCH RH	1	\$ 46.00	\$ <i>x</i> 46.00
8	FRONT DOOR WEATHERSTRIP RH	1	\$ 198.00	\$ <i>x</i> 198.00
9	FRONT DOOR REGULATOR MOTOR RH	1	\$ 475.90	\$ <i>x</i> 475.90
10	FRONT DOOR REGULATOR GEAR RH	1	\$ 321.00	\$ <i>x</i> 321.00
11	FRONT DOOR FRAME WEATHERSTRIP RH	1	\$ 254.00	\$ <i>x</i> 254.00
12	FRONT DOOR SIDE RUBBER RH	1	\$ 100.00	\$ <i>x</i> 100.00
13	FRONT DOOR BOTTOM RUBBER RH	1	\$ 100.00	\$ <i>x</i> 100.00
14	FRONT DOOR LOWER STEP GARNISH RH	1	\$ 498.70	\$ <i>cut</i> 498.70
15	CABIN REAR PILLAR RH	1	\$ 693.50	\$ <i>Ry</i> 693.50
16	CABIN REAR PILLAR EMBLEM (D4D)	1	\$ 96.80	\$ <i>ry</i> 96.80
17	FRONT MUDGUARD RH	1	\$ 374.20	\$ <i>cut</i> 374.20
18	FRONT ABSORBER RH	1	\$ 207.70	\$ <i>x</i> 207.70
19	FROTN ABSORBER TOP MOUNTING RH	1	\$ 90.00	\$ <i>x</i> 90.00
20	FRONT UPPER ARM RH	1	\$ 1,720.50	\$ <i>x</i> 1,720.50
21	FRONT LOWER ARM RH	1	\$ 1,029.60	\$ <i>x</i> 1,029.60
22	FRONT KNUCKLE ARM RH	1	\$ 518.70	\$ <i>??</i> 518.70
23	FRONT WHEEL BEARING RH	1	\$ 128.70	\$ <i>??</i> 128.70
24	AIR CLEANER BOX ASSY	1	\$ 876.40	\$ <i>cut</i> 876.40
25	RADIATOR SPARE TANK	1	\$ 224.50	\$ <i>cut</i> 224.50
26	SIDE GATE RH	1	\$ 1,898.60	\$ <i>BT</i> 1,898.60

27	SIDE GATE FRONT HANDLE LOCK RH	1	\$ 216.00	\$ <del>X</del> 216.00
28	SIDE GATE FRONT HANDLE LOCK BRACKET RH	1	\$ 225.30	\$ X 225.30
29	SIDE GATE HINGE RH	3-6	\$ 90.00	\$ <del>66</del> 540.00
30	SIDE GATE BOTTOM PANEL RH	1	\$ 752.40	\$ <del>66</del> 752.40
31	SIDE GATE BOTTOM STEP PANEL RH	1	\$ 244.30	\$ <del>66</del> 244.30
32	TAIL GATE LOWER SIDE RAILING RH <i>Rear RH</i>	1	\$ 246.00	\$ <del>66</del> 246.00
33	TAIL GATE LOWER SIDE RAILING STOPPER RH	1	\$ 38.50	\$ <del>out</del> 38.50
34	REAR MUDGUARD RH	2	\$ 372.40	\$ <del>66</del> 744.80
35	REAR MUDGUARD BRACKET RH	2 <del>4</del>	\$ 70.00	\$ <del>66</del> 280.00
36	TAIL LAMP RH	1	\$ 354.00	\$ X 354.00
37	TAIL LAMP BRACKET RH	1	\$ 172.40	\$ X 172.40
38	DIESEL TANK	1	\$ 1,278.90	\$ <del>66</del> 1,278.90
39	DIESEL TANK BELT	2	\$ 233.50	\$ <del>cut</del> 467.00
40	DIESEL TANL BELT BRACKET	1 <del>2</del>	\$ 417.00	\$ <del>66</del> 834.00
41	REAR ABSORBER RH	1	\$ 580.00	\$ X 580.00
42	REAR WHEEL BEARING RH	1	\$ 790.00	\$ X? 790.00
43	REAR AXLE BEAM	1	\$ 2,245.00	\$ X 2,245.00

Subtotal : \$ 17,077.50

Less 25% \$ 4,269.38

Parts Total : \$ 12,808.13

NO.	SPECIAL NETT	QTY	UNIT PRICE	PRICE
1	FRONT DOOR COMPANY STICKER <i>net</i>	1	\$ 300.00	\$ <del>150</del> 300.00
2	FRONT DOOR COMPANY LETTERING <i>net</i>	1	\$ 60.00	\$ <del>40</del> 60.00
3	CABIN REAR PILLAR SEALANT	1	\$ 80.00	\$ X 80.00
4	RADIATOR COOLANT	1	\$ 60.00	\$ <del>40</del> 60.00
5	FRONT MUDGUARD CLIP	1	\$ 50.00	\$ <del>60</del> 50.00
6	FRONT MUDFLAP RH	1	\$ 200.00	\$ X 200.00
7	REAR MUDGUARD CLIP	1	\$ 50.00	\$ X 50.00
8	REAR MUDGUARD MUDFLAP	2	\$ 40.00	\$ X 80.00
9	FORNT RIM RH	1	\$ <del>250</del> 450.00	\$ <del>del</del> 450.00
10	FRONT TYRE RH	1	\$ 350.00	\$ X 350.00
11	REAR TYRE RH	1 <del>2</del>	\$ <del>120</del> 300.00	\$ <del>at</del> 600.00
12	REAR RIM RH	1 <del>2</del>	\$ <del>150</del> 350.00	\$ 700.00
13	SIDE GATE COMPANY STICKER <i>net</i>	1	\$ <del>300</del> 600.00	\$ 600.00
14	SIDE GATE TOP RAILING BAR	1	\$ 1,500.00	\$ X 1,500.00
15	SIDE GATE INNER ALUMINIUM PLATE	1	\$ 800.00	\$ X 800.00
16	RIVET <i>net</i>	1	\$ 150.00	\$ <del>100</del> 150.00

	SPECIAL NETT	\$	6,030.00
LABOUR			PRICE
PANEL BEATING, REMOVAL AND REPLACING PARTS	900	\$	1,600.00
TO SPRAY PAINT AFFECTED AREA	900	\$	1,800.00
TO SPRAY TUFF COAT		\$ 30	600.00
WIRING, BULB CHECKING		\$ 3X	600.00
REMOVE AND REFIX UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR		\$ X	400.00
REMOVE & REINSTALL FRONT DOOR MECHANISIM PART		\$ X	200.00
REMOVE & REINSTALL REAR DIESEL TANK		\$ 100	200.00
REMOVE AND INSTALL REAR UNDER CARRIAGE	photo ?	\$ 100	600.00
REMOVE AND INSTALL FRONT UNDER CARRIAGE	photo ?	\$ 100	600.00
TO CHECK FOUR WHEEL ALIGHMENT	report?	\$ 80	200.00
	<b>LABOUR TOTAL</b>	<b>\$</b>	<b>6,800.00</b>

	<b>Total Parts Cost</b>	<b>\$</b>	<b>18,838.13</b>
	<b>Total Labour Cost</b>	<b>\$</b>	<b>6,800.00</b>
	<b>Total Repair Cost</b>	<b>\$</b>	<b>25,638.13</b>

**APPROVED DETAILS**  
**NO. OF WORKING DAYS**  
**PART BY PART OR LUMP SUM**  
**DATE & TIME OF SURVEY**  
**SURVEYED BY**  
**CONTACT NUMBER**  
**FAX NUMBER**

Taphin 97495745  
 - WP 21/3/21 @ 12pm  
 w/s resurvey after repair  
 Taphin @ lkkauto.com  
 = 7 days

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

> Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	153M
Vehicle Details	
Vehicle No.:	GBK9197A
Vehicle to be Exported:	No
Intended Deregistration Date:	31 Mar 2021
Vehicle Make:	TOYOTA
Vehicle Model:	DYNA 150 5MT
Primary Colour:	Silver
Manufacturing Year:	2020
Engine No.:	1KDB068812
Chassis No.:	JTFAT35Y80K216265
Maximum Power Output:	-
Open Market Value:	\$29,446.00
Original Registration Date:	22 Jan 2021
First Registration Date:	22 Jan 2021
Transfer Count:	0
Actual ARF Paid:	\$1,473.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	21 Jan 2031
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$32,696.00
COE Rebate Amount:	\$32,063.00
<b>Total Rebate Amount:</b>	<b>\$32,063.00</b>

The information contained herein is correct as at 31 Mar 2021

OK



toyota dyna Price Range Depreciation 2021 Vehicle Type

Advanced Search

Home » Used Cars » Net Link Partners Pte Ltd » Toyota Dyna 150 3.0M

# Toyota Dyna 150 3.0M

Overview Financial Accessories Similar Research Photos Map

PREMIUM AD

**NETLINK** *Your Commercial Specialist*  
 Specialized in New & Used Commercial Vehicles. Insurance. Hire Purchase. Scrap/Export

<b>Price</b>	\$87,800	<b>Lifespan</b>	25-Jan-2041
<b>Depreciation</b>	\$8,930 /yr <small>View models with similar depre</small>	<b>Reg Date</b>	26-Jan-2021 <small>(9yrs 9mths 25days COE left)</small>
<b>Mileage</b>	N.A.	<b>Manufactured</b>	2020
<b>Road Tax</b>	N.A.	<b>Transmission</b>	Manual
<b>Dereg Value</b>	\$26,632 as of today (change)	<b>OMV</b>	\$29,446
<b>COE</b>	\$27,100	<b>ARF</b>	\$1,473
<b>Engine Cap</b>	2,982 cc	<b>No. of Owners</b>	2
<b>Curb Weight</b>	1,780 kg		
<b>Type of Vehicle</b>	Truck		



**Features**

View specs of the Toyota Dyna 150 (2014)

**Description**

New Toyota Dyna Borneo Unit, One & Only One Unit Left. High Trade-In Available Also. Call Now To Book Before Its Gone.!

**Category**

Almost New Car, Premium Ad Car

**Status**

Available for sale. Shortlist this car to get alerted whenever the price or availability changes.

**Resources**



**Vehicle Evaluation**

Afraid of lemons? Request to have this car evaluated professionally. Find out more



**Car Valuation - Free**

Find out the market value of your existing car for free. Get started

Posted on: 29-Mar-2021 | Last Updated on: 29-Mar-2021


**Upfront Payment**

<b>Transfer Fee</b>	N.A.
<b>Dc</b>	\$8,780 (change) Maximum 3

> more financial info

**Price Chart**

**Summary**



Click on the point to view the vehicle

Shortlist Compare Report Error More

**Seller Information**

**Net Link Partners Pte Ltd**

125 vehicles for sale. 83 sold in past 3 mths

71 Woodlands Industrial Park E9 #07-01, #08-08

Wave9

Tel: 67531661

Search cars nearby

Date of Accident : 19/3/2021 Accident Time: 15:00hr (24-HR-Format)  
 Accident Place : Grange Rd tuds Orchard Blvd  
 Vehicle No. (Car Plate No.) : GBK 9197A Make/Model: Toyota Dyna  
 Insurance Company : \_\_\_\_\_ Policy No: \_\_\_\_\_  
 Owner or Company Name /IC No. : \_\_\_\_\_  
 Owner or Company Contact No. : 9126 5164 Owner's Hp 6784 1024 Company Tel  
 DRIVER'S Name / IC No. : Ganesan Sathiya Sundaram (G8398140M)  
 DRIVER'S Date Of Birth : 9 Jul 1984 DRIVER'S License Pass Date 19 Sep 2019  
 Relationship of Owner & Driver : Spouse \ Parents \ Children \ Sibling \ Employee \ Others: \_\_\_\_\_  
 DRIVER'S Address : Blk 9012 Tampines St 93 #04-181 (S) 628845  
 DRIVER'S Contact No./ Alt No. : 1) 9011 4312 2) \_\_\_\_\_  
 DRIVER'S Occupation : INDOOR \ OUTDOOR (e.g. working inside or outside office)  
 Email Address : Samydrpcpl@gmail.com  
 Weather & Road Surface : CLEAR & DRY \ RAINING & WET \ AFTER RAIN & WET  
 Reporting Type : Reporting Only \ Claim Other Party \ Claim Own Insurance  
 Number of Passengers (Including Driver): 02  
 Was the accident reported to the police? YES \ NO  
 Was there any video Captured by car camera: YES \ NO  
 Exact purpose for which vehicle was being used at the time of accident: Private use \ Work purpose  
 Any Injury (If YES, Pls state): \_\_\_\_\_

**Other Party Driver's Particular (if any)**

Vehicle No: <u>SLM 9408 M</u>	Vehicle No: _____
Vehicle Make/Model: _____	Vehicle Make/Model: _____
Name Driver: _____	Name Driver: _____
IC No. Driver/Contact: _____	IC No. Driver/Contact: _____

\* NEW - Passenger's name & gender:

① Rajendren Tharmaseelan (M)

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that :

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


  
Policyholder's Signature / Date

\_\_\_\_\_  
Driver's Signature (if driver is not the policyholder) / Date & Time

\_\_\_\_\_  
Witnessed by Reporting Centre Personnel

**Sketch Plan**

Wh A: GBK9197A  
Wh B: SLM9408M



**Describe Circumstances of the Accident**

Handwritten text in the lined area: "Refer to Attached"

**Declaration**

We declare the foregoing particulars are true in every respect.

*[Signature]* 19/03/21

Policyholder's Signature / Date & Time



Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

ON THE STATED DATE AND TIME. I , VEHICLE A (GBK9197A) WAS TRAVELLING STRAIGHT ON THE STATED VENUE. SUDDENLY VEHICLE B (SLM9408M) CUT INTO MY LANE AND COLLIDED ONTO MY VEHICLE RIGHT PORTION. AFTER I ALIGHTED I REALISE THAT MY CAR WAS DAMAGE FROM THE FRONT RIGHT ALL THE WAY TO THE REAR RIGHT.

**VEHICLE A : GBK9197A**

**VEHICLE B : SLM9408M**