

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

TPM
Jasper.

MUCHI LEASING PTE LTD

421 TAGORE INDUSTRIAL AVE #01-21

SINGAPORE 787805

Contact : 81833239, 85189376

ESTIMATE

Repair Code : CLM16748

Date in : 31/03/2021

Vehicle Num. : SJM7193T

Model : TOYOTA VIOS E AUTO

Chassis/Eng# : MR053HY9305085062/1NZX815068

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT BUMPER <i>del d</i>	1	495.70	✓ 495.70
FRONT BUMPER 'LOGO' EMBLEM <i>me</i>	1	66.20	✓ 66.20
FRONT BUMPER RH FOGLAMP GARNISH <i>cancel</i>	1	84.70	✓ 84.70
FRONT BUMPER SIDE RETAINER L/R <i>cancel RH Dmg</i>	2	64.60	64.60 129.20
FRONT RH FENDER <i>Dented</i>	1	637.70	✓ 637.70
FRONT RH FENDER 'VVT-I' EMBLEM <i>me</i>	1	58.00	✓ 58.00
FRONT RH FENDER INNER BRACKET <i>me</i>	1	58.00	+ 58.00
FRONT RH FENDER INNER GARNISH (VERTICAL) <i>me</i>	1	54.10	+ 54.10
FRONT RH FENDER INNER SHIELD COVER <i>torn</i>	1	175.60	✓ 175.60
FRONT RH HEADLAMP <i>cancel</i>	1	558.90	✓ 558.90
FRONT RH KNUCKLE ARM <i>Dmg</i>	1	558.90	✓ 558.90
FRONT RH KNUCKLE ARM BEARING <i>me</i>	1	183.80	✓ 183.80
FRONT RH LOWER ARM <i>Bent</i>	1	1195.40	39740 1,195.40
FRONT RH SHOCK ABSORBER <i>Bent</i>	1	463.80	✓ 463.80
FRONT RH SHOCK ABSORBER TOP MOUNTING <i>me me</i>	1	223.30	+ 223.30
FRONT RH STABILIZER LINK <i>me</i>	1	213.60	+ 213.60
FRONT RH TIE ROD END <i>me</i>	1	117.70	+ 117.70
FRONT WASHER TANK <i>cancel</i>	1	145.80	✓ 145.80

*** This is a computer-generated document which requires no signature.***

page 1

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

MUCHI LEASING PTE LTD

421 TAGORE INDUSTRIAL AVE #01-21

SINGAPORE 787805

Contact : 81833239, 85189376

ESTIMATE

Repair Code : CLM16748

Date in : 31/03/2021

Vehicle Num. : SJM7193T

Model : TOYOTA VIOS E AUTO

Chassis/Eng# : MR053HY9305085062/1NZX815068

FRONT WASHER TANK MOTOR <i>NE nu</i>	1	293.00	293.00
Subtotal before discount			5,713.40
Percentage discount	25%		1,428.35
Sub-total 1			4,285.05
FRONT BUMPER CLIPS - SET <i>nu</i>	1	50.00	50.00
FRONT RH 185/65R15 TYRE <i>Acu</i>	1	350.00	350.00
FRONT RH FENDER INNER SHIELD COVER CLIPS - SET <i>m</i>	1	30.00	30.00
FRONT RH SPORT RIM <i>lt</i>	1	900.00	900.00
Subtotal before discount			1,330.00
Percentage discount	0%		0.00
Sub-total 2			1,330.00
Parts-total			5,615.05

LABOUR

To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)

To remove, change front suspension parts, absorber, lower arm, knuckle arm, wheel bearing, bearing hub, drive shaft, anti-roll bar, top-arm and steering rack and pinion.

To road test driving, check and resetting wheel alignments system.

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

Labour Total

2,040.00

Parts & Labour Total

7,655.05

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

*** This is a computer-generated document which requires no signature.***

page 2

Acknowledged by Repairer

Signature:

Date:

3.7K