

ASS. BY:

REF: 08/CTI 21004158/Dvj3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TPWS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured GBG 6416J

Policy No. DMCVSNW00087462003

Claims No. SNM21D201759/C02/TANKL

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. of Market Value: _____

IDAC Accident Report Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 10 days Res.: Yes or No

Lump Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: GBH3499J Yr Regn: 2018, May

Type: M.Car / M.Cycle / Bus / Van / / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Toyota Dyna c.c. 2982

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 65891 T/Radio: Insured / Std / NI / NA

Eng/No: 1KD2662081

C/No: KDT231802A278

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195 R15L

R: 165 R13L

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Maxxis

Front Rear

R/Bal. 5 mm R/Bal. 5/5 mm

L/Bal. 5 mm L/Bal. 5/5 mm

D.O.A. 28/03/2021 D.O.I. 31/03/2021

Survey held at JWG AMK

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Front & 4/5 Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time	Action / Instruction
	China Liping GBG 6413J
29/07/20	From 2/5 10,000/- with 10 days of work (Red 45,224.87,81%)

Date/Time, File Pass to? : Preli. Report

1) : Final Report

Date/Time, File Return to?

2) 29/7/21-Typist

Report Format: Merimen

Lump Sum / L.B.H. (%)

Days Of Repair: 10

Resurvey No. of Trip: 2

Add Fee: : Site Insp (\$)

: Interview (\$)

: Tech. Invs (\$)

: Weekend (\$)

Survey Fee:

Transportation:

S + RS: \$

Photos

Others

JWG INTERNATIONAL PTE. LTD.

10, ANG MO KIO IND PARK 2A, #03-08 AMK AUTOPOINT, SINGAPORE 568047

H/P: 8299 6103 | FAX: 6909 9592

E-Mail: jwg.claims@yahoo.com

To: CHINA TAIPING INSURANCE SINGAPORE PTE LTD

Att: Motor Claims Dept

ACCIDENT INVOLVING GBG6416J [YOUR INSURED] & GBH3499J [OUR CLIENT]
ON 28/03/2021.

ESTIMATED REPAIR COSTS FOR GBH3499J

<u>QTY</u>	<u>PARTS</u>	<u>AMOUNT</u>		
1PC	SIDE MIRROR GARNISH RH 44	\$ 211.30	X	
1PC	SIDE PANEL RH 44	\$ 489.90	X	
1PC	HEAD LAMP RH 44	\$ 827.40	X	
1PC	HEAD LAMP LOWER PANEL RH 44	\$ 332.90	X	
1PC	FRONT BUMPER 44	\$ 1,045.10	X	
1PC	FRONT BUMPER BRACKET 44	\$ 465.10	X	
1PC	A/C BLOWER 44	\$ 608.40	X	
1PC	A/C COOLING COIL 44	\$ 968.80	X	
1PC	A' PILLAR 44	\$ 1,492.40	X	
1PC	FRONT WINDSCREEN MOULDING 44	\$ 398.42	X	
1PC	FRONT DOOR RH Bnc	1455.10	\$ 1,796.50	✓
1PC	FRONT DOOR WINDOW RH Shatt, 2x2	650.00	\$ 1,592.80	✓
1PC	FRONT DOOR WINDOW MOULDING RH 1st		\$ 236.20	✓
1PC	FRONT DOOR INNER WEATHER STRIP RH detoured		\$ 198.00	✓
1PC	FRONT DOOR OUTER WEATHER STRIP RH detoured		\$ 251.90	✓
1PC	FRONT DOOR SIGNAL LAMP RH 44		\$ 145.00	X
1PC	FRONT DOOR LOCK RH Dem		\$ 301.70	✓
1PC	FRONT DOOR INNER TRIM RH 1st	645.20	\$ 922.50	✓
1PC	FRONT DOOR WINDOW REGULATOR RH R 1st		\$ 236.20	2 ✓
1PC	FRONT DOOR WINDOW MOTOR RH 2 Dem	261.50	\$ 724.30	2 ✓
1PC	FRONT DOOR UPPER HINGE RH 2 1st		\$ 65.10	2 ✓
1PC	FRONT DOOR LOWER HINGE RH 2 1st		\$ 65.10	2 ✓
1PC	FRONT WHEEL HOUSING RH Dem	653.00	\$ 1,848.90	✓
1PC	FRONT WHEEL HOUSING TOP GARNISH RH detoured		\$ 178.10	✓
1PC	FRONT DOOR PLASTIC STEP RH 2 Wade		\$ 239.40	2 ✓
1PC	WIPER WASHER TANK REFILL COVER 44		\$ 45.00	X
1PC	FRONT DOOR VENT RH 44		\$ 195.90	X
1PC	DASH BOARD ASSY 44		\$ 1,290.80	X
1PC	FRONT CABIN FLOOR PANEL 44		\$ 4,289.15	X
1PC	FRONT RIM RH 44		\$ 528.10	X

1PC	FRONT WHEEL BEARING & HUB ASSY RH	HW		\$ 532.60	X
1PC	FRONT KNUCKLE ARM RH	2 distm	469.43	\$ 987.50	Z ✓
1PC	FRONT ABSORBER RH	2 distm	379.20	\$ 490.40	Z ✓
1PC	FRONT LOWER ARM RH	2 distm	348.00	\$ 689.40	Z ✓
1PC	FRONT UPPER ARM RH	2 HW		\$ 680.00	Z X
1PC	TIE ROD RH	HW		\$ 329.00	X
1PC	TIE ROD END RH	HW		\$ 385.00	X
1PC	STEERING RACK & PINION ASSY	HW		\$ 2,723.10	X
1PC	CENTER PILLAR RH	Dent	738.20	\$ 2,004.50	✓
1PC	REAR SIDE GATE RH	Dent	1854.72	\$ 2,680.20	✓
1PC	REAR SIDE GATE STEP PANEL RH	Dent	221.75	\$ 398.90	✓
1PC	RADIATOR TANK	Crack	140.00	\$ 349.80	✓
1PC	TAILGATE	key		\$ 2,184.25	X
2PCS	TAILGATE LOCK LH / RH @ \$289.10 EACH	key		\$ 578.20	X
2PCS	TAILGATE LOCK BRACKET LH / RH @ \$349.19 EACH	key		\$ 698.38	X
4PCS	TAILGATE HINGE @ \$189.10 EACH	HW		\$ 378.20	X
1PC	REAR END PANEL	HW		\$ 1,492.80	X
2PCS	REAR END PANEL REFLECTOR LH / RH @ \$112.71 EACH	H/S broken		\$ 225.42	✓
2PCS	TAIL LAMP LH / RH @ \$401.90 EACH	SN		\$ 803.80	X
2PCS	TAIL LAMP REFLECTOR LH / RH @ \$104.20 EACH	SV2		\$ 208.40	X
1PC	FRONT DOOR INNER MOUNDING RH	HW		\$ 217.90	X
1PC	FRONT WHEEL HOUSING INNER SHIELD RH	dented	190.70	\$ 471.10	✓
1PC	REAR SIDE GATE STEP PANEL RUBBER STOPPER RH	dented		\$ 97.80	✓ 25.95
2PCS	TAIL LAMP PANEL LH / RH @ \$497.10 EACH	H/S 1st o/s low		\$ 994.20	✓ 119.30

350.00 SH 1PC
45.85 2PCS 4PC
1PC

REAR TOOL BOX \$ 987.90 2 1st / Dent ✓
 REAR RUBBER STOPPER LH / RH @ \$112.71 EACH ✓
 FRONT DOOR TOP RUBBER MOUNDING H/S broken o/s HW \$ 217.10 ✓
PARTS SUM: \$ 40,810.22
PARTS LESS 25%: \$ 10,202.56
PARTS TOTAL: \$ 30,607.67

10299.41
252 7724.55

LABOUR & SPECIAL NETT ITEMS

*	TO SUPPLY 1PC TYRE 160.00 \$ 400.00 (cut 50% 80/-		
*	TO SUPPLY FRONT GRILLE CLIPS HW	\$ 50.00	X
*	TO SUPPLY HEAD LAMP CLIPS HW	\$ 50.00	X
*	TO SUPPLY FRONT & REAR NO. PLATE HW	\$ 200.00	X
*	TO SUPPLY SIDE PANEL SEALANT HW	\$ 50.00	X
*	TO SUPPLY WHEEL HOUSING SEALANT H/c	\$ 50.00	40/-
*	TO SUPPLY WHEEL HOUSING TOP GARNISH CLIPS H/c	\$ 50.00	15/-
*	TO SUPPLY DOOR INNER TRIM CLIPS HW	\$ 100.00	X
*	TO SUPPLY CANOPY GREEN CANVASS form	\$ 1,000.00	800/-
*	TO SUPPLY SIDE GATE CHECKERED PLATE key	\$ 1,800.00	X
*	TO SUPPLY 1 SET REVERSE SENSOR HW	\$ 300.00	X
*	TO SUPPLY TAILGATE COMPANY STICKER H/c	\$ 1,200.00	150/-
*	TO SUPPLY 70KM STICKER H/c	\$ 50.00	20/-
*	TO SUPPLY 13 PAX STICKER H/c	\$ 50.00	20/-
*	TO SUPPLY DYNA STICKER H/c	\$ 60.00	15/-
*	TO SUPPLY 1500KG STICKER H/c	\$ 60.00	15/-
*	TO SUPPLY FRONT DOOR COMPANY STICKER H/c	150/- \$ 800.00	✓
*	TO REMOVE ALL INTERIOR UPHOLSTERLY ITEMS TO FACILITATE	\$ 300.00	120/-
*	TO SUPPLY SIDE GATE COMPANY STICKER H/c	\$ 600.00	150/-

1805.00

REPAIRS

*	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	\$ 6,000.00 1800/-
*	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	\$ 6,000.00 1200/-
*	TO TUFF COAT DAMAGED AREAS	\$ 300.00 40/-
*	TO RNR A/C CONDENSOR & REFILL GAS TO FACILITATE REPAIRS	\$ 100.00 44
*	TO RNR DASH BOARD ASSY TO FACILITATE REPAIRS	\$ 600.00 44
*	TO RNR FRONT DOOR MECHANISM TO FACILITATE REPAIRS	\$ 200.00 60/-
*	TO RNR FRONT UNDER CARRAIGE TO FACILITATE REPAIRS	\$ 400.00 150/-
*	TO RNR FRONT WINDSCREEN TO FACILITATE REPAIRS	3460.00 \$ 300.00 44
*	TO RNR WIPER WASHER TANK TO FACILITATE REPAIRS	\$ 100.00 44
*	TO CONDUCT COMPUTERIZED ALIGNMENT	\$ 150.00 60/-
*	TO VACUUM GLASS SHARD TO FACILITATE REPAIRS	\$ 100.00 30/-
*	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS	\$ 200.00 44
*	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS. RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	\$ 800.00 44

LABOUR & S/N TOTAL: \$ 20,620.00

GRAND TOTAL ESTIMATED REPAIR COSTS (NON-INCLUSIVE OF 7% GST): \$ 51,227.67

31/03/22 @ 1600hr
 Hut Antm
 4/5mm 10 days.

12989.55 (s) 3997.20
 4/5 10,000/- 55,224.87

[Signature]
 Jyan
 LKK Ant

[Signature]
 Check part price
 Check MV

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	29/03/2021 18:20 (SGT)
Date of Accident	28/03/2021 02:00 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	8 SELETAR NORTH LINK PPT LODGE 1A OSCP
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBH3499J
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	RICO ENGINEERING WORKS PTE LTD
Company Reg No	1XXXXX407G
Email Address	eas@ricoeng.com.sg
Mobile Phone No	(Phone) +65-66905713
Alternative Phone No	(Office) +65-66095713

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Dyna
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Commercial vehicle
Transmission	Manual
CC	2982

INSURANCE COMPANY

Name of Insurance Company	NTUC Income Insurance Co-operative Ltd
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	5100108204-02
Cover Note Number	02/05/2020 - 01/05/2021

DRIVER

Name of Driver	BALASUBRAMANIAN DHINESH
Passport No/FIN	GXXXX864X

Date Of Birth	26/09/1987
Occupation	Outdoor
Date Of Driving Pass	30/10/2013
Driving experience	7 YEARS AND 5 MONTHS
Gender	Male
Mobile Number	(Phone) +65-90885917
Alt. Phone Number	-
Email Address	dineshish887@gmail.com
Address	8 SELETAR NORTH LINK PPT LODGE 1A
Address complement	-
Postcode	797455
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Employee
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Hit and run / Vandalism / Damaged whilst parked
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	3
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	0
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Punggol Neighbourhood Police Centre
Police Station Phone No	(Phone) +65-18006049999
Alt. Police Station Phone No	(Fax) +65-64468015
Police Station Address	Blk 21A Tebing Lane Singapore 828837
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO POLICE REPORT

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBG6413J
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle

Name of Driver	VIJAYAKUMAR RAJARAM
Passport No/FIN	GXXXX344Q
Contact Number	(Phone) +65-93718398
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	GBF3789H
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

SKETCH PLAN

GBH 3499J (NTUC)
DOA: 28/03/2021 @ 0315

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow Insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that :

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sted outside of Singapore, for one or more of the above Purposes.



882 29/03/2021

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Jaylyn (AMK) 29/03/21

Sketch Plan



Vehicle A: GBH 3499J
Vehicle B: GBA 646J
Vehicle C: GBF 3789H

8 Seletar North Link PPT Lodge 1A Open Space Carpark



**SINGAPORE
POLICE FORCE**



T/20210328/2039

Police Station Of Origin:
Punggol N.P.C
21A Tebing Lane SINGAPORE 828837
Tel No: 1800-6049999

1 of 3

Report No. T/20210328/2039

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 28/03/2021 15:35	Vide Report No.: F/20210328/0076	Station Diary No.: 53
--	-------------------------------------	--------------------------

Informant's Particulars			
Name of Informant: BALASUBRAMANIAN DHINESH		Address: 8 SELETAR NORTH LINK PPT LODGE 1A SINGAPORE 797455	
ID Type / ID No.: FIN NO / G6509864X		Contact No.: Home/Office: Mobile: 90885917	
Nationality: INDIAN		Email:	
Sex: Male	Age: 33	Date of Birth: 26/09/1987	Type of Informant: Driver
Race: Indian		Language:	Institution / School Name:
Occupation: Lorry driver		Driving Licence Information: Class: 2B,3 Date of Expiry:	

General Information of the Accident				
Type of Accident:	Non-Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 28/03/2021 03:15	Type of Location: Straight Road
Location: SELETAR NORTH LINK				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume: No Traffic
Type of Collision: Moving Vehicle Against - Parked Vehicle				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBF3789H	Lorry				Seriously Damaged	0
GBG6416J	Van				Seriously Damaged	0
GBH3499J	Lorry				Seriously Damaged	0



**SINGAPORE
POLICE FORCE**



T/20210328/2039

Police Station Of Origin:
Punggol N.P.C
21A Tebing Lane SINGAPORE 828837
Tel No: 1800-6049999

2 of 3

Report No. T/20210328/2039

CONTINUATION OF REPORT

Details of Person Involved			
Any Pedestrian Involved: No			
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA	
Driver			
Name	VIJAYAKUMAR RAJARAM	ID No.	G8598344Q
Related Vehicle	GBG6416J (Van)	Contact No.	93718398
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
Driver			
Name	BALASUBRAMANIAN DHINESH	ID No.	G6509864X
Related Vehicle	GBH3499J (Lorry)	Contact No.	90885917
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 27/03/2021 at about 1700hrs, I parked my vehicle bearing registration plate: GBH3499J at PPT Lodge 1A open space carpark. Everything was intact and nothing was amiss.

On 28/03/2021 at about 0200hrs, I was informed by security guard that one van bearing GBG6416J has collided onto my vehicle while he was parking. I then made a check and saw another vehicle bearing GBF3789H that was parked beside my vehicle was also hit by the van. My vehicle driver's side door was dented and unable to open. Due to the collision, the fence behind my vehicle was also knocked down and causing it to hit onto my vehicle.

My supervisor was informed regarding the accident and I was advised to call for police. Shortly after police attended to me and I was told to lodge a police report.



**SINGAPORE
POLICE FORCE**



T/20210328/2039

Police Station Of Origin:
Punggol N.P.C
21A Tebing Lane SINGAPORE 828837
Tel No: 1800-6049999

3 of 3

Report No. T/20210328/2039

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:
F /
Sgt 1 TING WEI CHENG

Signature Of Informant:

Signature Of Interpreter:
Not applicable

Date/Time:
28/03/2021 15:35

Officer In Charge Of Case:
TP / GIT /
Sr Staff Sgt SYED MUHAMMAD BIN SYED
FARID ALBAR
Contact No.: 65476200

Classification Of Case:

Authentication Stamp
NP168

SIGNATURE

Back to OneMotoring

Inquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Owner ID:

Company

Vehicle Details

407G

Vehicle No.:

Vehicle to be Exported:

GBH3499J

Intended Deregistration Date:

Yes

Vehicle Make:

29 Mar 2021

Vehicle Model:

TOYOTA

Primary Colour:

DYNA 3.0 MANUAL

Manufacturing Year:

Silver

Engine No.:

2016

Chassis No.:

1KD2662081

Maximum Power Output:

KDY2318027278

Open Market Value:

-

Original Registration Date:

\$32,513.00

First Registration Date:

02 May 2018

Transfer Count:

02 May 2018

Actual ARF Paid:

0

Intended PARF Rebate Details

\$1,626.00

PARF Eligibility:

No

PARF Eligibility Expiry Date:

-

PARF Rebate Amount:

\$0.00

Intended COE Rebate Details

COE Expiry Date:

01 May 2028

COE Category:

C - Goods Vehicle & Bus

COE Period(Years):

10

PQP Paid:

\$29,127.00

COE Rebate Amount:

\$20,647.00

Total Rebate Amount:

\$20,647.00

The information contained herein is correct as at 29 Mar 2021

OK