

* LKK Jaslin

limited

**ZOOM AUTOWERKS PTE LTD**

130 Bedok Reservoir Road, Eunos Spring

#08-1339 Singapore 470130

Tel: 9450 7920

✉ zoomautowerks@gmail.com

Car Number: SGX296D

Model : Honda Stream

Damaged Area: **(Rear & Front Damaged)**

Repairer Estimation Cost of Repair :

Supplementary may be included during the cost of repair :

Not Authorized
LKK
31/3/21
4/5 @ 4000
8 days

Parts / Material :

1	Rear Bumper	DIS	665.40	\$ 725.30	✓
2	Rear Bumper Side Retainer @ 49.40	nn		\$ 98.80	X
3	Rear Bumper Tow Garnish Cover	nn	20.80	\$ 34.70	✓
4	Rear Bumper Clips	nn	39	\$ 60.00	✓
5	Rear End Panel Top Garnish	DIS	168.00	\$ 195.60	✓
6	Rear End Panel	Body PD	306.00	\$ 545.90	✓
7	Rear End Panel top Garnish Clips	nn		\$ 60.00	X
8	Rear Tailgate	Body PD	953	\$ 1,171.30	✓
9	Rear Tailgate Inner Trimboard	nn		\$ 281.60	X
10	Rear Tailgate Inner Trimboard Clips	nn		\$ 60.00	X
11	Rear Tailgate Inner Lock	should	145.50	\$ 245.90	✓
12	Rear Tailgate Inner Handle	nn		\$ 68.40	X
13	Rear Tailgate Centre Garnish	nn		\$ 361.20	X
14	Rear Tailgate Emblem (Stream)	SC		\$ 72.40	X
15	Rear Tailgate Logo	nn		\$ 98.40	X
16	Rear Tailgate Damper @ 195.20	nn		\$ 390.40	X
17	Rear Tailgate Weather Strip	nn	109.20	\$ 214.50	✓
18	Rear Taillamps @ 725.40	nn		\$ 1,450.80	X
19	Rear Taillamps clips	nn		\$ 32.00	X
20	Rear Fender Inner Trimboard @ 770.40	nn		\$ 1,540.80	X
21	Rear Fender Inner Trimboard Clips	nn		\$ 60.00	X
22	Reverse Sensor Original	should		\$ 380.00	200 S/N
23	Reverse Sensor Holder	nn		\$ 160.00	X
24	Rear Floor Panel Top Tray	nn		\$ 245.70	X
25	Rear Floor Panel	nn		\$ 1,451.60	X
26	Rear Spare Tyre Holder	nn		\$ 425.80	X
27	Rear Exhaust Chrome Muffler	nn		\$ 120.00	X
28	Rear Exhaust End Pipe	nn		\$ 785.00	X
29	Rear Exhaust Mounting @ 54.20	nn		\$ 108.40	X
30	Front Bumper	De/To. n	665.40	\$ 785.90	✓
31	Front Bumper Fog Lamp @ 195.80	nn		\$ 391.60	X
32	Front Bumper Fog Lamp Garnish @ 58.90	nn		\$ 117.80	X
33	Front Bumper Centre Air-Grille	nn		\$ 115.60	X
34	Front Bumper Side Retainer @ 95.60	nn		\$ 191.20	X
35	Front Bumper Tow Garnish	nn		\$ 43.50	X
36	Front Bumper Reinforcement	Bent	228.20	\$ 258.40	✓
37	Front Bumper Clips	nn	39.00	\$ 60.00	✓
38	Radiator Grille Based	nn	282.00	\$ 286.70	✓
39	Radiator Grille Chrome	nn		\$ 198.50	X
40	Radiator Grille Logo	nn		\$ 95.00	X
41	Radiator Grille Emblem (RSZ)	nn		\$ 115.00	X
42	Front Bonnet	Bent / Bur	685.00	\$ 738.60	✓

1 set

43	Front Bonnet Lock	u	\$ 125.80	X
44	Front Bonnet Insulator	u	\$ 115.60	X
45	Front Bonnet Insulator Clips	u	\$ 60.00	X
46	Headlamp Assy @ 780.90	SVC	\$ 1,561.80	X
47	Headlamp Bracket @ 124.30	u	\$ 248.60	X
48	Front Support Panel	R	\$ 466.20	X
49	AC Condenser	u	\$ 956.80	X
50	Radiator Assy	u	\$ 1,486.20	X

Parts \$19,863.30
Less 20% \$3,972.66
Total Parts \$15,890.64

Special Net Item :

1	Rear Tailgate Glass Inner Seal	u	\$ 75.00	30
2	Rear Tailgate Glass Sealant	u	\$ 80.00	40
3	Rear Number Plate	SVC	\$ 55.00	X

Total S/N Parts : \$ 210.00

Total Labour :

To Remove, Repair & Renew affected Rear Accident Areas	\$ 1,100.00	800
To Putty, Spray Paint on affected Rear Accident Areas	\$ 1,200.00	1000
To Remove, Repair & Renew affected Front Accident Areas	\$ 950.00	400
To Putty, Spray Paint on affected Front Accident Areas	\$ 1,000.00	600
To Discharge & Charge Up Gas	\$ 120.00	X
To Check & Re-Connect all electrical wiring	\$ 50.00	20
To Remove & Install Rear Tailgate Glass	\$ 150.00	120
To Remove & Refit Rear Tailgate Component to Assist Repairs	\$ 100.00	60
To Remove & Install Rear Bootlid Compartment Trims to Assist Repairs	\$ 100.00	80
To Remove & Re-position Rear Exhaust Pipe	\$ 150.00	X
To Conduct Rear Water Seepage Test	\$ 100.00	X
To Remove & Re-position Reverse Sensor	\$ 80.00	50
To Re-Programme & Reset Diagnostic	\$ 250.00	X
To Rust Proof Affected Areas	\$ 100.00	90

Total Labour : \$ 5,450.00

TOTAL PARTS : \$15,890.64
TOTAL SPECIAL NET IT \$210.00
TOTAL LABOUR : \$5,450.00
TOTAL REPAIR COST: \$21,550.64

DATE OF SURVEY / INSPECTED:

RECOMMENDED PART BY PART / LUMP SUM :

RECOMMENDED NUMBER OF DAYS :

SURVEY BY / SURVEYOR FIRM :

RE-SURVEY DISMANTLE PARTS / BEFORE PAINT / AFTER PAINT :

FINALISED AMOUNT :

LKK Auto Consultants hence notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-4296-50
 202
 P-3437-20
 S.N-270.00
 L-3220
 6927.20
 202
 8341