



南方摩哆 Southern Motor

Business Reg. No. 234147/001.
Block 1006, Bukit Merah Lane 2, #01-10, Singapore 159762
Tel: 6273-0369 (3 Lines) Fax: 6274-6614

30-Mar-2021

AIG Asia Pacific Insurance Pte Ltd
78 Shanton Way #07-16
AIG Building
Singapore (079120)

Dear Sirs,

RE: Cost of repair to Yamaha FZN150 – FBN486.J

1pc of Handle Bar	/ OT	S\$	68.00
1pc of Handle Grip	/ CUT		35.00
1pc of Handle Balancer	/ CUT		25.00
1pc of Exhaust Pipe Protector	/ CUT		85.00
1pc of Givi Box	/ CM		350.00
1pc of Front Signal	X		45.00
			608.00
		Less 10%	60.80
		Nett	547.20
		Transport	30.00 /
		Alignment Fork	75.00 /
		Alignment Front Rim	65.00 /
		Labor	180.00 150
			<u>\$897.20</u>

Yours Faithfully,
Southern Motor



Steve (LKK) 83228813

h2 RL

L/S

5/4/21, 12.30 am

3 dys

My AL sky

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: