



南方摩哆 Southern Motor

Business Reg. No: 234147/00L
Block 1006, Bukit Merah Lane 2, #01-10, Singapore 159762
Tel: 6273-0369 (3 Lines) Fax: 6274-6614

30-Mar-2021

AIIG Asia Pacific Insurance Pte Ltd
78 Shanton Way #07-16
AIIG Building
Singapore (079120)

Dear Sirs,

RE: Cost of repair to Yamaha FZN150 – FBN486J

1pc of Handle Bar	✓ OT	S\$	68.00 ✓
1pc of Handle Grip	✓ CUT		35.00 ✓
1pc of Handle Balancer	✓ CUT		25.00 ✓
1pc of Exhaust Pipe Protector	✓ CUT		85.00 ✓
1pc of Givi Box	✓ CUT		350.00 ✓
1pc of Front Signal	X NM		45.00
		563 -19% 506.70 ✓	608.00
			60.80
			547.20
			30.00 ✓
			75.00 ✓
			65.00 ✓
			180.00 150
			<u>\$897.20</u>

Yours Faithfully,
Southern Motor



Steve (LKK) 83228813 = 826.70

WZ NL

L/S

5/4/21, 12.30 am

3 dys

My AL sig

L/S - 661.36
= 650

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: