

KARZ WORKS PTE LTD
53 UBI AVENUE 1 #01-23, PAYA UBI INDUSTRIAL PARK
SINGAPORE 408934
(TEL) 6 8 4 4 5 9 3 4 (FAX) 6 8 4 4 2 4 7 4 - (E-MAIL) KARZWORKSSG@GMAIL.COM

REPAIR PERFORMA INVOICE

Vehicle number FBJ2573Z
Make / Model KTM 390
Chassis number VBKJGJ406DC214980
Accident date 14/12/20
Reference KK2103-52

FCI

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	FRONT FORK ? <i>bt</i> ✓	550.00 ✓
1	FRONT FORK BRACKET <i>Xsu</i>	350.00 X
1 SET	BALANCER <i>26</i> ✓	150.00 <i>68</i>
1	HANDLE BAR ? <i>bt</i> ✓	280.00 ✓
1	FRONT FAIRING UPPER LH <i>sc</i> ✓	450.00 } <i>648</i>
1	FRONT FAIRING LOWER LH <i>cm</i> ✓	450.00 }
1	FRONT FAIRING BOTTOM LH <i>cm</i> ✓	350.00 }
1	RADIATOR <i>bt</i> ✓	600.00 <i>580</i>
1	RADIATOR COVER LH <i>ms</i> ✓	180.00 ✓
1	RADIATOR COVER RH <i>Xsu</i>	180.00 X
1	RADIATOR FAN COWLING <i>de</i> ✓	300.00 ✓
1	FRONT FAIRING UPPER RH <i>Xsu</i>	400.00 X
1	FRONT FAIRING LOWER RH <i>Xsu</i>	400.00 X
1	BODY FRAME BRACKET LH <i>repair</i>	200.00 X
1	BRAKE PEDAL <i>br</i> ✓	90.00 ✓
1	FOOTREST LH <i>Xsu</i>	70.00 X
1	FOOTREST BRACKET LH <i>Xsu</i>	90.00 X
1	FOOTREST RUBBER LH <i>Xsu</i>	60.00 X
1	FOOTREST RH <i>sc</i> ✓	70.00 ✓
1	FOOTREST BRACKET RH <i>sc</i> ✓	90.00 ✓
1	FOOTREST RUBBER RH <i>Xsu</i>	60.00 X
1	FRONT FENDER <i>sc</i> ✓	250.00 ✓
1	PILLION FOOTREST RH <i>sc</i> ✓	70.00 ✓
		5690.00
Less 10%		569.00
		5121.00
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
1	RIM <i>Xsu</i>	300.00 X
1	TYRE <i>Xsu</i>	300.00 X
2	GEAR SHAFT OIL SEAL <i>ne</i> ✓	24.00
1 BOT	FORK OIL SEAL <i>ntentah</i> ✓ <i>NEC</i>	120.00 <i>60</i>
	FORK OIL <i>ne</i> ✓	60.00 <i>40</i>
Subtotal		804.00
Balance C/F		5925.00
<u>LABOUR AND MISCELLANEOUS CHARGES</u>		
1	TO CHECK WIRING SYSTEM	60.00 X
2	TO CHECK FORK ALIGNMENT	200.00 <i>650</i>
3	TO REALIGN BODY FRAME	350.00 <i>150</i>
4	TO R&R SUSPENSION, HANDLE BAR, HEADLAMP & FAIRING	400.00 <i>250</i>
5	TO SPRAY FENDER, SIDE FAIRINGS AND AFFECTED AREAS	500.00 <i>200</i>
Subtotal		1510.00
Grand total		7435.00

Repair
Hp 90010068
4 days
4/5
31/03/21 @ 1450
Rising after repair

3176
10%
2858.40

124

650

KARZ WORKS PTE LTD
53 UBI AVENUE 1 #01-23, PAYA UBI INDUSTRIAL PARK
SINGAPORE 408934
(TEL) 6 8 4 4 5 9 3 4 (FAX) 6 8 4 4 2 4 7 4 - (E-MAIL) KARZWORKSSG@GMAIL.COM

FCI

REPAIR PERFORMA INVOICE

Vehicle number	FBJ2573Z
Make / Model	KTM 390
Chassis number	VBKJGJ406DC214980
Accident date	14/12/20
Reference	KK2103-52

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
1	BRAKE LEVER (AFTER MARKET) <i>SCR /</i>	80.00 65
1 SET	WING MIRROR (AFTER MARKET) <i>SCR /</i>	180.00 70
1	BODY SLIDER <i>SCR /</i>	150.00 120
1	STICKERS <i>me /</i>	500.00 200
	Subtotal	910.00
	Grandtotal	910.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2858.40

124.00

650.00

455.00

4087.40

20%

3269.92

41,325.00

4 days