

KARZ WORKS PTE LTD

53 UBI AVENUE 1 #01-23, PAYA UBI INDUSTRIAL PARK

SINGAPORE 408934

(TEL) 68445934 (FAX) 68442474 - (E-MAIL) KARZWORKSSG@GMAIL.COM

REPAIR PERFORMA INVOICE

FCI

Vehicle number	FBJ2573Z
Make / Model	KTM 390
Chassis number	VBKJGJ406DC214980
Accident date	14/12/20
Reference	KK2103-52

Qty Particulars Unit Price - SGD \$

<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	FRONT FORK ?	550.00
1	FRONT FORK BRACKET X	350.00
1 SET	BALANCER <i>scr</i>	150.00
1	HANDLE BAR	280.00
1	FRONT FAIRING UPPER LH <i>scr</i>	450.00
1	FRONT FAIRING LOWER LH <i>con</i>	450.00
1	FRONT FAIRING BOTTOM LH <i>con</i>	350.00
1	RADIATOR <i>st</i>	600.00
1	RADIATOR COVER LH <i>mis</i>	180.00
1	RADIATOR COVER RH <i>X</i>	180.00
1	RADIATOR FAN COWLING <i>de</i>	300.00
1	FRONT FAIRING UPPER RH <i>X</i>	400.00
1	FRONT FAIRING LOWER RH <i>X</i>	400.00
1	BODY FRAME BRACKET LH <i>repair</i>	200.00
1	BRAKE PEDAL <i>br</i>	90.00
1	FOOTREST LH <i>X</i>	70.00
1	FOOTREST BRACKET LH <i>X</i>	90.00
1	FOOTREST RUBBER LH <i>X</i>	60.00
1	FOOTREST RH <i>scr</i>	70.00
1	FOOTREST BRACKET RH <i>scr</i>	90.00
1	FOOTREST RUBBER RH <i>X</i>	60.00
1	FRONT FENDER <i>scr</i>	250.00
1	PILLION FOOTREST RH <i>scr</i>	70.00

Same
Hp 90010068
4 days
4s
31/03/21 @ 1450
Rising after repair

Less 10%

PARTS REPLACEMENT - SPECIAL NETT ITEMS

1	RIM X	300.00
1	TYRE X	300.00
2	GEAR SHAFT OIL SEAL <i>na</i>	24.00
1 BOT	FORK OIL SEAL <i>leaking</i>	120.00 60
	FORK OIL <i>na</i>	60.00 40

Subtotal

Balance C/F

LABOUR AND MISCELLANEOUS CHARGES

1	TO CHECK WIRING SYSTEM	60.00 X
2	TO CHECK FORK ALIGNMENT	200.00 150
3	TO REALIGN BODY FRAME	350.00 150
4	TO R&R SUSPENSION, HANDLE BAR, HEADLAMP & FAIRING	400.00 250
5	TO SPRAY FENDER, SIDE FAIRINGS AND AFFECTED AREAS	500.00 200

Subtotal

Grand total

7435.00