

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

1-Apr-21

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6387 J

| | | | |
|-------|----------------------------------------------|-------------|------|
| 1 pc | Rear bumper | \$ 696.00 | Rx |
| 2 pcs | Rear bumper n/s & o/s side bracket @ \$29.00 | \$ 58.00 | o/s? |
| 1 pc | Rear o/s wheel cover | \$ 116.00 | int |
| 1 pc | Rear o/s fender | \$ 1,205.00 | Rx |
| 1 pc | Rear o/s door | \$ 765.00 | bt |
| 1 pc | Rear windscreen moulding | \$ 98.00 | X |
| | | \$ 2,938.00 | |
| | | \$ 293.80 | |
| | | \$ 2,644.20 | |

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Less 10%

Acknowledged by Repairer

Signature:

Date:

S/NETT

| | | | |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------|-------------|---------|
| 1 set | Rear bumper clips | \$ 48.00 | X |
| 1 pc | Rear bumper top protector | \$ 80.00 | X |
| 1 pc | Rear o/s fender sticker | \$ 60.00 | Song |
| 1 set | o/s door stickers | \$ 100.00 | Song |
| 1 set | Sealant | \$ 50.00 | X |
| Sundry | | \$ 50.00 | X |
| To check rear o/s wheel alignment | | \$ 80.00 | ✓ |
| To dismantle and refit old windscreen glass onto new moulding | | \$ 120.00 | X |
| To dismantle / replace reverse sensor to new bumper and reset to the same | | \$ 120.00 | 30 |
| To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs. | | \$ 180.00 | X |
| To labour charge for dismantle and renew the accident damaged parts. To heat/weld & cut rear o/s fender. Including knock-out, straighten, repair, reshape and adjust of the same, etc. Refitting of rear o/s door inner components. | | \$ 1,000.00 | \$ 400. |
| To putty and spray painting on rear bumper, rear o/s fender, rear o/s door, front o/s door, o/s rocker panel garnish | | \$ 1,000.00 | 900 |
| To apply rustproofing on the repaired and replaced panels. | | \$ 120.00 | |
| | | \$ 5,652.20 | |

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)
THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES.