

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

1-Apr-21

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6387 J

1 pc	Rear bumper
2 pcs	Rear bumper n/s & o/s side bracket @ \$29.00
1 pc	Rear o/s wheel cover
1 pc	Rear o/s fender
1 pc	Rear o/s door
1 pc	Rear windscreen moulding

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed Less 10%
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanphie 27/4/21
WP' 5/4/21 @ 3:15pm
L/S Resurvey after repair
3 days
Tanphie 11/4/21

\$	696.00	Rx
\$	58.00	o/s Xny
\$	116.00	unt
\$	1,205.00	Rx
\$	765.00	bt
\$	98.00	Xny
\$	2,938.00	881
\$	293.80	
\$	2,644.20	792.90

S/NETT

1 set	Rear bumper clips	\$	48.00	Xny
1 pc	Rear bumper top protector	\$	80.00	Xny
1 pc	Rear o/s fender sticker	\$	60.00	Song
1 set	o/s door stickers	\$	100.00	Bone
1 set	Sealant	\$	50.00	Xny
	Sundry	\$	50.00	Xny
	To check rear o/s wheel alignment	\$	80.00	✓
	To dismantle and refit old windscreen glass onto new moulding	\$	120.00	Xny
	To dismantle / replace reverse sensor to new bumper and reset to the same	\$	120.00	30
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	180.00	Xny
	To labour charge for dismantle and renew the accident damaged parts. To heat/weld & cut rear o/s fender. Including knock-out, straighten, repair, reshape and adjust of the same, etc. Refitting of rear o/s door inner components.	\$	1,000.00	400.
	To putty and spray painting on rear bumper, rear o/s fender, rear o/s door, front o/s door, o/s rocker panel garnish	\$	1,000.00	800
	To apply rustproofing on the repaired and replaced panels.	\$	120.00	Xny

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)
THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES.

792.90
110
1340
2242.90
4591800
1340
1340