

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Cecilia Low

Date: 03 Jun 2021

Preliminary Advice

Insured Vehicle No	: SGX296D		
TP Vehicle No	: SMK6837B	Accident Date	: 30/03/2021
Make	: HYUNDAI AD AVANTE	Assignment Date	: 31/03/2021
Date of Inspection	: 06/04/2021	Est. Duration of Repair	: 5
Inspection At	: ISHARE AUTO PTE. LTD. (HQ) 8 KAKI BUKIT AVENUE 4 #08-09 PREMIER @ KAKI BUKIT SINGAPORE 415875		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,902.64
Revised Amount	:S\$	6,373.28
Check Items (Estimated)	:S\$	0.00
Total	:S\$	6,373.28
 Lump Sum Repair	 :S\$	 5,100.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :