



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLQ 8851B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	RR BUMPER (CONSISTENT)	DEFORMED	898.00	731.00
1	RR BUMPER SIDE RETAINER RH (CONSISTENT)	NECESSARY	91.30	91.30
1	RR BUMPER SIDE RETAINER LH(CONSISTENT)	NECESSARY	91.30	91.30
1	RR BUMPER REINFORCEMENT (CONSISTENT)	DENTED	560.00	315.00
1	RR BUMPER SPONGE RH (CONSISTENT)	CRACKED	164.00	164.00
1	RR BUMPER SPONGE LH (CONSISTENT)	CRACKED	164.00	164.00
1	RR TAILGATE (CONSISTENT)	TO REPAIR SEE LABOUR	1,570.00	-
1	RR TAILGATE NISSAN LOGO (CONSISTENT)	NECESSARY	95.00	95.00
1	RR TAILGATE PULSAR EMBLEM (CONSISTENT)	NECESSARY	105.00	105.00
1	RR TAILGATE LOCK (CONSISTENT)	NOT NECESSARY	227.00	-
1	RR TAILGATE LOCK CATCHER -STRIKER (CONSISTENT)	NOT NECESSARY	88.00	-
1	RR TAILGATE LOCK KEYLESS RECEIVER SENSOR (CONSISTENT)	CRACKED	103.00	103.00
1	RR TAILGATE REFLECTOR RH-T/LAMP FOG (CONSISTENT)	NOT NECESSARY	484.00	-
1	RR TAILGATE REFLECTOR LH-T/LAMP FOG (CONSISTENT)	NOT NECESSARY	484.00	-
1	RR TAILGATE WEATHERSTRIP (CONSISTENT)	CUT	228.00	228.00
1	RR TAILLAMP RH (CONSISTENT)	NOT NECESSARY	540.00	-
1	RR TAILLAMP LH(CONSISTENT)	NOT NECESSARY	540.00	-
1	RR END PANEL (CONSISTENT)	DENTED	898.00	685.00
1	RR END PANEL TOP GARNISH (CONSISTENT)	NOT NECESSARY	223.00	-
1	RR SPARE TYRE TOOL FOAM(CONSISTENT)	NOT NECESSARY	519.00	-
1	RR SPARE TYRE BOARD (CONSISTENT)	NOT NECESSARY	606.00	-
	LESS 10% DISCOUNT		-867.86	-277.26
			7,810.74	2,495.34
<b>SPECIAL NETT ITEMS</b>				
10	FENDER INNERSHIELD CLIP (SN)(CONSISTENT)	NOT NECESSARY	60.00	-
10	RR BUMPER CLIP (SN)(CONSISTENT)	NECESSARY	60.00	30.00
5	RR END PANEL TOP GARNISH CLIP (SN)(CONSISTENT)	NOT NECESSARY	30.00	-
1	RR WINDSCREEN SEALANT (SN)(CONSISTENT)	NOT NECESSARY	65.00	-

Report Ref No. CC4/ASM21004155/Aba3q2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	RR WINDSCREEN INNER SEAL (SN)(CONSISTENT)	NOT NECESSARY	40.00	-
1	RR WINDSCREEN SOLAR FILM (SN)(CONSISTENT)	NOT NECESSARY	200.00	-
			455.00	30.00
	<b>LABOUR</b>			
	TO DISMANTLE /RENEW THE ACCIDENT DAMAGED PORTION ,TO PANEL BEATING ,RESHAPE ,STAIGHTEN,ORIENTATE AND ALIGN REPAIR /REPLACEMENT PARTS.INCLUSIVE OF THE REPAIR OF RR TAILGATE .		1,400.00	600.00
	CARRY OUT SPRAY PAINTIGN ON ACCIDENT AFFECTED AREA RR BUMPER ,RR END PANEL ,RR SPARE TYRE PANEL ,RR FENDER LH ,RR TAILGATE ,RR FENDER RH .		1,400.00	600.00
	TO CONDUCT ANTI RUST OF UNDER CARRIAGE TUFF COAT.		120.00	60.00
	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS ,RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR .		160.00	30.00
	TO REMOVE AND REFIX REVERSE SENSOR AND CONDUCT TEST.		100.00	50.00
	TO REMOVE AND REFIX REVERSE CAMERA AND CONDUCT TEST.	NOT NECESSARY	100.00	-
	TO CONDUCT TRANSFER OF PARTS FROM OLD TAILGATE TO NEW TAILGATE.	NOT NECESSARY	200.00	-
	TO CONDUCT WATER LEAKAGE TEST AFTER REPAIR OF VEHICLE.	NOT NECESSARY	80.00	-
	TO REMOVE AND REFIX REAR TAIL GATE WINDSCREEN .	NOT NECESSARY	160.00	-
	TO REMOVE AND REFIX INTERIOR LINING FOR ASSIST REPAIR.		160.00	60.00
	TO PERFORM DIAGNOSIS RESET FAULTY CODE AFTER REPAIR VEHICLE .	NOT NECESSARY	300.00	-
			4,180.00	1,400.00
<b>GRAND TOTAL</b>			<b>12,445.74</b>	<b>3,925.34</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>3,100.00</b>

Report Ref No. CC4/ASM21004155/Aba3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.