

COMFORTDELGRO ENGINEERING PTE LTD

Date: 29.03.2021

REPAIR ESTIMATE

Time: 09:03:56

Page: 1

China Taiping
CP/P

LKK-

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010070
 ADDRESS : CITYCAB PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65551188

JOB NO : 305460823
 REGN NO : SHB3646L
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G3)
 DATE OF REGN : 14.11.2019
 DATE/TIME IN : 27.03.2021 09:20
 ACCIDENT DATE : 26.03.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-2282-G	REAR BUMPER	1	459.40	20.00	367.52	OK
0002 04-01-0104-2533-G	REAR BUMPER CTR MOULDING	1	451.25	20.00	361.00	RY
0003 04-01-0104-2532-G	REAR BUMPER SIDE BRKT RH	1	55.80	20.00	44.64	OK
0004 04-01-0104-0852-G	REAR BUMPER REFLECTOR RH	1	41.45	20.00	33.16	X
0005 04-01-0104-2698-G	TAILLAMP RH	1	870.40	20.00	696.32	OK
0006 04-01-0101-0111-G	REAR BUMPER CLIPS	10	22.00	20.00	17.60	OK
0007 04-01-0104-1150-A	REAR BUMPER MAT	1	50.00		50.00	OK

SUB-TOTAL : 1,570.24

JOB NATURE

0000 PB	PANEL BEATING	400.00	350
0001 SP	SPRAYPAINT CHARGE	300.00	250
0002 17-01	CHECK ALL LIGHTING	30.00	30
0003 L	R/I REVERSE SENSOR	120.00	30

COMFORTDELGRO ENGINEERING PTE LTD

Date: 29.03.2021

REPAIR ESTIMATE

China Taiping C/P

Time: 09:03:56

Page: 2

LKK-

COMPANY : THIRD PARTY'S CLAIMS (CAS)

CUSTOMER: 7010070

ADDRESS : CITYCAB PTE LTD

383 SIN MING DRIVE

SINGAPORE SINGAPORE 575717

65551188

JOB NO : 305460823
REGN NO : SHB3646L
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 14.11.2019
DATE/TIME IN : 27.03.2021 09:20
ACCIDENT DATE : 26.03.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

SUB-TOTAL : 850.00

TOTAL : 2,420.24

MVA NAME & SIGNATURE

DATE :

AUTHORISED : YES / NO

SURVEYOR NAME & SIGNATURE

DATE :

Taiping 97495749
'up' 24/3/21 @ 4pm
02 days
8/p Resurvey before paint
taiping@lkkauto.com

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date/Time: 27.03.2021 11:55 Page : 1

Team: ARC Repair TP(CFS0)1

JOB CARD

Sales Order:

JC NO.: 305460823

STOMER

VMS CITYCAB PTE LTD
STOMER NO. 7010070
DRESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
65551188
(R) (O)
(P)

ICOUNT CARD NO.

REGN NO.

SHB3646L

MILEAGE

MAKE :

HYUNDAI

FUEL

E.....1/2.....F

MODEL

IONIQ(G3)

DATE/TIME IN 27.03.2021 09:20

YR OF MANU.

14.11.2019

TARGET DATE

CHASSIS CODE

KMHC851CVLU183055

COMPLETION DATE/TIME:

JOB DESCRIPTION


Accident Date: 26.03.2021

NATURE: 3P 26.03.2021

S/NO

LABOR CODE

DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

Vehicle No.:

SHB3646L

Vehicle No.:

SHB3646L

LIMITS

Name of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard