

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: CHINA TAIPING	DATE	: 29/03/2021
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SJS6204X	KNAFW411MA5113659	
MODEL	: KIA CERATO FORTE		
CHASSIS NO		Ashes.	
<u>ACCIDENT DETAILS</u>		DATE	: 28-Mar-21
		TIME	: 16:45HRS
THIRD PARTY REQUESTOR / CONTACT : JACK LI			

QUOTATION SUMMARY

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BONNET <i>Dented</i>	1	\$ 830.50	\$ 830.50
2	FRONT BUMPER <i>Deformed</i>	1	\$ 620.00	\$ 620.00
3	FRONT BUMPER SIDE RETAINER <i>New LH</i>	2	\$ 62.40	\$ 124.80
4	HEADLAMP LH <i>Int</i>	1	\$ 588.60	\$ 588.60
5	HEADLAMP LOWER BRACKET LH <i>Best</i>	1	\$ 32.50	\$ 32.50
6	FRONT FENDER LH <i>Dented</i>	1	\$ 433.50	\$ 433.50
7	FRONT FENDER INNER PANEL LH <i>Reps</i>	1	\$ 366.50	\$ 366.50
8	FRONT FENDER COWLING LH <i>torn</i>	1	\$ 155.90	\$ 155.90
9	FRONT SHOCK ABSORBER LH <i>Best</i>	1	\$ 322.50	\$ 322.50
10	FRONT KNUCKLE ARM LH <i>Dented</i>	1	\$ 346.00	\$ 346.00
11	FRONT KNUCKLE ARM BEARING LH <i>2x1</i>	1	\$ 180.30	\$ 180.30
12	FRONT LOWER ARM LH <i>Best</i>	1	\$ 366.80	\$ 366.80
13	FRONT LINK STABILIZER ARM LH <i>2x1</i>	1	\$ 199.40	\$ 199.40
14	FRONT STEERING TIE ROD END LH <i>2x1</i>	1	\$ 103.00	\$ 103.00
15	STEERING RACK AND OPINION <i>New</i>	1	\$ 1,855.90	\$ 1,855.90
16	FRONT DRIVESHAFT ASSEMBLY LH <i>New</i>	1	\$ 1,533.30	\$ 1,533.30
17	FRONT DOOR LH <i>2x1</i>	1	\$ 1,155.30	\$ 1,155.30

62.40

1034

4973
4475.70

TOTAL PRICE	\$	9,214.80
LESS 10%	\$	921.48
SUB TOTAL PRICE	\$	8,293.32

SPECIAL NETT ITEMS

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT BUMPER CLIP	1	\$ 22.00	\$ 22.00
2	FRONT FENDER COWLING CLIP	1	\$ 20.00	\$ 20.00
3	FRONT WHEEL RIM	1	\$ 850.00	\$ 850.00
4	FRONT WHEEL TYRE	1	\$ 450.00	\$ 450.00

442

TOTAL	\$	1,342.00
--------------	-----------	-----------------

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,400.00	600	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,400.00	800	
3	TUFF COAT	\$ 250.00	40	
4	WIRING CHECK	\$ 180.00	30	
5	REFOCUS HEADLAMP BEAM	\$ 120.00	x	
6	TO REMOVE AND REFIX FRONT UNDERCARRIAGE	\$ 350.00	220	
7	WHEEL ALIGNMENT	\$ 120.00	80	
8	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	x	

1770

TOTAL	\$4,000.00
--------------	-------------------

ESTIMATE REPORT

TOTAL PARTS COST : \$ 9,635.32
TOTAL LABOUR COST : \$ 4,000.00
TOTAL REPAIR COST : \$ 13,635.32

APPROVED DETAILS

SURVEYOR
CONTACT NO

PART BY PART / LUMP SUM
NO OF DAYS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

FAX :

Adrian Lim
1/s 29/03/24

06 Days

Supplementary: 739.20
Total: 7426.80
1/s: 5.9K

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 (South Wing) #02-03 Singapore 415933

Tel: (+65) 6243 1373 | Fax: (+65) 6243 1376

Reg. No: 201427944N

TO	: CHINA TAIPING	DATE	: 29/03/2021
ATTENTION	: MOTOR CLAIMS DEPT	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
<u>VEHICLE DETAILS</u>			
VEHICLE NO	: SJS6204X		
MODEL	: KIA CERATO FORTE		
CHASSIS NO			
<u>ACCIDENT DETAILS</u>		DATE	: 28-Mar-21
		TIME	: 16:45HRS
THIRD PARTY REQUESTOR / CONTACT : JACK LI			

QUOTATION SUMMARY

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	SUPPORT PANEL <i>cracked</i>	1	\$ 788.30	\$ 788.30

TOTAL PRICE \$ 788.30

LESS 10% \$ 78.83

SUB TOTAL PRICE \$ 709.47

CLAIM DETAILS: LABOUR AND SPRAY PAINTING

1	REMOVE AND REFIX AIRCON CONDENSER AND REFILL AIRCON GAS	\$ 140.00	60	
2	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	\$ 120.00	60	

TOTAL \$260.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 709.47

TOTAL LABOUR COST : \$ 260.00

TOTAL REPAIR COST : \$ 969.47

APPROVED DETAILS

SURVEYOR :

Adrian
30/03/21
H.S.

Supplementary: 739.20