

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD717A**AAD2103-***Not Authorised*
11 Pys \$5950h

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

26 MAR 2021**SHD717A**

VF1ABL15AUC283320

RENAULT

LATITUDE

25/03/2021

CHINA

29/12/2017

PART**LIST**

1 REAR BOOT	\$	<i>B</i> 1,677.20 ✓
1 BOOT FINISHER	\$	<i>PL</i> 344.70 X
1 BOOT STRUT LH	\$	<i>L</i> 145.10 X
1 BOOT STRUT RH	\$	<i>R</i> 145.10 X
1 BOOT WEATHERSTRIP	\$	<i>SL</i> 178.20 X
1 BOOT HINGE LH	\$	<i>H</i> 254.20 X
1 BOOT HINGE RH	\$	<i>R</i> 254.20 X
1 BOOT BADGE 'RENAULT'	\$	<i>MC</i> 82.40 ✓
1 BOOT BADGE	\$	<i>MC</i> 95.80 ✓
1 BOOT REFLECTOR LAMP LH	\$	<i>SL</i> 277.70 X
1 BOOT REFLECTOR LAMP RH	\$	<i>SL</i> 277.70 ✓
1 BUMPER COVER REAR	\$	<i>BR</i> 561.70 ✓
1 BUMPER LOWER REAR	\$	<i>BR</i> 411.90 ✓
1 BUMPER REFLECTOR RH	\$	<i>SL</i> 16.60
1 BUMPER BRACKET CTR REAR	\$	<i>SL</i> 98.10
1 BUMPER BRACKET SIDE RH REAR	\$	<i>SL</i> 82.10
1 BUMPER RETAINER RH REAR	\$	<i>SL</i> 59.80
1 BUMPER BRACKET SIDE LH REAR	\$	<i>SL</i> 80.80
1 BUMPER RETAINER LH REAR	\$	<i>SL</i> 54.20
1 BUMPER BEAM REAR	\$	<i>R</i> 547.80
1 BUMPER BEAM BRACKET LH REAR	\$	<i>R</i> 114.50
1 BUMPER BEAM BRACKET RH REAR	\$	<i>R</i> 114.50
1 OUTER PANEL REAR (End Panel)	\$	<i>R</i> 745.80 X
1 OUTER PANEL REAR (End Panel)TRIM	\$	<i>SL</i> 404.56 X
1 FENDER PANEL REAR RH	\$	<i>R</i> 1,933.20 X
1 WHEELARCH REAR RH	\$	<i>SL</i> 275.40 X
1 TAILLAMP LH	\$	<i>SL</i> 401.40 X

Trans-cab Auto Services Pte Ltd**AAD2103-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD717A

- 1 TAILLAMP RH
- 1 BUMPER COVER FRT
- 1 BUMPER ABSORBER FRT
- 1 BUMPER BEAM FRT
- 1 BUMPER BRACKET KIT FRT RH
- 1 FENDER PANEL FRT RH
- 1 WHEELARCH FRT RH
- 1 HEADLAMP RH
- 1 BUMPER FOG LAMP GRILLE RH
- 1 WIPER RESERVOIR

\$	401.40	✓
\$	747.20	✓
\$	394.68	X
\$	663.70	X
\$	101.40	✓
\$	437.10	✓
\$	191.40	X
\$	743.60	✓
\$	207.21	X
\$	179.60	X
\$	13,701.95	
10% \$	1,370.20	
\$	12,331.76	

Special Nett

- 1SET PARKING AID
- 1SET FENDER CLIP
- 1SET FENDER LINER CLIP
- 1SET REAR BUMPER CLIP
- 1SET BUMPER LOWER REAR CLIP
- 1 REAR NUMBER PLATE WITH MOULDING
- 1 EXHAUST MOUNTING REAR
- 1 BUMPER CLIP FRT
- 1 BUMPER RETAINER CLIP FRT
- 1 BUMPER GRILLE LOWER CLIP
- 1 LICENSE PLATE WITH HOLDER FRT
- 1 BOOT STICKER TRANSCAB
- 1 BOOT STICKER TEL NO.
- 2 WINDSCREEN SEALANT
- 1 WINDSCREEN MOULDING
- 1 WINDSCREEN INNER SPONGE SEAL
- 1SET BUMPER BRACKET CTR CLIP
- 1SET BUMPER BRACKET SIDE CLIP RH RR
- 1SET BUMPER RETAINER RH CLIP RR
- 1SET BUMPER BRACKET SIDE CLIP LH RR
- 1SET BUMPER RETAINER CLIP LH RR
- 1 BUMPER CLIP FRT
- 1 BUMPER GRILLE LOWER CLIP

\$	700.00	X
\$	65.00	X
\$	60.00	X
\$	66.00	✓
\$	66.00	✓
\$	180.00	X
\$	17.82	X
\$	85.00	665A
\$	70.00	X
\$	70.00	X
\$	120.00	X
\$	100.00	305A
\$	100.00	305A
\$	150.00	} X
\$	200.00	
\$	130.00	
\$	33.00	
\$	10.00	
\$	20.00	
\$	10.00	
\$	20.00	}
\$	85.00	
\$	70.00	

Trans-cab Auto Services Pte Ltd**AAD2103-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD717A

TOTAL	\$	1,499.82
TOTAL PARTS	\$	13,831.58

LABOUR

To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.	\$	<i>nn</i> 300.00 <i>X</i>
Putty And Spray Painting Of The Affected Portion.	\$	3,000.00 <i>11001</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00 <i>8001</i>
To Rust-Proofing Of The Affected Areas.	\$	170.00 <i>601</i>
To reinstall rear bumper parking sensor.	\$	170.00 <i>601</i>
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00 <i>601</i>
To repair and realign rear exhaust pipe.	\$	<i>nn</i> 170.00 <i>X</i>
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>nn</i> 170.00 <i>X</i>
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00 <i>601</i>
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>nn</i> 170.00 <i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00 <i>X</i>

Trans-cab Auto Services Pte Ltd**AAD2103-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD717A

To Check Electrical Lighting Concerned.

\$

170.00

*401***TOTAL \$****7,880.00****Over All Total****\$****34,043.33****(LUMP SUM)****Repair Days*****20 DAYS******6 day***

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: