

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD717A**AAD2103-***Not available**11 Rps 8*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

26 MAR 2021**SHD717A**

VF1ABL15AUC283320

RENAULT

LATITUDE

25/03/2021

CHINA

29/12/2017

PART**LIST**

1 REAR BOOT	\$	<i>B</i> 1,677.20 ✓
1 BOOT FINISHER	\$	<i>R</i> 344.70 X
1 BOOT STRUT LH	\$	<i>R</i> 145.10 X
1 BOOT STRUT RH	\$	<i>R</i> 145.10 X
1 BOOT WEATHERSTRIP	\$	<i>R</i> 178.20 X
1 BOOT HINGE LH	\$	<i>R</i> 254.20 X
1 BOOT HINGE RH	\$	<i>R</i> 254.20 X
1 BOOT BADGE 'RENAULT'	\$	<i>R</i> 82.40 ✓
1 BOOT BADGE	\$	<i>R</i> 95.80 ✓
1 BOOT REFLECTOR LAMP LH	\$	<i>R</i> 277.70 X
1 BOOT REFLECTOR LAMP RH	\$	<i>R</i> 277.70 ✓
1 BUMPER COVER REAR	\$	<i>B</i> 561.70 ✓
1 BUMPER LOWER REAR	\$	<i>R</i> 411.90 ✓
1 BUMPER REFLECTOR RH	\$	<i>R</i> 16.60
1 BUMPER BRACKET CTR REAR	\$	<i>R</i> 98.10
1 BUMPER BRACKET SIDE RH REAR	\$	<i>R</i> 82.10
1 BUMPER RETAINER RH REAR	\$	<i>R</i> 59.80
1 BUMPER BRACKET SIDE LH REAR	\$	<i>R</i> 80.80
1 BUMPER RETAINER LH REAR	\$	<i>R</i> 54.20
1 BUMPER BEAM REAR	\$	<i>R</i> 547.80
1 BUMPER BEAM BRACKET LH REAR	\$	<i>R</i> 114.50
1 BUMPER BEAM BRACKET RH REAR	\$	<i>R</i> 114.50
1 OUTER PANEL REAR (End Panel)	\$	745.80 7
1 OUTER PANEL REAR (End Panel)TRIM	\$	<i>R</i> 404.56 X
1 FENDER PANEL REAR RH	\$	<i>R</i> 1,933.20 X
1 WHEELARCH REAR RH	\$	<i>R</i> 275.40 X
1 TAILLAMP LH	\$	<i>R</i> 401.40 X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2103-

SHD717A

1 TAILLAMP RH	\$	401.40 ✓
1 BUMPER COVER FRT	\$	747.20 ✓
1 BUMPER ABSORBER FRT	\$	394.68 X
1 BUMPER BEAM FRT	\$	663.70 X
1 BUMPER BRACKET KIT FRT RH	\$	101.40 ✓
1 FENDER PANEL FRT RH	\$	437.10 ✓
1 WHEELARCH FRT RH	\$	191.40 X
1 HEADLAMP RH	\$	743.60 ✓
1 BUMPER FOG LAMP GRILLE RH	\$	207.21 X
1 WIPER RESERVOIR	\$	179.60 X

	\$	13,701.95
10%	\$	1,370.20
	\$	12,331.76

Special Nett

1SET PARKING AID	\$	700.00 X
1SET FENDER CLIP	\$	65.00 X
1SET FENDER LINER CLIP	\$	60.00 X
1SET REAR BUMPER CLIP	\$	66.00 ✓
1SET BUMPER LOWER REAR CLIP	\$	66.00 ✓
1 REAR NUMBER PLATE WITH MOULDING	\$	180.00 X
1 EXHAUST MOUNTING REAR	\$	17.82 X
1 BUMPER CLIP FRT	\$	85.00 66.50
1 BUMPER RETAINER CLIP FRT	\$	70.00 X
1 BUMPER GRILLE LOWER CLIP	\$	70.00 X
1 LICENSE PLATE WITH HOLDER FRT	\$	120.00 X
1 BOOT STICKER TRANSCAB	\$	100.00 30.50
1 BOOT STICKER TEL NO.	\$	100.00 30.50
2 WINDSCREEN SEALANT	\$	150.00
1 WINDSCREEN MOULDING	\$	200.00
1 WINDSCREEN INNER SPONGE SEAL	\$	130.00
1SET BUMPER BRACKET CTR CLIP	\$	33.00
1SET BUMPER BRACKET SIDE CLIP RH RR	\$	10.00
1SET BUMPER RETAINER RH CLIP RR	\$	20.00
1SET BUMPER BRACKET SIDE CLIP LH RR	\$	10.00
1SET BUMPER RETAINER CLIP LH RR	\$	20.00
1 BUMPER CLIP FRT	\$	85.00
1 BUMPER GRILLE LOWER CLIP	\$	70.00

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD717A

AAD2103-

TOTAL	\$	1,499.82
TOTAL PARTS	\$	13,831.58

LABOUR

To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.	\$	nn	300.00	X
Putty And Spray Painting Of The Affected Portion.	\$		3,000.00	11001
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$		3,000.00	800
To Rust-Proofing Of The Affected Areas.	\$		170.00	601
To reinstall rear bumper parking sensor.	\$		170.00	601
To transfer of bootlid fittings, attachments and perform water seepage test.	\$		170.00	601
To repair and realign rear exhaust pipe.	\$	nn	170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	nn	170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$		170.00	601
To transfer of rear windscreen fittings and conduct water seepage test.	\$	nn	170.00	X
To check steering geometry and computer wheel alignment	\$	nn	220.00	X

Trans-cab Auto Services Pte Ltd
 No. 2 Ang Mo Kio Street 63 Singapore 569111
 Tel No. : 6287 6666 Fax No. : 6257 1330
 CO./GST Reg. No. 201019626G
SHD717A

To Check Electrical Lighting Concerned.

\$ 170.00 *401*

TOTAL \$ 7,880.00

Over All Total \$ 34,043.33

(LUMP SUM)

Repair Days

20 DAYS

6 days

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: