



## Section A - Accident Details

Registration Number	SHB1092Y
Case Reference Number	TAX/03/21/2089
Registration Date	28/11/2017
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	NG WAI SENG
Type of Accident	Head to Rear
Accident Date and Time	27/3/2021 4:00 PM
Accident Reported Date and Time	29/3/2021 2:24 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24110278
Special Instruction to ARC, if any	REAR PORTION / TOWED \$40
Prepared Date and Time	29/3/2021 9:45 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

## Section B - Summary of Repair Estimates

## Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$926.00	\$450.00
Total Spray Cost	\$1,854.00	\$500.00
Total Spare Part Cost	\$4,108.49	\$1,517.95
Total Other Cost	\$516.00	(\$417.95)
<b>TOTAL COST</b>	<b>\$7,404.49</b>	<b>\$2,050.00 (L/S)</b>
<b>Lump Sum Total</b>	<b>\$7,400.00</b>	<b>\$0.00</b>
Number of Repair Days	5.0	3.0
Prepared / Adjusted By	Kim Ming Chin	Sun Pin (LKK) / NTUC
ARC / Surveyor Sign Off Date	01/04/2021 12:36 PM	01/04/2021 11:24 AM
Signature		
Remarks	Total number of repair days = 3 days SUP = + 1 day.	L/S, after paint photo.

## Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2104-0146	Invoice Number	
Quotation Date	14.04.2021	Invoice Date	
Invoice Amount		Prepared Date	

## Section D - Details of Repair Estimates

## Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR END PANEL	\$250.00	\$150.00 /supp
TO REPAIR REAR PORTION	\$676.00	\$300.00 /
<b>Total Labour</b>	<b>\$926.00</b>	<b>\$450.00 /</b>

## Part 2 - Spray Painting &amp; Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR PANEL	\$180.00	\$100.00 /supp
TO RESPRAY REAR BUMPER	\$378.00	\$200.00 /
TO RESPRAY REAR BUMPER REINFORCEMENT	\$180.00	\$0.00
TO RESPRAY FILLER RR BUMPER RH	\$180.00	\$100.00 /
TO RESPRAY TAIL GATE	\$378.00	\$0.00
TO RESPRAY TAILGATE OUTSIDE GARNISH	\$180.00	\$100.00 /
TO RESPRAY REAR FENDER RH	\$378.00	\$0.00
<b>Total Spray Painting &amp; Panel Beating</b>	<b>\$1,854.00</b>	<b>\$500.00 /</b>

## Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Lump Sum Adjustment by Surveyor	\$0.00	(\$497.95)
TOWING CHARGE	\$56.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00 /
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$30.00 /
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$30.00 /
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
<b>Total Other Costs</b>	<b>\$516.00</b>	<b>(\$417.95)</b>

## Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52159479 13	COVER, RR BUMPER ASSY	1.00	\$423.90	25.00	\$317.93	Replace	Replace
		52462470 30	PAD, RR BUMPER, RH & LH , 1	2.00	\$3.80	25.00	\$5.70	Replace	Replace
		52462470 20	PAD, RR BUMPER, RH & LH , 2	2.00	\$3.80	25.00	\$5.70	Replace	Replace
		52462470 10	PAD, RR BUMPER, RH & LH , 3	2.00	\$3.80	25.00	\$5.70	Replace	Replace
		52191470 30	SEAL, RR BUMPER ARM, RH & LH	0.00	\$11.00	0.00	\$0.00	Replace	Not Given
		52453470 10	GUARD, RR BUMPER, LOWER	1.00	\$558.30	25.00	\$418.73	Replace	Replace
		52169470 20	COVER, GUARD RR BUMPER LOWER	1.00	\$14.80	25.00	\$11.10	Replace	Replace
		52461470 10	PAD, RR BUMPER, CTR	3.00	\$2.20	25.00	\$4.95	Replace	Replace
		66259470 10	COVER, REAR FLOOR UNDER CENTER	0.00	\$222.60	0.00	\$0.00	Replace	Not Given

CR4

NEC

NEC

NEC

SVC

CR4

CRU

NEC

SVC

# SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 14/04/2021

User ID : PohSuan

		58398470 50	COVER, REAR FLOOR UNDER, RH	0.00	\$169.50	0.00	\$0.00	Replace	Not Given	X
			SENSOR REVERSE	1.00	\$180.00	0.00	\$180.00	Replace	Replace	/
		52023470 30	REAR BUMPER REINFORCEMENT	1.00	\$318.80	25.00	\$239.10	Replace	Replace	/
		52575470 40	RETAINER, RR BUMPER, RH	0.00	\$112.70	0.00	\$0.00	Replace	Not Given	X
		52591470 50	SEAL, RR BUMPER , RH	0.00	\$85.20	0.00	\$0.00	Replace	Not Given	X
		52565479 00	FILLER, RR BUMPER , RH	1.00	\$119.90	25.00	\$89.93	Replace	Replace	/
		90467062 06C0	CLIP SEAL, RR BUMPER , RH & LH	0.00	\$2.00	0.00	\$0.00	Replace	Not Given	X
		52161160 10	CLIPS PIECE, FRT & RR BUMPER	10.00	\$1.50	25.00	\$11.25	Replace	Replace	/
		81581470 10	LENS & BODY ASSY , RR BUMPER , RH	0.00	\$486.80	0.00	\$0.00	Replace	Not Given	X
		81551472 81	LENS & BODY, REAR COMBINATION LAMP , RH	0.00	\$438.10	0.00	\$0.00	Replace	Not Given	X
			PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace	/
		67005474 40	TAIL GATE PANEL SUB- ASSY, BACK DOOR	0.00	\$929.60	0.00	\$0.00	Replace	Not Given	X
		69350470 50	TAIL GATE LOCK ASSY, BACK DOOR	0.00	\$452.10	0.00	\$0.00	Replace	Not Given	X
		76801471 10A1	TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-	1.00	\$891.20	100.00	\$0.00	Replace	Repair	/
		75441470 90	NAME PLATE (HYBRID) , LUGGAGE COMPARTMENT	1.00	\$52.30	25.00	\$39.23	Replace	Replace	/
		75442471 30	NAME PLATE (PRIUS) , LUGGAGE COMPARTMENT	1.00	\$52.30	25.00	\$39.23	Replace	Replace	/
			STICKER DECAL 6555 8888	1.00	\$21.60	0.00	\$21.60	Replace	Replace	/
			STICKER SMRT LOGO	1.00	\$7.80	0.00	\$7.80	Replace	Replace	/
		61601471 50	PANEL SUB-ASSY, FENDER REAR RH	0.00	\$824.80	0.00	\$0.00	Replace	Not Given	X
Total					\$6,450.40		\$1,517.95			

SVC  
Short  
BT  
SVC  
SVC  
Cut  
SVC  
Nec  
SVC  
SVC  
Nec  
SVC  
R  
Nec  
Nec  
Nec  
Nec  
SVC

## Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

1517.95 /  
+ 450.00 /  
+ 580.00 /  
-----  
2547.95 /  
- 20%  
-----  
2038.36 /  
L/S \$2050 /-  
3 days  
SHB 10924