



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2105446

INV Date 03/08/2021

Reference CC4/LPC21004213/T1ga3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SLM 8332D
Insured Veh. XE 957D
Claim No. 21/21/21/VC05/024395
Policy No. Z21VC05007160
Accident Date 25/03/2021
Inspection Date 26/03/2021

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CC4/LPC21004213/T1ga3q2 Date: 03/08/2021 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XE 957D	Veh. Inspected	SLM 8332D	
Policy No.	Z21VC05007160	Coverage (\$)	0.00	
Claim No.	21/21/21/VC05/024395	Excess (\$)	0.00	
Assign From	GERALD	Assign Date	26/03/2021	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA LEXUS RX200T	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JTJBAMCA502025673	Colour	WHITE	
Odometer	66363 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/55 R20	CONTINENTAL	6 mm	
L/H Front Tyre	235/55 R20	CONTINENTAL	6 mm	
R/H Rear Tyre	235/55 R20	CONTINENTAL	6 mm	
L/H Rear Tyre	235/55 R20	CONTINENTAL	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	25/03/2021	Inspection Date	26/03/2021	
Survey held at	TAN LIM MOTOR PTE LTD NO.1 DEFU LANE 6 SINGAPORE 539365			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			7 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLM 8332D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	DEFORMED	812.50	812.50
8	FRONT BUMPER CLIPS @\$4.30	NECESSARY	34.40	34.40
1	O/S FRONT BUMPER SIDE RETAINER	CRACKED	97.20	97.20
1	FRONT BUMPER TOP RUBBER SEAL	NOT NECESSARY	51.30	-
1	O/S HEADLAMP	CRACKED	7,159.20	7,159.20
1	O/S HEADLAMP BRACKET	NOT NECESSARY	85.00	-
1	O/S HEADLAMP PANEL	TO REPAIR SEE LABOUR	195.00	-
1	O/S FRONT FENDER	BENT	776.70	776.70
1	O/S FRONT FENDER INNER COWLING	TORN	386.75	386.75
6	O/S FRONT FENDER CLIPS @\$4.30	NECESSARY	25.80	25.80
1	O/S FRONT FENDER CENTER GARNISH	DEFORMED	135.00	135.00
1	O/S FRONT FENDER EXTENSION	BENT	198.00	198.00
1	O/S FRONT WIND DEFLECTOR	TORN	78.90	78.90
1	O/S FRONT DOOR	BENT	1,069.30	1,069.30
2	O/S FRONT DOOR TOP & BOTTOM HINGE @\$84.05	TO REPAIR SEE LABOUR	168.10	-
1	O/S FRONT DOOR OUTER CHROME MOULDING	NOT NECESSARY	154.00	-
1	O/S FRONT DOOR RUBBER MOULDING	NOT NECESSARY	200.30	-
1	O/S FRONT DOOR LOWER OUTER GARNISH	NOT NECESSARY	548.00	-
1	O/S A PILLAR SIDE MOULDING	MISSING	283.10	283.10
1	RADIATOR TOP PANEL GARNISH	NOT NECESSARY	475.00	-
1	ABS PUMP ASSY	NOT NECESSARY	7,084.20	-
1	O/S FRONT WHEEL RIM	CUT	2,892.70	2,892.70
1	O/S FRONT WHEEL BEARING	NOT NECESSARY	529.75	-
1	O/S FRONT LOWER ARM	NOT NECESSARY	782.20	-
1	O/S FRONT ABSORBER	NOT NECESSARY	494.70	-
6	RADIATOR TOP PANEL GARNISH CLIPS @\$4.50	NOT NECESSARY	27.00	-
7	RIVET @\$4.30 (ADDITIONAL)	NECESSARY	30.10	30.10
3	O/S FENDER INNER GARNISH CLIPS @\$4.30 (ADDITIONAL)	NECESSARY	12.90	12.90
1	BONNET (ADDITIONAL)	BENT	1,983.90	1,983.90

Report Ref No. CC4/LPC21004213/T1ga3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	O/S FRONT 1/4 GLASS GARNISH (ADDITIONAL)	MISSING	93.70	93.70
1	O/S FRONT FENDER WHEEL ARCH MOULDING (ADDITIONAL)	DEFORMED	162.50	162.50
	LESS 30% DISCOUNT		-8,108.16	-4,869.79
			18,919.04	11,362.86
	<u>SPECIAL NETT ITEMS</u>			
1	O/S FRONT TYRE (SN)	NOT NECESSARY	450.00	-
1	FRONT WINDSCREEN SEALANT (SN)	NOT NECESSARY	80.00	-
			530.00	-
	<u>LABOUR</u>			
	PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME .INCLUSIVE OF THE REPAIR OF O/S HEADLAMP PANEL AND O/S FRONT DOOR TOP & BOTTOM HINGE.		1,600.00	1,100.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		100.00	30.00
	TO REINSTALL OF FRONT BUMPER PARKING SENSOR .		120.00	30.00
	TO TRANSFER OF TYRE ,RIM AND ON WHEEL BALANCING .		80.00	30.00
	TO DROP FRONT SUSPENSION UNDERCARRIAGE PARTS ,REMOVE AND RENEWAL OF THE AFFECTED PARTS ,TO PERFORM FINAL CHECKING AND TESTING.	NOT NECESSARY	350.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT .		100.00	80.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION .		1,600.00	1,200.00
	USING ONBOARD SCAN TOOL (OBD) PERFORM FULL ENGINE DIAGNOSTIC CHECK ,TO CONFIGURE AND CLEAR ,RESET SRS SERVICE LIGHT.	NOT NECESSARY	380.00	-
	TO REMOVE AND REFIT FRONT WINDSCREEN GLASS .	NOT NECESSARY	120.00	-
	TO TRANSFER OF DOOR FITTINGS AND PERFORM WATER SEEPAGE TEST .		180.00	60.00
	TO RUST -PROOFING OF THE AFFECTED AREAS.		380.00	40.00
			5,010.00	2,570.00
GRAND TOTAL			24,459.04	13,932.86

Report Ref No. CC4/LPC21004213/T1ga3q2



RECOMMENDED COST OF REPAIRS			13,932.86
-----------------------------	--	--	-----------

Report Ref No. CC4/LPC21004213/T1ga3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLM 8332D

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLM 8332D

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLM 8332D

RE-INSPECTION

