

ASS. REC. BY:

Tang Jkh

REF:

LPC

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$153K

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No:

SLM8332D

Yr Regn:

2017 April

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Lexus RX200 c.c 1998

Colour

white

A/C: Insured / Std / NI / NA

Sp. Reading

66363

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JT JRAM C4502025673

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

235/55R20

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

26/3/21

Survey held at

Tan Lim

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

Preli. Report

1)

Date/Time, File Return to?

☐

Final Report

2)

Rep. Format:

Lump Sum / I.B.I. (%)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL



陳林摩哆私人有限公司  
TAN LIM MOTOR PTE LTD

Lonpac Insured's Veh No : XE957D

Date of Accident : 25 March 2021

1 Defu Lane 6 Singapore 539365  
Tel : 68585151 ( 24 Hours ) Fax : 68580877

GST Regn. No. : M2-8922054-2

Messrs Tan Well Engineering Pte Ltd

Date : 26 March 2021

Estimate To Repair SLM8332D - Toyota Lexus RX200T LUXURY AT S/R

Chassis No : JTJBAMCA502025673

S/No	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
01	1 pc	front bumper	\$ 812.50
02	8 pc	front bumper clips @ \$4.30	\$ 34.40
03	1 pc	o/s front bumper side retractor	\$ 97.20
04	1 pc	front bumper top rubber seal	\$ 51.30
05	1 pc	o/s headlamp	\$ 7,159.20
06	1 pc	o/s headlamp bracket	\$ 85.00
07	1 pc	o/s headlamp panel	\$ 195.00
08	1 pc	o/s front fender	\$ 776.70
09	1 pc	o/s front fender inner cowling	\$ 386.75
10	6 ps	o/s front fender clips @ \$4.30	\$ 25.80
11	1 pc	o/s front fender inner garnish	\$ 135.00
12	1 pc	o/s front fender extension bracket	\$ 198.00
13	1 pc	o/s front wind deflector	\$ 78.90
14	1 pc	o/s front door	\$ 1,069.30
15	2 ps	o/s front door top & bottom hinge @ \$84.05	\$ 168.10
16	1 pc	o/s front door outer chrome moulding	\$ 154.00
17	1 pc	o/s front door rubber moulding	\$ 200.30
18	1 pc	o/s front door lower outer garnish	\$ 548.00
19	1 pc	o/s A pillar side moulding	\$ 283.10
20	1 pc	radiator top panel garnish	\$ 475.00
21	1 pc	ABS pump assy	\$ 7,084.20
22	1 pc	o/s front wheel rim	\$ 2,892.70
23	1 pc	o/s front wheel bearing	\$ 529.75
24	1 pc	o/s front lower arm	\$ 782.20
25	1 pc	o/s front absorber	\$ 494.70
26	6 ps	radiator top panel garnish clips @ \$4.50	\$ 27.00
		→ Bonnet	\$ 24,744.10
		Less 30 %	\$ 7,423.23
			\$ 17,320.87
		<u>SPECIAL NETT ITEMS</u>	
27	1 pc	o/s front tyre	\$ 450.00
28	1 pc	front windscreen sealant	\$ 80.00
			\$ 530.00
		<u>LABOUR &amp; MISC. CHARGES</u>	
01		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 1,600.00
02		To check electrical lighting concerned.	\$ 100.00

Rev: 246  
26/03/2021 C15256

1100  
30





陳林摩哆私人有限公司  
TAN LIM MOTOR PTE LTD

Lonpac Insured's Veh No : XE957D

Date of Accident : 25 March 2021

1 Defu Lane 6 Singapore 539365  
Tel : 68585151 ( 24 Hours ) Fax : 68580877

GST Regn. No. : M2-8922054-2

Messrs Tan Well Engineering Pte Ltd

Date : 26 March 2021

Estimate To Repair SLM8332D - Toyota Lexus RX200T LUXURY AT S/R

Chassis No : JTJBAMCA502025673

S/No	Quantity	Description	Amount
		<b>LABOUR &amp; MISC. CHARGES</b>	
03		To reinstall of front bumper parking sensor.	\$ 120.00
04		To transfer of tyre, rim and on wheel balancing.	\$ 80.00
05		To drop front suspension undercarriage parts, remove and renewal of the necessary parts, to perform final checking and testing.	\$ 350.00
06		To check steering geometry and computer wheel alignment.	\$ 100.00
07		Putty and spray painting of the affected portion.	\$ 1,600.00
08		Using onboard scan tool (OBD) perform full engine diagnostic check, to configure and clear, reset SRS service light.	\$ 380.00
09		To remove and refit front windscreen glass.	\$ 120.00
10		To transfer of door fittings and perform water seepage test.	\$ 180.00
11		To rust-proofing of the affected areas.	\$ 380.00
			\$ 5,010.00
		<b>Total</b>	<b>\$ 22,860.87</b>

Tanpin 974915745  
WP' 26/3/21 @ 330pm  
p/p Reoving before paint-  
tanpin @ lkhauto.com.  
6-7 days

**LKK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 554H

### Vehicle Details

Vehicle No.: SLM8332D

Vehicle to be Exported: No

Intended Deregistration Date: 25 Mar 2021

Vehicle Make: TOYOTA

Vehicle Model: LEXUS RX200T LUXURY AT S/R

Primary Colour: White

Manufacturing Year: 2017

Engine No.: 8ARW523943

Chassis No.: JTJBAMCA502025673

Maximum Power Output: 175.0 kW (234 bhp)

Open Market Value: \$56,222.00

Original Registration Date: 13 Apr 2017

First Registration Date: 13 Apr 2017

Transfer Count: 0

Actual ARF Paid: \$73,200.00

### Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 12 Apr 2027

PARF Rebate Amount: \$54,900.00

### Intended COE Rebate Details

COE Expiry Date: 12 Apr 2027

COE Category: B - Car above 1600cc or 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$54,000.00

COE Rebate Amount: \$32,667.00

**Total Rebate Amount: \$87,567.00**

The information contained herein is correct as at 25 Mar 2021

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission	25/03/2021 18:20 (SGT)
Date of Accident	25/03/2021 14:55 (SGT)
Exact Location of Accident	Near 10 Defu Lane 5, Singapore 539397
Additional Location Information	-
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLM8332D
INSURED/POLICYHOLDER	
Is company?	Yes
Name Of Registered Owner	Tan Well Engineering Pte Ltd
Company Reg No	1XXXXX554H
Email Address	chloe@tanwell.com.sg
Mobile Phone No	(Phone) +65-91388657
Alternative Phone No	+65-98239392

### VEHICLE PARTICULARS

Manufacturer	Toyota
Model	LEXUS RX200T LUXURY AT S/R
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1998

### INSURANCE COMPANY

Name of Insurance Company	NTUC Income Insurance Co-operative Ltd
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	5108025079-01
Cover Note Number	-

### DRIVER

Name of Driver	Tan Ah Huat
NRIC No	SXXXX003I

Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-



Describe Circumstances of the Accident

SLM8332D was parked at Lot 5 along Jifu Lane S  
 XE957D reversed and hit the front right side of SLM8332D

Declaration

We declare the foregoing particulars are true in every respect



Policyholder's Signature - Date & Time

Driver's Signature (if driver is not the policyholder) - Date & Time

Witnessed by Reporting Centre Personnel

*[Signature]*  
 25/02/2021 14:30h

*[Signature]*  
 Cam [unclear]