



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS  
WORKSHOP : UBI ROAD 1  
CONTACT NO : 6366 2323  
FAX NO : 6841 1183  
REFERENCE : PA/OD/0273/2021/HR  
DATE : 31-Mar-21  
WIP : 21696

VEHICLE TOWED IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 1/4/21

**AIG ASIA PACIFIC INSURANCE PTE LTD**

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR. TAY CHING KOCK  
ADDRESS : 235 PASIR RIS ST 21  
#02-59  
SINGAPORE 510235  
TELEPHONE : 65 93850621  
TYPE OF CLAIM : OWN DAMAGE CLAIM  
POLICY NO : 1900173682-01  
VEHICLE NO : **SMP 9739 E**  
MODEL CODE : A6 2.0 TFSI S TRONIC  
MODEL YEAR : 24/10/2019  
ENGINE NO : DLH 065560  
CHASSIS NO : WAUZZZF29LN016034  
MILEAGE : -  
DATE IN : -  
ESTIMATED BY : JOHNNY BOO / ALLAN WU  
ACCIDENT DATE : 31-Mar-21  
PLACE OF ACCIDENT : LOYANG AVENUE

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMP 9739 E

| S/N                  | NATURE OF JOBS                                                                                                                                                                                                | ESTIMATED CHARGES                                                       | SURVEYOR'S RECOMMENDATIONS |
|----------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------|----------------------------|
| 1                    | TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.                                                              | S/N \$ 480.00 ✓                                                         |                            |
| 2                    | TO REMOVE AND RENEW AIRCON CONDENSER, CHARGED AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS. (R1234)                              | S/N \$ 1,700.00 ? ✓                                                     |                            |
| 3                    | TO DISMANTLE AND REINSTALL BOTH FRONT DOOR PANEL TRIMS. TO REMOVE AND REINSTALL BOTH WING MIRROR ASSYS. <i>LH only.</i>                                                                                       | S/N \$ 800.00 360 ✓                                                     |                            |
| 4                    | TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNITS AND POWER MODULES.                                                                                                                                      | S/N \$ 800.00 250 ✓                                                     |                            |
| 5                    | TO DISMANTLE AND RENEW FRONT BUMPER, BOTH FRONT FENDERS, BONNET AND BOTH HEADLIGHTS. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. | \$ 6,300.00 1500 (Without Lock Carrier) X<br>2750 (With Lock Carrier) ✓ |                            |
| 6                    | TO RESPRAY FRONT BUMPER, BONNET, HINGES, BOTH FRONT FENDERS, BOTH UPPER A-PILLARS AND BOTH FRONT DOORS. <i>LH only.</i>                                                                                       | \$ 7,800.00 3300 ✓<br>7 x 530 = 3710<br>3850                            |                            |
| 7                    | TO CARRY OUT DIAGNOSTIC CHECK.                                                                                                                                                                                | S/N \$ 384.00 ✓                                                         |                            |
| TOTAL LABOUR CHARGES |                                                                                                                                                                                                               | : \$ 18,264.00                                                          |                            |

55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMP 9739 E**

|                              |                                                   |     | DAMAGED PARTS & PRICES |         |
|------------------------------|---------------------------------------------------|-----|------------------------|---------|
| S/N                          | PARTS DESCRIPTION                                 | QTY | S/NETT                 | REMARKS |
| 1                            | FRONT BUMPER <i>Distorted</i>                     | 1   | \$ 2,832.00            | ✓       |
| 2                            | FRONT BUMPER FIXING PARTS <i>new</i>              | 1   | \$ 650.00              | ✓       |
| ③                            | FRONT BUMPER CLOSING ELEMENT - CTR <i>new</i>     | 1   | \$ 222.00              | ✓       |
| 4                            | FRONT BUMPER ADAPTER - LH / RH                    | 2   | \$ 78.00               | 7       |
| 5                            | FRONT BUMER REINFORCEMENT - LH / RH <i>Best</i>   | 2   | \$ 222.00              | ✓       |
| 6                            | FRONT BUMPER LOWER GRILLE - CTR <i>2 behind</i>   | 1   | \$ 153.00              | ✓       |
| 7                            | FRONT BUMPER LOWER CLOSING ELEMENT <i>for new</i> | 1   | \$ 210.00              | ✓       |
| 8                            | FRONT BUMPER SPOILER <i>new</i>                   | 1   | \$ 252.00              | ✓       |
| 9                            | FRONT BUMPER AIR GUIDE GRILLE - LH / RH           | 2   | \$ 868.00              | ✓       |
| 10                           | FRONT BUMPER OUTER AIR GUIDE - LH / RH <i>new</i> | 2   | \$ 58.00               | ✓       |
| 11                           | FRONT BUMPER INNER AIR GUIDE - LH / RH            | 2   | \$ 42.00               | ✓       |
| 12                           | FRONT RADIATOR GRILLE <i>smashed</i>              | 1   | \$ 2,217.00            | ✓       |
| 13                           | FRONT RADIATOR GRILLE COVER                       | 1   | \$ 54.00               | ✓       |
| 14                           | FRONT RADIATOR COVER CAP                          | 1   | \$ 89.00               | ✓       |
| 15                           | FRONT RADIATOR BRACKET                            | 1   | \$ 93.00               | ✓       |
| 16                           | FRONT RADIATOR SECURING PLATE                     | 1   | \$ 84.00               | ✓       |
| ①7                           | FRONT CAMERA <i>cut</i>                           | 1   | \$ 906.00              | ✓       |
| 18                           | FRONT CAMERA ADAPTER CABLE                        | 1   | \$ 416.00              | ✓       |
| 19                           | FRONT CAMERA FLAT CONNECTOR BRACKET               | 1   | \$ 14.00               | ✓       |
| 20                           | FRONT CAMERA CONNECTOR HOUSING BRACKET            | 1   | \$ 28.00               | ✓       |
| <b>SUB TOTAL SPARE PARTS</b> |                                                   |     | <b>\$ 9,488.00</b>     |         |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## **MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMP 9739 E**

|                              |                                                                    |     | DAMAGED PARTS & PRICES |         |
|------------------------------|--------------------------------------------------------------------|-----|------------------------|---------|
| S/N                          | PARTS DESCRIPTION                                                  | QTY | S/NETT                 | REMARKS |
| 21                           | FRONT BUMPER WIRING SET <i>2 New</i>                               | 1   | \$ 577.00              | X       |
| 22                           | FRONT PARKING AID SENSOR                                           | 4   | \$ 1,074.00            | X       |
| 23                           | FRONT PARKING AID SENSOR ASSIST ?                                  | 1   | \$ 268.00              | 44 ?    |
| 24                           | FRONT PARKING AID SENSOR SEAL RING ?                               | 6   | \$ 21.00               | ca ?    |
| 25                           | FRONT BUMPER FOAM FILLER PIECE <i>Del'd</i>                        | 1   | \$ 226.00              | ✓       |
| 26                           | FRONT BUMPER CARRIER <i>But</i>                                    | 1   | \$ 1,012.00            | ✓       |
| 27                           | FRONT BUMPER POP RIVERT <i>new</i>                                 | 6   | \$ 5.00                | ✓       |
| 28                           | FRONT BUMPER SUPPORT <i>ca</i>                                     | 2   | \$ 59.00               | ?       |
| 29                           | FRONT BUMPER BRACKET - LH / RH <i>ca</i>                           | 2   | \$ 108.00              | ?       |
| 30                           | FRONT BUMPER GUIDE SECTION - LH / RH <i>ca</i> <i>Not</i>          | 2   | \$ 88.00               | X 44    |
| 31                           | FRONT BUMPER COVER <i>ca</i>                                       | 1   | \$ 126.00              | ✓       |
| 32                           | WARNING SIGN <i>2 New</i>                                          | 1   | \$ 30.00               | ✓       |
| 33                           | AIR CONDITIONER STICKER                                            | 1   | \$ 8.00                | ✓       |
| 34                           | FRONT FANFARE HORN - HIGH / LOW TONE - LH / RH <i>Not</i>          | 2   | \$ 432.00              | X       |
| 35                           | FRONT FANFARE HORN SPRING SHACKLE <i>new</i>                       | 2   | \$ 94.00               | X       |
| 36                           | FRONT FENDER - LH / RH <i>ca</i> <i>RH Rep's</i> <i>LH Buckled</i> | 2   | \$ 2,936.00            | 1468    |
| 37                           | FRONT FENDER ATTACHMENT PARTS <i>new</i>                           | 1   | \$ 42.00               | X       |
| 38                           | FRONT FENDER BRACE - LH / RH <i>ca</i>                             | 2   | \$ 236.00              | ?       |
| 39                           | FRONT FENDER BRACKET - LH / RH                                     | 2   | \$ 88.00               | ?       |
| 40                           | FRONT FENDER CLOSING ELEMENT - LH / RH                             | 2   | \$ 106.00              | ?       |
| <b>SUB TOTAL SPARE PARTS</b> |                                                                    |     | <b>\$ 7,536.00</b>     |         |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMP 9739 E

|                       |                                     |     | DAMAGED PARTS & PRICES |         |
|-----------------------|-------------------------------------|-----|------------------------|---------|
| S/N                   | PARTS DESCRIPTION                   | QTY | S/NETT                 | REMARKS |
| 41                    | FRONT WHEEL HOUSING LINER LH        | 1   | \$ 275.00              | X       |
| 42                    | FRONT WHEEL HOUSING LINER RH        | 1   | \$ 266.00              | X       |
| 43                    | WHEEL HOUSING LINER ATTACHMENT PART | 1   | \$ 71.00               | +       |
| 44                    | FRONT WHEEL SPOILER LH / RH         | 2   | \$ 332.00              | +       |
| 45                    | FRONT STONE CHIP GUARD LH / RH      | 2   | \$ 102.00              | +       |
| 46                    | SILL PANEL TRIM BRACKET LH / RH     | 2   | \$ 80.00               | ✓       |
| 47                    | BONNET                              | 1   | \$ 5,528.00            | ✓       |
| 48                    | BONNET HINGE LH / RH                | 2   | \$ 344.00              | ?       |
| 49                    | BONNET ATTACHMENT PARTS             | 1   | \$ 233.00              | +       |
| 50                    | BONNET ABSORBER                     | 2   | \$ 241.00              | 12000   |
| 51                    | BONNET IMPACT PROTECTION LH / RH    | 2   | \$ 38.00               | ✓       |
| 52                    | BONNET IMPACT PROTECTION CTR        | 1   | \$ 44.00               | ✓       |
| 53                    | BONNET STRIKER LH / RH              | 2   | \$ 220.00              | ?       |
| 54                    | BONNET LOCK WITH SWITCH             | 2   | \$ 419.00              | ?       |
| 55                    | FRONT FENDER TOP COVER LH / RH      | 2   | \$ 64.00               | 32      |
| 56                    | BONNET HINGE COVER LH / RH          | 2   | \$ 88.00               | +       |
| 57                    | PLENUM CHAMBER COVER                | 1   | \$ 200.00              | +       |
| 58                    | FRONT FENDER TOP LEDGE COVER        | 2   | \$ 72.00               | 36      |
| 59                    | BOWDEN CABLE                        | 2   | \$ 58.00               | ?       |
| 60                    | RELEASE ELEMENT                     | 1   | \$ 58.00               | ?       |
| SUB TOTAL SPARE PARTS |                                     | :   | \$ 8,733.00            |         |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMP 9739 E

|                       |                                                |     | DAMAGED PARTS & PRICES |         |
|-----------------------|------------------------------------------------|-----|------------------------|---------|
| S/N                   | PARTS DESCRIPTION                              | QTY | S/NETT                 | REMARKS |
| 61                    | RELEASE LEVER <i>cut</i>                       | 1   | \$ 14.00               | ?       |
| 62                    | RELEASE CABLE COVER <i>can</i>                 | 1   | \$ 10.00               | ?       |
| 63                    | HEADLIGHT MOUNTING <i>LH/RH can</i>            | 2   | \$ 236.00              |         |
| 64                    | LED HEADLIGHT LH <i>RH can LH smashed, RH?</i> | 2   | \$ 17,248.00           | 8624    |
| 65                    | LED HEADLIGHT CAP LH                           | 1   | \$ 58.00               | ?       |
| 66                    | LED HEADLIGHT HOSE LH <i>cut</i>               | 1   | \$ 29.00               | X       |
| 67                    | LIFT CYLINDER LH / RH                          | 2   | \$ 396.00              | ?       |
| 68                    | LIFT CYLINDER BRACKET LH                       | 1   | \$ 6.00                | ?       |
| 69                    | LIFT CYLINDER HOSE <i>new</i>                  | 1   | \$ 182.00              | X       |
| 70                    | LOCK CARRIER <i>can</i>                        | 1   | \$ 1,234.00            | ?       |
| 71                    | LOCK CARRIER LOWER SUPPORT <i>LH RH</i>        | 2   | \$ 44.00               | ?       |
| 72                    | A/C CONDENSER <i>lot</i>                       | 1   | \$ 622.00              | ?       |
| 73                    | A/C CONDENSER O-RING <i>new</i>                | 1   | \$ 10.00               | ?       |
| 74                    | A/C CONDENSER SEAL RING <i>new</i>             | 1   | \$ 7.00                | ?       |
| 75                    | A/C CONDENSER SEAL RING                        | 1   | \$ 10.00               | ?       |
| 76                    | A/C PRESSURE SENSOR                            | 1   | \$ 186.00              | ?       |
| 77                    | A/C CONDENSOR SAFETY SWITCH VALVE              | 1   | \$ 51.00               | ?       |
| 78                    | A/C REFRIGERANT LINE                           | 1   | \$ 248.00              | ?       |
| 79                    | A/C REFRIGERANT LINE                           | 1   | \$ 264.00              | ?       |
| 80                    | A/C REFRIGERANT LINE BRACKET                   | 1   | \$ 23.00               | ?       |
| SUB TOTAL SPARE PARTS |                                                | :   | \$ 20,878.00           |         |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1163  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMP 9739 E**

| DAMAGED PARTS & PRICES      |                                              |     |              |         |
|-----------------------------|----------------------------------------------|-----|--------------|---------|
| S/N                         | PARTS DESCRIPTION                            | QTY | S/NETT       | REMARKS |
| 81                          | OUTSIDE TEMPERATURE SENSOR ?                 | 1   | \$ 58.00     | ?       |
| 81                          | CHARGE AIR COOLER <i>the m</i>               | 1   | \$ 587.00    | x       |
| 82                          | CHARGE AIR COOLER SEAL RING <i>the m</i>     | 1   | \$ 56.00     | x       |
| 83                          | CHARGE AIR COOLER PRESSURE PIPE <i>the m</i> | 1   | \$ 375.00    | x       |
| 84                          | RADIATOR <i>bt</i>                           | 1   | \$ 904.00    | ?       |
| 85                          | RADIATOR COOLANT <i>me</i>                   | 4   | \$ 179.00    | ?       |
| 86                          | RADIATOR AIR GUIDE LH / RH <i>cm</i>         | 2   | \$ 78.00     | ?       |
| 87                          | RADIATOR AIR GUIDE UPPER <i>cm</i>           | 1   | \$ 30.00     | ?       |
| 88                          | RADIATOR AIR GUIDE LOWER ?                   | 1   | \$ 33.00     | ?       |
| 89                          | WATER DEFLECTOR STRIP LH <i>et</i>           | 1   | \$ 59.00     | ✓       |
| 90                          | WINDOW SLOT SEAL LH - OUTER <i>the m</i>     | 2   | \$ 400.00    | +       |
| 91                          | WINDOW SLOT SEAL RH - OUTER                  | 1   | \$ 46.00     | x       |
| 92                          | INTAKE AIR GUIDE - FRONT ?                   | 1   | \$ 84.00     | ?       |
| 93                          | INTAKE AIR GUIDE - REAR ?                    | 1   | \$ 150.00    | ?       |
| 94                          | AIR FILTER ?                                 | 1   | \$ 302.00    | ?       |
| 95                          | FRONT NUMBER PLATE <i>Distorted</i>          | S/N | \$ 60.00     | ✓       |
| 96                          | SUNDRIES ?                                   |     | \$ 400.00    | ?       |
| <b>TOTAL SPARE PARTS</b>    |                                              | :   | \$ 50,436.00 |         |
| <b>TOTAL LABOUR CHARGES</b> |                                              | :   | \$ 18,264.00 |         |
| <b>GRAND TOTAL</b>          |                                              | :   | \$ 68,700.00 |         |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.

 PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : Adrian King  
SURVEYED DATE : 01/04/21  
AUTHORISED DATE :  
EXCESS COST :  
LIABILITY :  
REMARKS : Not Authorised, 08 Days (Without Lock Carrier)  
10 Days (With Lock Carrier)

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.  
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: