

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0272/2021/HR
DATE : 31-Mar-21
WIP : 21581

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 1/4/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian,

9 days - ok - Jy - 29 Apr 21

OWNER'S NAME : MR NG SIAK PING
ADDRESS : 15 ELIAS GREEN
#06-01
SINGAPORE 519966
TELEPHONE : HP +65 90112145
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1900141337
VEHICLE NO : **SJC 6638 L**
MODEL CODE : A5 SPORTSBACK 2.0 TFSI S TRONIC
MODEL YEAR : 29/07/2019
ENGINE NO : CVK 084176
CHASSIS NO : WAUZZZF55KA060144
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 26-Mar-21
PLACE OF ACCIDENT : KPE TOWARDS CHANGI AIRPORT

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJC 6638 L

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY & FRONT PARKING AID.	S/N \$	480.00	\$	480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	400.00	\$	250.00
3	TO REMOVE AND TRANSFER RHS FRONT DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$	400.00	\$	360.00
4	TO INSTALL SOLAR FILM FOR RHS FRONT DOOR WINDOW GLASS.	S/N \$	400.00		
5	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION.	\$	360.00		
6	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER, RHS FRONT DOOR, REAR BUMPER AND RHS HEADLIGHT. TO REMOVE AND REINSTALL RHS SILL PANEL TRIM. TO REPAIR RHS REAR DOOR, RHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	5,600.00	\$	1,500.00
SUB LABOUR CHARGES		:	\$ 7,640.00	\$	2,590.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJC 6638 L

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
	<i>c/f</i>		\$ 2,590.00
7	TO RESPRAY FRONT BUMPER, RHS FRONT FENDER, RHS UPPER A-PILLAR, RHS FRONT DOOR, RHS REAR DOOR, DOOR HANDLES, RHS REAR FENDER, RHS SILL PANEL TRIM AND REAR BUMPER.	\$ 7,600.00	\$ 4,050.00
8	SUPPLEMENTARY	\$ 1,000.00	\$ 750.00
9	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$ 192.00	\$ 192.00
	SUB TOTAL LABOUR CHARGES	: \$ 16,432.00	\$ 7,582.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO.SJC 6638 L

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 2,251.00	
2	FRONT BUMPER COVER FIXING PARTS	1	\$ 407.00	
3	FRONT BUMPER SECURING STRIP	1	\$ 36.00	
4	FRONT BUMPER LOWER CLOSING ELEMENT - CENTER	1	\$ 228.00	
5	FRONT BUMPER AIR GUIDE - RH	1	\$ 63.00	
6	FRONT BUMPER AIR GUIDE GRILLE - RH	1	\$ 474.00	
7	FRONT BUMPER GUIDE SECTION - RH	1	\$ 36.00	
8	FRONT FENDER - RH	1	\$ 1,060.00	
9	FRONT FENDER ATTACHMENT PARTS - RH	1	\$ 53.00	
10	FRONT FENDER CLOSING ELEMENT - RH	1	\$ 74.00	
11	FRONT FENDER LONG BRACKET - RH	1	\$ 35.00	
12	FRONT FENDER BRACE - RH	1	\$ 118.00	
13	FRONT FENDER DEFORMATION BRACKET - RH	1	\$ 49.00	
14	FRONT FENDER SHORT BRACKET - RH	1	\$ 35.00	
15	FRONT FENDER TRIM - RH	1	\$ 164.00	\$ 130.80
16	FRONT WHEEL HOUSING LINER - RH	1	\$ 275.00	
17	FRONT WHEEL HOUSING ATTACHMENT PART - RH	1	\$ 169.00	
18	FRONT WHEEL SPOILER - RH	1	\$ 73.00	
19	FRONT WHEEL SPOILER TRIM - RH	1	\$ 36.00	
20	FRONT FENDER STONE CHIP GUARD	1	\$ 51.00	
SUB TOTAL SPARE PARTS		:	\$ 5,687.00	\$ 130.80

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJC 6638 L

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		<i>c/f</i>		\$	130.80
21	FRONT FENDER LONG LEDGE COVER	1	\$ 36.00		
22	FRONT FENDER SHORT LEDGE COVER - RH	1	\$ 16.00		
23	HEADLIGHT - RH	1	\$ 7,902.00	\$	6,321.60
24	WATER DEFLECTOR STRIP	1	\$ 67.00	\$	53.44
25	FRONT DOOR - RH	1	\$ 3,884.00	\$	3,107.20
26	FRONT DOOR OUTER DOOR SEAL - RH	1	\$ 222.00	\$	177.60
27	BONDING AGENT	1	\$ 49.00		
28	CLEANING SOLUTION	1	\$ 68.00		
29	APPLICATOR	1	\$ 8.00		
30	FRONT DOOR CATCH - RH	1	\$ 120.00	\$	96.00
31	FRONT DOOR TRIM - RH	1	\$ 164.00	\$	130.80
32	FRONT MIRROR MOUNTING - RH	1	\$ 1,089.00	\$	871.20
33	FRONT MIRROR CAP - RH	1	\$ 289.00	\$	231.20
34	FRONT MIRROR GLASS - RH	1	\$ 1,667.00	\$	1,333.60
35	FRONT DOOR HANDLE TRIM PLATE - RH	1	\$ 88.00		
36	FRONT DOOR CHROME TRIM - RH	1	\$ 136.00	\$	108.80
37	FRONT DOOR TRANSPARENT TRIM - RH	1	\$ 6.00		
38	FRONT DOOR CORNER TRIM - RH	1	\$ 46.00	\$	36.24
39	FRONT DOOR WINDOW SEAL TRIM - RH	1	\$ 399.00	\$	318.80
40	ROOF CHROME DRIP MOULDING - RH	1	\$ 629.00	\$	503.20
SUB TOTAL SPARE PARTS		:	\$ 16,885.00	\$	13,420.48

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJC 6638 L

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		<i>c/f</i>		\$	13,420.48
41	FRONT DOOR WINDOW - RH	1	\$ 290.00		
42	FRONT DOOR ATTACHMENT PARTS - RH	1	\$ 130.00		
43	ADHESIVE TAPES	1	\$ 212.00	\$	169.60
44	REAR BUMPER	1	\$ 2,504.00		
45	REAR BUMPER FIXING PARTS	1	\$ 262.00		
46	REAR BUMPER SIDE GUIDE SECTION - RH	1	\$ 44.00		
47	REAR BUMPER UPPER GUIDE SECTION - LH / RH	2	\$ 46.00		
48	SUPPLEMENTARY		\$ 391.00	\$	202.96
49	SUNDRIES		\$ 300.00	\$	36.00
TOTAL SPARE PARTS			:	\$ 26,751.00	\$ 13,829.04
TOTAL LABOUR CHARGES			:	\$ 16,432.00	\$ 7,582.00
GRAND TOTAL			:	\$ 43,183.00	\$ 21,411.04

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.
 BL-29/04/21



Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 / Fax: 6256 4315

Estimate No.
Date
Service Advisor
Pages
Regn No
Model No

PA/OD/0272/2021/HR

12-Apr-21

CHANG

1 of 1

SJC 6638 L

AUDI A5 SPORTBACK 2.0 TFSI

Quantity	Description	Unit Price	Amount
Labours			
1	TO RESPRAY RHS WING MIRROR COVER AND BONNET.	\$ 1,000.00	\$ 750.00
Parts			
1	REAR DOOR HANDLE TRIM - RH	\$ 88.00	\$ 69.92
2	REAR DOOR HANDLE CHROME TRIM - RH	\$ 136.00	
3	SIDE MEMBER TRIM ATTACHMENT PARTS	\$ 130.00	\$ 104.00
4	DATA PLATE FOR TYRE PRESSURE	\$ 37.00	\$ 29.04
GRAND TOTAL		\$ 1,391.00	\$ 952.96

For Premium Automobiles Pte Ltd

 Authorised Signature

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF
THE AFFECTED VEHICLE. SHOULD WE REQUIRE
FURTHER LABOUR CHARGES AND SPARE PARTS IN THE
PROGRESS OF REPAIR, WE SHALL INFORM YOU
ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR
APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT