



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS3/SMO21001730/Uqf3e2-1	
			Date: 21/04/2021	
			Code: SMO	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	<b>Insured Veh.</b>	SKD 7905S	<b>Veh. Inspected</b>	SMS 5987R
	<b>Policy No.</b>	D21MTPV01000297	<b>Coverage (\$)</b>	0.00
	<b>Claim No.</b>	CMTD2100402/AGC	<b>Excess (\$)</b>	0.00
	<b>Assign From</b>	AGNES CHAN SHU HUI	<b>Assign Date</b>	01/04/2021
<b>2. Vehicle Particulars &amp; Condition</b>				
	<b>Make &amp; Model</b>	TOYOTA C-HR HYBRID (A)	<b>c.c</b>	1797
	<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2020
	<b>Chassis No.</b>	ZYX102174029	<b>Colour</b>	BROWN
	<b>Odometer</b>	69189 KM	<b>Steering</b>	AFFECTED
	<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
	<b>General</b>	FAIR		
<b>3. Conditions of Tyres</b>				
		<b>Size</b>	<b>Make</b>	<b>Balance</b>
	<b>R/H Front Tyre</b>	215/60 R17	DAVANTI	5 mm
	<b>L/H Front Tyre</b>	215/60 R17	DAVANTI	5 mm
	<b>R/H Rear Tyre</b>	215/60 R17	MICHELIN	5 mm
	<b>L/H Rear Tyre</b>	215/60 R17	MICHELIN	5 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.  DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	<b>Accident Date</b>	03/02/2021	<b>Inspection Date</b>	05/02/2021
	<b>Survey held at</b>	APEX MOTORING 25 KAKI BUKIT ROAD 4 #01-55 SYNERGY @ KB SINGAPORE 417800.		
<b>5a. Remarks</b>				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>6 Working Days</b>	