

RIVERVIEW AUTO SERVICES PTE LTD
 10 AMK INDUSTRIAL PARK 2A, AMK AUTOPOINT
 #04-07/16 SINGAPORE 568047
 Tel: 6481 2025/ 6481 5797 Fax No: 6481 8715
 Email: service@riverviewauto.com.sg
 Website: www.riverviewauto.com.sg
 Co. Reg. 200800062E GST Reg. No. 200800062E

Lump Sum Repair
 Less 20%

SDN 655

Toyota Estima

Special nett items

	nett Price \$
Tailgate reverse camera	1m \$480 X
Rear windscreen sealant	1m \$80 40sn
Rear bumper reverse parking sensors	1m \$250 200sn
Rear bumper clips (1set)	1m \$35 ✓
○ Rear end panel sealant	1m \$80 30sn

Labour charges

- 1) To Renew the damaged parts at the accident area. To cut & weld the rear end panel. 800/
\$1200
- 2) To Remove & Refit the rear windscreen to facilitate the repairs. 120/
\$200
- 3) To assemble the wiring for the tailgate reverse camera and the reverse parking sensors. To check for proper functions. 80/
\$80
- 4) To spray paint tailgate, Rear Bumper, rear end panel, spare tyre floor panel 800/
\$900
- 5) To carry out anti-rust treatment at the accident area. 120/
\$120