

RIVERVIEW AUTO SERVICES PTE LTD

10 AMK INDUSTRIAL PARK 2A, AMK AUTOPOINT

#04-07/16 SINGAPORE 568047

Tel: 6481 2025/ 6481 5797 Fax No: 6481 8715

Email: service@riverviewauto.com.sg

Website: www.riverviewauto.com.sg

Co. Reg. 200800062E GST Reg. No. 200800062E

Lump Sum Repair
Cen 20%

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: BT
Date:

SDN 65S

Parts

Tailgate

Tailgate Toyota Logo

Tailgate estima emblem

Tailgate aeras emblem

○ Tailgate inner lock

Tailgate wiper motor

Tailgate inner trim board

Tailgate shock absorber x 2pc

Tailgate windscreen rubber moulding

Tailgate electric key antenna

Rear Bumper

Rear Bumper towing cover

○ Rear Bumper reflector RHS

Rear Bumper side retainer (Long) RHS

Rear Bumper side retainer (Short) RHS

Boot weatherstrip

Rear end panel top garnish

Rear end panel

Rear fender inner trim board RHS

Not Whair

6/1/11

Repair After Paint
6 days

25%

19/1

Est Price \$

Toyota Cen 25%

1931.10 ✓

61.90 ✓

58.50 ✓

56.20 ✓

Ta 407.60 ✓

In 622.50 x

CM 491.20 ✓

In 282.10 x 2pc x

In 138.90 ✓

net 164.80 ✓

By 868.80 ✓

net 45.80 ✓

net 55 ✓

net 46.80 ✓

net 43.50 ✓

net 363.40 ✓

net 274.50 ✓

By 688.50 ✓

By 658.80 ✓

RIVERVIEW AUTO SERVICES PTE LTD

10 AMK INDUSTRIAL PARK 2A, AMK AUTOPOINT
#04-07/16 SINGAPORE 568047
Tel: 6481 2025/ 6481 5797 Fax No: 6481 8715
Email: service@riverviewauto.com.sg
Website: www.riverviewauto.com.sg
Co. Reg. 200800062E GST Reg. No. 200800062E

Lump Sum Repair
Less 20%

SDN 655

Toyota Estima

Special nett items

	nett Price \$
Tailgate reverse camera	RM \$480 x
Rear windscreen sealant	RM \$80 40sn
Rear bumper reverse parking sensors	RM \$250 200sn
Rear bumper clips (1set)	RM \$35 ✓
○ Rear end panel sealant	RM \$80 30sn

Labour charges

- 1) To Renew the damaged parts at the accident area. To cut & weld the rear end panel. ^{800h} \$1200
- 2) To Remove & Refit the rear windscreen to facilitate the repairs. ^{12d} \$200
- 3) To assemble the wiring for the tailgate reverse camera and the reverse parking sensors. To check for proper functions. ^{60h} \$80
- 4) To spray paint tailgate, Rear Bumper, rear end panel, spare tyre floor panel ^{800h} \$900
- 5) To carry out anti-rust treatment at the accident area. ^{60h} \$120