

Lion City Rentals Pte Ltd
CARROS CENTER
60 JALAN LAM HUAT #04-35/36 S(737869)

Ms AIG Asia Pacific Insurance Pte Ltd

Date: 31/03/2021

Attn : MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO: SLK8932H

CHASSIS NO : RU11205898

MAKE / MODEL : Honda Vezel 1.5X

DATE OF ACCIDENT : 30/03/2021

YOUR INSURED VEHICLE NUMBER : GBA4681D

MILEAGE : 282561 km

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

	<u>PARTS DESCRIPTION</u>	<u>QTY</u>	<u>UNIT PRICE</u>	<u>LIST PRICE</u>
1	F/R fender / np	1PC	\$ 600.00	\$ 600.00 510
2	F/R fender inner liner X SVC	1PC	\$ 240.00	\$ 240.00 X
3	Front bumper / CHY	1PC	\$ 955.00	\$ 955.00 750.
4	Front bumper retainer (RH) / BN	1PC	\$ 120.00	\$ 120.00 /
5	F/R fender wheel arch moulding / SCH	1PC	\$300.00	\$300.00 187.50
6	F/R headlamp (LED) ? / CRU.	1PC	\$2,100.00	\$2,100.00 1,820
LIST TOTAL S\$: \$ 2,215.00				3,387.50
20.00% DISCOUNT S\$: \$ 443.00				-20%
				\$ 1,772.00 2,710.00

SPECIAL NETT

1	Front bumper clips / Nec	1 SET	\$ 80.00 30
2	Fenders arc moulding clips / Nec	1 SET	\$ 80.00 20
Special Nett Total S\$: \$ 160.00			50

LABOUR CHARGES

1	To labour charge for rmoving F/R fender, front bumper out to facilitate repairs and replacement of damaged parts.	\$ 800.00 500
2	To respray F/R fenders, front bumper, wheel arch moulding(RH)	\$ 700.00 400
3	To apply rustproofing on all damaged parts	\$ 40.00 /
4	To check wiring system	\$ 100.00 30
LABOUR TOTAL S\$: \$ 1,640.00		970
TOTAL S\$: \$ 3,572.00		
7% GST \$ 250.04		
GRAND TOTAL S\$: \$ 3,822.04		

Repair day 3 days.

L/S.

before paint paint.

Sun Pin(LH/R)

01/04/2021

Tr without prepa

2,710
50
970
3,730
-20%
2,984

L/S
\$ 3,000
3 days