



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CS/LPC21004233/Ktf3q2	
			Date: 18/05/2021	
			Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBH 7115R		Veh. Inspected	SJH 1082X
Policy No.			Coverage (\$)	0.00
Claim No.	20/21/21/VC05/024397		Excess (\$)	0.00
Assign From	GERALD POH		Assign Date	01/04/2021
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ C 180 (A)		c.c	1595
Engine No.	HIDDEN		Year of Reg.	2013
Chassis No.	WDD2040312A922039		Colour	METALLIC BROWN
Odometer	105449 KM		Steering	STANDARD ALLOY RIM
Brakes	IN ORDER		Modification	
General	GOOD			
3. Conditions of Tyres				
		Size	Make	Balance
R/H Front Tyre		225/45 R17	PIRELLI	8 mm
L/H Front Tyre		225/45 R17	PIRELLI	8 mm
R/H Rear Tyre		225/45 R17	PIRELLI	8 mm
L/H Rear Tyre		225/45 R17	PIRELLI	8 mm
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	31/03/2021		Inspection Date	01/04/2021
Survey held at	160 SIN MING DRIVE SIN MING AUTOCITY #08-13			
Repairer	HENG YAP SENG AUTO SERVICE			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			8 Working Days	