

Not Notified
L1 Rm & 8000h
Purvey After Paint
Solays

HENG YAP SENG AUTO SERVICES

Blk 160, Sin Ming Drive, #08-13 Sin Ming AutoCity, Singapore 575722

Hp : 9183 3008

Fax : 6873 2017

Model : SJH1082X
Mercedes C180

Date : 04.04.2021

Estimate Repair Cost

Qty	Part Description	Part Number	Unit Price	Total Price	Notes
1	Rear bumper	1312-00	\$1,530.00	\$1,530.00	✓
2	Rear bumper brackets	0150A	\$140.00	\$280.00	✓
1 set	Rear bumper clips	m	\$50.00	\$50.00	✓
2	Rear bumper retainers	0150A	\$80.00	\$160.00	✓
1	Rear bumper reinforcement	615	\$670.00	\$670.00	✓
1	Rear bumper chrome moulding	188	\$310.00	\$310.00	✓
1	Rear bootlid	855	\$1,986.00	\$1,986.00	✓
1	Rear bootlid centre logo		\$50.00	\$50.00	✓
1	Rear bootlid "C180" emblem		\$85.00	\$85.00	✓
1	Rear bootlid "7G TRONIC" emblem	85	\$110.00	\$110.00	✓
1	Rear bootlid outer chrome moulding	194	\$210.00	\$210.00	✓
1	Rear bootlid lock		\$290.00	\$290.00	✓
2	Rear bootlid hinges	855	\$300.00	\$600.00	X
1	Rear bootlid weatherstrip	Dis 188	\$170.00	\$170.00	5085
1	Rear bootlid inner trim board	855	\$220.00	\$220.00	X
1 set	Rear bootlid inner trim clips	m	\$50.00	\$50.00	X
2	Tail lamps	0680	\$1,576.00	\$3,152.00	✓
1	Rear cross member		\$823.00	\$823.00	X
1	Rear fender		\$2,444.00	\$2,444.00	X
2	Rear fender inner side trims	855	\$340.00	\$680.00	X
1 set	Rear fender inner trim clips	m	\$50.00	\$50.00	X
1	Rear end panel	1206	\$330.00	\$330.00	✓
1	Rear end panel top gamish	215	\$1,533.00	\$1,533.00	✓
1	Rear spare tyre compartment		\$394.00	\$394.00	X
1	Rear spare tyre board		\$310.00	\$310.00	X
1	Rear exhaust silencer		\$1,770.00	\$1,770.00	X
1	Rear exhaust silencer mounting		\$90.00	\$90.00	X
3	Safety belt		\$1,296.00	\$3,888.00	✓
2	Headrest		\$1,084.00	\$2,168.00	2005
	Total			\$18,291.00	

Parts Special Nett Items

1	Rear number plate	\$ ^{fm} 60.00	X
1 set	Reverse sensor	<i>Red / Silver</i> \$ 300.00	<i>2 coins</i>
1	Reverse camera	\$ ^{fm} 400.00	X
1	Rear floor panel insulation	\$ ^{nm} 250.00	X
		<u>\$ 1,010.00</u>	
Total Parts		<u>\$ 19,301.00</u>	

Labour

Labour charge to remove, cut out damage portion, jack out, straighten, panel beating, welding, align and renew replaced parts.	\$ 1,600.00	900l
To putty and respray painting on affected areas.	\$ 1,500.00	1000l
To remove, replace rear bootlid fittings to facilitate repair.	\$ 300.00	60l
To remove, replace reverse sensor.	\$ 200.00	50l
To remove, replace reverse camera.	\$ 200.00	40l
To remove, replace exhaust silencer.	~ \$ 200.00	X
To check wiring and lightings.	\$ 80.00	20l

Total Labour \$ 4,080.00

Total Parts and Labour \$ 23,381.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: