

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0275/2021/HR
DATE : 1-Apr-21
WIP : 21444

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 7/4/21
YOUR INSURED VEH NO : YP 9965 B

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR. JIANG JING
ADDRESS : 193 EDGEFIELD PLAINS
#08-214
SINGAPORE 820193
TELEPHONE : HP +65 91910698
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 2070147041
VEHICLE NO : **SMV 8374 Z**
MODEL CODE : Q3 1.4 TFSI S TRONIC
MODEL YEAR : 23/10/2020
ENGINE NO : CZD C04451
CHASSIS NO : WAUZZZF36M1005526
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 29-Mar-21
PLACE OF ACCIDENT : AIRPORT ROAD BEFORE KPE ENTRANCE

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMV 8374 Z

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO DISMANTLE AND REINSTALL BOTH FRONT DOOR PANEL TRIM. TO REMOVE AND RENEW RHS WING MIRROR ASSY.	S/N \$	280.00	✓
2	TO RESPRAY RHS WING MIRROR COVER AND RHS FRONT DOOR	\$	1,500.00	180 ✓ 550 ✓ 730
3	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	✓
TOTAL LABOUR CHARGES		:	\$ 1,972.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMV 8374 Z

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT SIDE VIEW MIRROR MOUNTING - RH <i>ok</i>	1	\$ 2,065.00	<i>✓</i>	
2	FRONT SIDE VIEW MIRROR CAP - RH <i>missing</i>	1	\$ 191.00	<i>✓</i>	
3	FRONT SIDE VIEW MIRROR GLASS - RH <i>ok</i>	1	\$ 998.00	<i>✓</i>	
4	FRONT DOOR WINDOW CORNER TRIM - RH <i>not in</i>	1	\$ 46.00	<i>x</i>	
5	FRONT DOOR WINDOW OUTER SEAL TRIM - RH <i>ok</i>	1	\$ 224.00	<i>✓</i>	
6	SUNDRIES <i>?</i>		\$ 300.00	<i>?</i>	
TOTAL SPARE PARTS		:	\$ 3,824.00		
TOTAL LABOUR CHARGES		:	\$ 1,972.00		
GRAND TOTAL		:	\$ 5,796.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Lj*
SURVEYED DATE : *07/04/21*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 03 days.*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT