

55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS  
WORKSHOP : UBI ROAD 1  
CONTACT NO : 6366 2323  
FAX NO : 6841 1183  
REFERENCE : PA/TP/0275/2021/HR  
DATE : 1-Apr-21  
WIP : 21444

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 7/4/21  
YOUR INSURED VEH NO : YP 9965 B

AIG ASIA PACIFIC INSURANCE PTE LTD  
78 SHENTON WAY  
#07-16 AIG BUILDING  
SINGAPORE 079120  
Attn: Motor Claims Dept  
Tel: 6880 4602 - Fax: 6880 4838

*Cecil*  
\$3384

OWNER'S NAME : MR. JIANG JING  
ADDRESS : 193 EDGEFIELD PLAINS  
#08-214  
SINGAPORE 820193  
TELEPHONE : HP +65 91910698  
TYPE OF CLAIM : THIRD PARTY CLAIM  
POLICY NO : 2070147041  
VEHICLE NO : SMV 8374 Z  
MODEL CODE : Q3 1.4 TFSI S TRONIC  
MODEL YEAR : 23/10/2020  
ENGINE NO : CZD C04451  
CHASSIS NO : WAUZZZF36M1005526  
MILEAGE : -  
DATE IN : -  
ESTIMATED BY : JOHNNY BOO / ALLAN WU  
ACCIDENT DATE : 29-Mar-21  
PLACE OF ACCIDENT : AIRPORT ROAD BEFORE KPE ENTRANCE

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMV 8374 Z**

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO DISMANTLE AND REINSTALL BOTH FRONT DOOR PANEL TRIM. TO REMOVE AND RENEW RHS WING MIRROR ASSY. <span style="float: right;">S/N S</span>	280.00	✓
2	TO RESPRAY RHS WING MIRROR COVER AND RHS FRONT DOOR <span style="float: right;">S</span>	1,500.00	730 ✓
3	TO CARRY OUT DIAGNOSTIC CHECK. <span style="float: right;">S/N S</span>	192.00	✓
<b>TOTAL LABOUR CHARGES</b>		<b>: \$ 1,972.00</b>	



55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMV 8374 Z**

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT SIDE VIEW MIRROR MOUNTING - RH <i>lt</i>	1	\$ 2,065.00 ✓	1652.00
2	FRONT SIDE VIEW MIRROR CAP - RH <i>missing</i>	1	\$ 191.00 ✓	152.80
3	FRONT SIDE VIEW MIRROR GLASS - RH <i>lt</i>	1	\$ 998.00 ✓	798.00
4	FRONT DOOR WINDOW CORNER TRIM - RH <i>new</i>	1	\$ 46.00 x	
5	FRONT DOOR WINDOW OUTER SEAL TRIM - RH <i>lt</i>	1	\$ 224.00 ✓	179.20
6	SUNDRIES <i>Not New</i>		\$ 300.00 x	
TOTAL SPARE PARTS		:	\$ 3,824.00	
TOTAL LABOUR CHARGES		:	\$ 1,972.00	
GRAND TOTAL		:	\$ 5,796.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST  
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Lj*  
 SURVEYED DATE : *07/04/21*  
 AUTHORISED DATE :  
 EXCESS COST :  
 LIABILITY :  
 REMARKS : *the Authorised, 03 days.*  
*H.S.*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORA KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,  
 PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO  
 BODY REPAIR MANAGER

ALLAN WU  
 CLAIMS CONSULTANT

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: