


Section A - Accident Details

Registration Number	SHB853A
Case Reference Number	TAX/03/21/2075
Registration Date	10/10/2017
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	YEO TIONG GUAN
Type of Accident	Rear To Head
Accident Date and Time	23/3/2021 6:00 PM
Accident Reported Date and Time	24/3/2021 10:55 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24110193
Special Instruction to ARC, if any	TP/ DROVE IN / NTUC - LKK
Prepared Date and Time	25/3/2021 10:31 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates
Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$907.00	\$400.00
Total Spray Cost	\$1,872.00	\$600.00
Total Spare Part Cost	\$8,566.27	\$2,861.70
Total Other Cost	\$480.00	(\$761.70)
TOTAL COST	\$11,825.27	\$3,100.00 (L/S)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	5.0	3.0
Prepared / Adjusted By	Ang Bang Kien	Sun Pin (LKK) / NTUC
ARC / Surveyor Sign Off Date	26/03/2021 5:20 PM	26/03/2021 5:13 PM
Signature		
Remarks	Total number of repair days = 2 + 1 = 3 days. SUP = 1 day.	
	L/S, After paint photo.	

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2104-0098	Invoice Number	
Quotation Date	12.04.2021	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT HOOD	\$200.00	\$100.00 / Supp
TO REPAIR FRONT RH FENDER	\$200.00	\$100.00 / Supp
TO REPAIR FRONT PORTION	\$507.00	\$200.00 /
Total Labour	\$907.00	\$400.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00 /
TO RESPRAY FRONT BUMPER LOWER GRILLE	\$180.00	\$0.00
TO RESPRAY FRONT FENDER RH	\$378.00	\$0.00
TO RESPRAY RIM	\$180.00	\$0.00
TO REPSRAY FRONT HOOD	\$378.00	\$200.00 / Supp
TO RESPRAY FRONT FENDER RH	\$378.00	\$200.00 / Supp
Total Spray Painting & Panel Beating	\$1,872.00	\$600.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$0.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00 /
TO WASH AND VACUUM	\$60.00	\$0.00
Lump Sum Adjustment by Surveyor	\$0.00	(\$781.70)
Total Other Costs	\$480.00	(\$761.70)

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		52119479 62	COVER, FR BUMPER	1.00	\$495.50	100.00	\$0.00	Replace	Repair R
		52115470 50	SUPPORT, FR BUMPER RH	1.00	\$76.90	25.00	\$57.68	Replace	Replace BR
		52116470 50	SUPPORT, FR BUMPER LH	1.00	\$82.30	25.00	\$61.73	Replace	Replace BR
		52021471 10	REINFORCEMENT FRONT UPPER	0.00	\$691.10	0.00	\$0.00	Replace	Check X
		52611471 40	ABSORBER, FR BUMPER	0.00	\$70.30	0.00	\$0.00	Replace	Check X
		52103470 10	EXTENSION SUB-ASSY, LH	0.00	\$116.30	0.00	\$0.00	Replace	Check X
		52102470 20	EXTENSION SUB-ASSY, RH	0.00	\$116.30	0.00	\$0.00	Replace	Check X
		52132470 10	REINFORCEMENT FRONT LOWER	0.00	\$238.50	0.00	\$0.00	Replace	Check X
		52618470 90	ABSORBER, FR BUMPER LOWER	0.00	\$117.00	0.00	\$0.00	Replace	Not Given X
		53112472 40	GRILLE, RADIATOR	0.00	\$165.00	0.00	\$0.00	Replace	Check X

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 09/04/2021

User ID : PohSuan

		53101470 80	GRILLE SUB-ASSY	0.00	\$335.60	0.00	\$0.00	Replace	Check	X
		52161160 10	CLIPS PIECE, FRT & RR BUMPER	0.00	\$1.50	0.00	\$0.00	Replace	Not Given	X
		51420470 30	COVER ASSY, ENGINE	0.00	\$180.10	0.00	\$0.00	Replace	Not Given	X
		51410470 20	COVER ASSY, ENGINE UNDER CENTER SET	0.00	\$452.80	0.00	\$0.00	Replace	Not Given	X
		81210470 20	LAMP ASSY, FOG, RH	0.00	\$910.20	0.00	\$0.00	Replace	Not Given	X
		81145476 91	UNIT , HEADLAMP , RH	1.00	\$2,558.90	10.00	\$2,303.01	Replace	Replace	X
		53801470 80	FENDER SUB-ASSY, FR , RH	1.00	\$933.10	100.00	\$0.00	Replace	Old Damage	X
		75374471 40	EMBLEM, SIDE PANEL (HYBRID)	0.00	\$52.90	0.00	\$0.00	Replace	Not Given	X
		53875470 70	LINER, FR FENDER, RH	0.00	\$198.40	0.00	\$0.00	Replace	Not Given	X
		53851470 61	PAD, FR WHEEL RH	0.00	\$57.70	0.00	\$0.00	Replace	Not Given	X
		42611-47450	WHEEL, DISC FRONT	0.00	\$1,555.10	0.00	\$0.00	Replace	Not Given	X
		43550470 20	HUB & BEARING ASSY, RH & LH	0.00	\$554.20	0.00	\$0.00	Replace	Not Given	X
			TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given	X
		52114471 90	BRACKET, FR BUMPER	1.00	\$99.80	25.00	\$74.85	Replace	Replace	X
			NUMBER PLATE	1.00	\$35.00	0.00	\$35.00	Replace	Replace	X
			NUMBER PLATE FRAME	1.00	\$25.00	0.00	\$25.00	Replace	Replace	X
Total					\$10,246.24		\$2,557.27			

SVC
SVC
SVC
CRA
DD
CRA

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		52611471 40	ABSORBER, FR BUMPER	1.00	\$70.30	25.00	\$52.73	Replace	Replace
		53101470 80	GRILLE SUB-ASSY	1.00	\$335.60	25.00	\$251.70	Replace	Replace
Total					405.90		304.43		

CRU
CRU

2861.70
+ 400.00
+ 620.00

3881.70
- 206

3105.36

42 \$3,100
3 days

SHB 853A