



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFQ 110E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	DOOR PANEL FRT LH XC (SN)	BENT	2,695.90	2,426.31
1	XC60 18- DOOR PROTEC (SN)	DEFORMED	331.00	297.90
1	DOOR HANDLE BRACKET (SN)	NOT NECESSARY	152.30	-
1	DOOR HANDLE OUTER LH (SN)	SCRATCHED	388.40	349.56
1	ROCKER STRIP SEAL LH (SN)	NOT NECESSARY	256.00	-
1	XC60 18- SEAL STRIP (SN)	NECESSARY	128.10	115.29
1	XC60 18- GUIDE MOULD (SN)	NOT NECESSARY	256.00	-
1	V032205553/XC60 18- (SN)	NOT NECESSARY	114.80	-
1	BOTTOM RAIL (SN)	NOT NECESSARY	1,441.50	-
1	SOUND DEADENING PAD (SN)	NOT NECESSARY	578.00	-
4	RUST INHIBITING FLUI @\$37.70 (SN)	NECESSARY	150.80	135.72
1	ADHESIVE TUBE CHEMIC (SN)	NECESSARY	797.60	717.84
			7,290.40	4,042.62
	<b><u>LABOUR</u></b>			
	TO REPLACE LHF DOOR, DOOR MOULDING, DOOR HANDLE, 'B' PILLAR, ROCKER PANEL, ETC.		3,400.00	2,550.00
	TO PUTTY AND SPRAY PAINT ON LHF DOOR, DOOR MOULDING, DOOR HANDLE, 'B' PILLAR, ROCKER PANEL, ETC.		3,750.00	2,250.00
	TO TRANSFER DOOR PARTS.		250.00	250.00
	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULE.		588.00	588.00
			7,988.00	5,638.00
	<b>GRAND TOTAL</b>		<b>15,278.40</b>	<b>9,680.62</b>

<b>RECOMMENDED COST OF REPAIRS</b>			<b>9,680.62</b>
<b>LESS EXCESS</b>			<b>-750.00</b>
<b>NETT LIABILITY</b>			<b>8,930.62</b>

Report Ref No. CS/UOI21004257/R1vf3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.