LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road

#16-00 Springleaf Tower Singapore 079909 From: LKK Auto Consultants Pte Ltd

Est. Duration of Repair

: 10

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Adeline Chng Pei Wen Date: 23 Apr 2021

Preliminary Advice

Insured Vehicle No : YP8132U

TP Vehicle No : PC9332C Accident Date : 03/04/2021

Make : GOLDEN DRAGON XML6113J98 Assignment Date : 05/04/2021

Date of Inspection : 05/04/2021

Inspection At : CONNECT3 (HQ)

566 WOODLANDS ROAD SINGAPORE 728697

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	32,536.00
Revised Amount	:S\$	15,295.40
Check Items (Estimated)	:S\$	0.00
Total	:S\$	15,295.40
Lump Sum Repair	:S\$	12,250.00

Total Loss Consideration

New for Old Value :\$\$
Pre-Accident Value :\$\$
COE / PARF Rebate :\$\$
Salvage Value :\$\$
Margin for Repair :\$\$

Remarks

()	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.
		Kindly let us have your authorisation.

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments: SURVEY WP