

VIEW AUTO SERVICES PTE LTD

ANG MO KIO INDUSTRIAL PARK 2A

-07/04-16 AMK AUTOPOINT

SAPORE 568047

: 6481 2025 / 6481 5797 Fax: 6481 8715

il : service@riverviewauto.com.sg

bsite : www.riverviewauto.com.sg

leg No: 200800062E GST.Reg No: 200800062E

Lump Sum Repair

(ex 20%

Not Adhesive

11 Sep 8 20, 600

Recovery After Pain

3ME2941R

nissan teana

List Price \$

Parts

Nissan

Bootlid	As	1119.80	✓
Bootlid nissan Logo	m	66.50	✓
Bootlid 250 XV emblem	1c	62.70	✓
Bootlid Teana emblem	m	60.40	✓
Bootlid V6 Badge	1c	60.20	✓
Bootlid no plate chrome garnish	Bu	351.10	✓
Bootlid Lower chrome garnish	cm	173.70	✓
Bootlid inner Lock	Tr	123.20	✓
Bootlid inner trim	Refm	164.60	✓
Bootlid hinges x 2pc	As @ 120 x 2pc =	240	✓
Bootlid shock absorber x 2pc	Pr @ 144.50 x 2pc =	289	✓
tail lamp x 2pc	Bul/m @ 641.70 x 2pc =	1283.40	✓
tail lamp lower bracket x 2pc	cm @ 28.20 x 2pc =	56.40	✓
Rear Bumper	889.40	R 933.30	✓
Rear Bumper chrome x 2pc	C/45	m 290	✓
Rear Bumper side retainer x 2pc	@ 3630	115/cm 72.60	✓
Rear Bumper sponge		cm 123.20	✓
Rear Bumper reinforcement Beam	330.90	R 369.60	✓
Rear Reinforcement Beam bracket x 2pc			
exhaust muffler LH	As	634.80	✓
exhaust muffler RH	As	634.80	✓
Rear fender LH	Buc	1288.30	✓
Rear fender RH	B+Bu	1288.30	✓
Rear fender inner shield x 2pc	o/s/m @ 98.50 x 2pc =	197	✓

108

RIVERVIEW AUTO SERVICES PTE LTD

10 ANG MO KIO INDUSTRIAL PARK 2A

#04-07/#04-16 AMK AUTOPOINT

SINGAPORE 568047

Tel : 6481 2025 / 6481 5797 Fax : 6481 8715

Email : service@riverviewauto.com.sg

Website : www.riverviewauto.com.sg

Co.Reg No: 200800062E GST.Reg No: 200800062E

Lump Sum Repair
Cen 20%

SME2941R

Parts

nisson team

List Price \$

Nissan

Rear end panel top garnish

CM 191.90 ✓

end panel lock catch

pi 45 ✓

Boot weatherstrip

82.551N val/cm 165.10 508JN

Rear end panel

B1 650.20 ✓

Spare tyre panel

B1/B2 998.10 ✓

Spare tyre panel top board

CM 144.40 ✓

Spare tyre panel sponge toolbox

CM 454.60 ✓

Spare tyre panel side sponge X 2pc

return @ 80.50 X 2pc = 161 ✓

Rear fender inner trim X 2pc

return 1cm @ 233 X 2pc = 466 ✓

Bottled antihena key

SN 121.20 X

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts/confirm resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary Survey Report is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Pg 2

RIVERVIEW AUTO SERVICES PTE LTD

10 ANG MO KIO INDUSTRIAL PARK 2A
#04-07/#04-16 AMK AUTOPOINT
SINGAPORE 568047

Tel: 6481 2025 / 6481 5797 Fax: 6481 8715

Email: service@riverviewauto.com.sg

Website: www.riverviewauto.com.sg

Co.Reg No: 200800062E GST.Reg No: 200800062E

Lump Sum Repair
Cus 20%

SME 2941R	Nissan teana	Est Price \$
Parts	Nissan	
Bonnet	Rn	1203.60 ✓
Bonnet Radiator chrome grille	cm	592.70 -
Radiator chrome grille Nissan Logo	rn	66.50 -
Bonnet inner lock	or	123.80 ✓
Bonnet lock catch	Rn	45 ✓
Bonnet hinges x 2pc	n @ 122 x 2pc = 244 x	
Bonnet shock absorber x 2pc	n @ 149.80 x 2pc = 299.60 x	
Bonnet insulator board	rn	175.80 x
Headlamp LH	cm	1352.50 ✓
Headlamp RH	cm	1352.50 ✓
Headlamp lower bracket x 2pc	or @ 32.10 x 2pc = 64.20 -	
front Bumper	Rn	800.10 -
front Bumper wiper cover RH	mix	144 ✓
front Bumper lower centre grille	or together with Bumper	✓
front Fog lamp cover RH	nd	80.40 ✓
front Fog lamp chrome RH	rn	145.60 x
front Bumper no plate garnish	or	126.90 ✓
front fender RH	Bu	777.30 -
front Bumper side retainer RH	or	38.30 -
front Bumper sponge	cm	122.20 ✓
front Bumper reinforcement Beam	Rn	362.90 ✓
front Reinforcement Beam bracket x 2pc	dis	4
front Bumper Beam bracket	R	126.50 x
front wiper motor RH	rn	128.90 x

Repairer Estimates

Atk. No. 11/11/11

RIVERVIEW AUTO SERVICES PTE LTD

10 ANG MO KIO INDUSTRIAL PARK 2A
#04-07/#04-16 AMK AUTOPOINT
SINGAPORE 568047

Tel: 6481 2025 / 6481 5797 Fax: 6481 8715

Email: service@riverviewauto.com.sg

Website: www.riverviewauto.com.sg

Co.Reg No: 200800062E GST.Reg No: 200800062E

Lump Sum Repair
Len 20%

SME 2941R Parts Nissan Teana Lot Price \$ Nissan

front horn x 2pc	Od/CM @ 80 x 2pc = 160 ✓
front air con condenser	A1 548.30 ✓
front radiator support panel	Bu 785.40 ✓
front radiator	A1 869.20 ✓
front radiator housing	CM 866.80 ✓
front radiator fan motor x 2pc	Im } 1 set ✓
front radiator fan blade x 2pc	Di } @ 871.70 ✓
front radiator casing	C } x

special rct item nett price \$

Rear license plate with holder	Od 50 45m
Bottled reverse camera	Im 480 x
Bottled inner trim clips	Im 40 ✓
Reverse parking sensors	Od 250 200m
Rear end panel sealant	Im 80 30m
spare tyre panel sealant	Im 60 30m
Rear fender LH sealant	Im 80 30m
Rear fender RH sealant	Im 80 30m
Rear windscreen sealant	Im 80 40m
front license plate with holder	Od 50 45m
front bumper clips (1 set)	Im 40 ✓
front insulator board clips (1 set)	Im 40 ✓
Carant (1 bottle)	Im 40 30m

294

Format:

Sum / I.B.I: (3

RIVERVIEW AUTO SERVICES PTE LTD

10 AMK INDUSTRIAL PARK 2A, AMK AUTOPOINT
#04-07/16 SINGAPORE 568047

Tel: 6481 2025/ 6481 5797 Fax No: 6481 8716

Email: service@riverviewauto.com.sg
Website: www.riverviewauto.com.sg

Co. Reg. 200800062E GST Reg. No. 200800062E

Lump Sum Repair

cen 20%

SME 2941R

Nissan teana

Labour charges (Rear)

- 1) To Renew damaged parts & repair the rear portion.
To cut & weld Rear fender, Rear end panel
and spare tyre panel. \$1500 ✓
- 2) To Remove & Refit the rear windscreen to
facilitate the repairs & welding of the Rear fender. 120d
\$200
- 3) To assemble wiring of the Rear Reverse Camera
and the reverse parking sensors. To check for
proper functions. 60d
\$80
- 4) To spray paint Bootlid, Rear Bumper,
Rear end panel, spare tyre panel, rear fender LH
and rear fender RH. (6 panels) 140d
\$1500
- 5) To carry out anti-rust treatment &
check water leakage at the rear portion. \$150 ✓
- 6) To Remove, renew & refit the rear
exhaust mufflers 100d
\$200

pg 5

RIVERVIEW AUTO SERVICES PTE LTD
10 AMK INDUSTRIAL PARK 2A, AMK AUTOPOINT
#04-07/16 SINGAPORE 568047
Tel: 6481 2025/ 6481 5797 Fax No: 6481 5715
Email: service@riverviewauto.com.sg
Website: www.riverviewauto.com.sg
Co. Reg. 200800062E GST Reg. No. 200800062E

Lump Sum Repair
@ 20%

SME2941R

Nissan Teana

Labour charges (incl)

- 1) To Renew damaged parts & repair the front portion. 700l
To Renew the Bonnet, front Bumper, front fender RH \$1200
and the front support panel.
- 2) To Renew air con condensor & top up 100l
air con gas. \$150
- 3) To Renew Radiator & top up 50l
Coolant. \$150
- 4) To spray paint Bonnet, front Bumper, 800l
front fender RH \$1000
- 5) To carry out anti rust treatment at 90l
the front portion of vehicle \$100
- 6) To check with nissan computer scanner
& clear all fault code. 111 \$250 X

pg 6