

[Service Requests](#)[Messages](#)[Claims](#)

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving	TPVD Nissan Teana (SME2941R)
Date of Loss	3 April 2021
Time of Loss	11:40
Loss Description	CHAIN COLLISION: SGS6419D (INSD) > SME2941R (TP) > SLL1193D
Comment	

Workshop Details

Total Rebate Amount	0
Nett Loss Amount	\$0.00
Assigned Workshop	LKK AUTO CONSULTANTS PTE LTD (TP)
Days of work completion *	20



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details



Vehicle Registration#	SME2941R	Purchase Date	<div>DD/MM/YYYY</div> <div></div>
Registration State	<div>SINGAPORE</div>	Registration Date *	<div>01/04/2010</div> <div></div>
Mileage	<div>188812</div>	Age of Vehicle	11

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Manufacturing Year		<div>2009</div>





Driver Details

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Driver Name	CHIN CHIEN SIONG	<div></div>

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Make	TPVD Nissan	<input type="text" value="NISSAN"/>
Model	Teana	<input type="text" value="TEANA 2.5 CVT ABS D/"/>
Type		<input type="text" value=""/>
Type of Paint		<input type="text" value=""/>
Chassis No		<input type="text" value="JN1BBUJ32Z0002408"/>
Engine No		<input type="text" value="VQ25495673A"/>
Engine Capacity		<input type="text" value="2496"/>
Sum Insured		<input type="text" value="0"/>

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Date of Birth	19 July 1976	<input type="text" value="DD/MM/YYYY"/> 
Age	44	
Occupation	Director	<input type="text" value=""/>
Education Qualification	Other	<input type="text" value=""/>
Driving Experience	0	
Driver License #		<input type="text" value=""/>
License Type		<input type="text" value=""/>
License Issue Date		<input type="text" value="DD/MM/YYYY"/> 

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Market Value		<input type="text" value="0"/>

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
License Expiration Date		<input type="text" value="DD/MM/YYYY"/> 
Address	TBC, Singapore	<input type="text"/>
Address type	Personal Correspondence	<input type="text" value=""/> 
Gender	Male	<input type="text" value=""/> 
Marital status	Unknown	<input type="text" value=""/> 
Identification #	S7668734Z	<input type="text"/>



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

05/04/2021



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/
Unnamed Driver Excess

0

Condition of Vehicle at time of survey

General condition

Good



Steering (Serviceable)

Yes

No

Footbrake
(Serviceable)

Yes

No

Handbrake
(Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good



Other Excess

0

Tyre Condition

Age of Tyres

Front Tyre Size

Front left side

Front right side

Spare wheel

Rear Tyre Size

Rear left side

Rear right side

245/40R18

GOODYEAR7mm

GOODYEAR7mm

245/40R18

GOODYEAR6mm

GOODYEAR6mm



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

0

Salvage%

0

Discount%

10

Settlement%

100

Paint Labour/Material Ratio

Paint Labour Ratio

20

Cash Loss

Yes

No

Paint Material Ratio

80

Part Supplied by AXA

Yes

No

Save



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition








Taxes & Ratio













Parts & Labour












Miscellaneous












Summary












Parts












Add		Approve		Deny		Submit All								
EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	
	0	1		BOOTLID	Bent	0	1119.8	No	0	10	0	0	1007.82	
	0	1		BOOTLID NISSAN LOGO	Necessary	0	66.5	No	0	10	0	0	59.85	
	0	1		BOOTLID 250XV EMBLEM	Necessary	0	62.7	No	0	10	0	0	56.43	
	0	1		BOOTLID TEANA EMBLEM	Necessary	0	60.4	No	0	10	0	0	54.36	
	0	1		BOOTLID V6 BADGE	Necessary	0	60.2	No	0	10	0	0	54.18	
	0	1		BOOTLID NO PLATE CHROME GARNISH	Buckled	0	351.1	No	0	10	0	0	315.99	
	0	1		BOOTLID LOWER CHROME GARNISH	Cracked	0	173.7	No	0	10	0	0	156.33	


EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT
	0	1		BOOTLID INNER LOCK	Damaged	0	123.2	No	0	10	0	0	110.88
	0	1		BOOTLID INNER TRIM	Deformed	0	164.6	No	0	10	0	0	148.14
	0	2		BOOTLID HINGES	Bent	0	120	No	0	10	0	0	216
	0	2		BOOTLID SHOCK ABSORBERS		0	144.5	No	0	10	0	0	260.1
	0	2		TAILLAMP	Broken	0	641.7	No	0	10	0	0	1155.06
	0	2		TAILLAMP LOWER BRACKET	Cracked	0	28.2	No	0	10	0	0	50.76
	0	1		REAR BUMPER	Bent	0	869.4	No	0	10	0	0	782.46
	0	2		REAR BUMPER CHROME	Necessary	0	145	No	0	10	0	0	261
	0	2		REAR BUMPER SIDE RETAINER	Cracked	0	36.3	No	0	10	0	0	65.34
	0	1		REAR BUMPER SPONGE	Cracked	0	123.2	No	0	10	0	0	110.88
	0	1		REAR BUMPER REINFORCEMENT BEAM	Bent	0	330.9	No	0	10	0	0	297.81
	0	1		EXHAUST MUFFLER LH	Bent	0	634.8	No	0	10	0	0	571.32

EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT
	0	1		EXHAUST MUFFLER RH	Bent	0	634.8	No	0	10	0	0	571.32
	0	1		REAR FENDER LH	Buckled	0	1288.3	No	0	10	0	0	1159.47
	0	1		REAR FENDER RH	Buckled	0	1288.3	No	0	10	0	0	1159.47
	0	1		REAR FENDER INNER SHIELD N/S	Serviceable	0	0	No	0	0	0	0	0
	0	1		REAR FENDER INNER SHIELD O/S	Cracked	0	98.5	No	0	10	0	0	88.65
	0	1		REAR END PANEL TOP GARNISH	Cracked	0	191.9	No	0	10	0	0	172.71
	0	1		END PANEL LOCK CATCH	Damaged	0	45	No	0	10	0	0	40.5
	0	1		REAR END PANEL	Bent	0	650.2	No	0	10	0	0	585.18
	0	1		SPARE TYRE PANEL	Buckled	0	998.1	No	0	10	0	0	898.29
	0	1		SPARE TYRE PANEL TOP BOARD	Cracked	0	144.4	No	0	10	0	0	129.96
	0	1		SPARE TYRE PANEL SPONGE TOOLBOX	Cracked	0	454.6	No	0	10	0	0	409.14

EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT
	0	2		SPARE TYRE PANEL SIDE SPONGE	Deformed	0	80.5	No	0	10	0	0	144.9
	0	2		REAR FENDER INNER TRIM	Deformed	0	233	No	0	10	0	0	419.4
	0	1		BOOTLID ANTENNA KEY	Serviceable	0	0	No	0	0	0	0	0
	0	1		BONNET	Bent	0	1203.6	No	0	10	0	0	1083.24
	0	1		BONNET RADIATOR CHROME GRILLE	Cracked	0	592.7	No	0	10	0	0	533.43
	0	1		RADIATOR CHROME GRILLE NISSAN LOGO	Necessary	0	66.5	No	0	10	0	0	59.85
	0	1		BONNET INNER LOCK	Damaged	0	123.8	No	0	10	0	0	111.42
	0	1		BONNET LOCK CATCH	Bent	0	45	No	0	10	0	0	40.5
	0	2		BONNET HINGES	Repair	0	0	No	0	0	0	0	0
	0	2		BONNET SHOCK ABSORBER	Serviceable	0	0	No	0	0	0	0	0
	0	1		BONNET INSULATOR BOARD	Serviceable	0	0	No	0	0	0	0	0

EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT
	0	1		HEADLAMP LH	Cracked	0	1352.5	No	0	10	0	0	1217.25
	0	1		HEADLAMP RH	Cracked	0	1352.5	No	0	10	0	0	1217.25
	0	2		HEADLAMP LOWER BRACKET	Damaged	0	32.1	No	0	10	0	0	57.78
	0	1		FRONT BUMPER }	Bent	0	800.1	No	0	10	0	0	720.09
	0	1		FRONT BUMPER WIPER COVER RH	Missing	0	44	No	0	10	0	0	39.6
	0	1		FRONT BUMPER LOWER CENTRE GRILLE }	Damaged	0	0	No	0	10	0	0	0
	0	1		FRONT FOG LAMP COVER RH	Dented	0	80.4	No	0	10	0	0	72.36
	0	1		FRONT FOG LAMP CHROME RH	Serviceable	0	0	No	0	0	0	0	0
	0	1		FRONT BUMPER NO PLATE GARNISH	Dented	0	126.9	No	0	10	0	0	114.21
	0	1		FRONT FENDER RH	Buckled	0	777.3	No	0	10	0	0	699.57
	0	1		FRONT BUMPER SIDE RETAINER RH	Damaged	0	38.3	No	0	10	0	0	34.47

EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT
	0	1		FRONT BUMPER SPONGE	Cracked	0	122.2	No	0	10	0	0	109.98
	0	1		FRONT BUMPER REINFORCEMENT BEAM	Bent	0	362.9	No	0	10	0	0	326.61
	0	1		FRONT BUMPER BEAM BRACKET	Repair	0	0	No	0	0	0	0	0
	0	1		FRONT WIPER MOTOR RH	Serviceable	0	0	No	0	0	0	0	0
	0	2		FRONT HORN	Dented	0	80	No	0	10	0	0	144
	0	1		FRONT AIR CON CONDENSER	Bent	0	548.3	No	0	10	0	0	493.47
	0	1		FRONT RADIATOR SUPPORT PANEL	Buckled	0	785.4	No	0	10	0	0	706.86
	0	1		FRONT RADIATOR	Bent	0	869.2	No	0	10	0	0	782.28
	0	1		FRONT RADIATOR HOUSING	Cracked	0	866.8	No	0	10	0	0	780.12
	0	2		FRONT RADIATOR FAN MOTOR }	Damaged	0	435.85	No	0	10	0	0	784.53
	0	2		FRONT RADIATOR FAN BLADE }	Damaged	0	0	No	0	10	0	0	0

EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT
	0	1		FRONT RADIATOR COATING }	Damaged	0	0	No	0	10	0	0	0













Labour











Add

Approve

Deny

Submit All

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	REMOVE
	0		TO RENEW DAMAGED PARTS & REPAIR THE REAR PORTION. TO CUT & WELD REAR FENDER , REAR END PANEL AND SPARE TYRE PANEL	0	1500	0	0	Reviewing		
	0		TO REMOVE & REFIT THE REAR WINDSCREEN TO FACILITATE THE REPAIRS & WELDING OF THE REAR FENDER	0	120	0	0	Reviewing		
	0		TO ASSEMBLE WIRING OF THE REAR REVERSE CAMERA AND THE REVERSE PARKING SENSORS. TO CHECK FOR PROPER FUNCTIONS	0	60	0	0	Reviewing		
	0		TO SPRAY PAINT BOOTLID, REAR BUMPER, REAR END PANEL, SPARE TYRE PANEL, REAR FENDER LH AND REAR FENDER RH (6 PANELS)	0	1400	0	0	Reviewing		
	0		TO CARRY OUT ANTI-RUST TREATMENT & CHECK WATER LEAKAGE AT THE REAR PORTION	0	150	0	0	Reviewing		
	0		TO REMOVE, RENEW & REFIT THE REAR EXHAUST MUFFLERS	0	100	0	0	Reviewing		

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	REMOVE
	0		TO RENEW DAMAGED PARTS & REPAIR THE FRONT PORTION. TO RENEW THE BONNET, FRONT BUMPER, FRONT FENDER RH AND THE FRONT SUPPORT PANEL	0	700	0	0	Reviewing		
	0		TO RENEW AIR CON CONDENSER & TOP UP AIR CON GAS	0	100	0	0	Reviewing		
	0		TO RENEW RADIATOR & TOP UP COOLANT	0	50	0	0	Reviewing		
	0		TO SPRAY PAINT BONNET, FRONT BUMPER, FRONT FENDER RH	0	800	0	0	Reviewing		
	0		TO CARRY OUT ANTI RUST TREATMENT AT THE FRONT PORTION OF VEHICLE	0	90	0	0	Reviewing		
	0		TO CHECK WITH NISSAN COMPUTER SCANNER & CLEAR ALL FAULT CODE	0	0	0	0	Deny		



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add		Approve		Deny		Submit All	
EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	DAYS OF REPAIR : 24 DAYS	Reviewing	0	0		
	0	REAR LICENSE PLATE WITH HOLDER	Reviewing	0	45	DENTED	
	0	BOOTLID REVERSE CAMERA	Deny	0	0	SERVICEABLE	

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	BOOTLID INNER TRIM CLIPS	Reviewing	0	40	NECESSARY	
	0	REVERSE PARKING SENSORS	Reviewing	0	200	DENTED	
	0	REAR END PANEL SEALANT	Reviewing	0	30	NECESSARY	
	0	SPARE TYRE PANEL SEALANT	Reviewing	0	30	NECESSARY	
	0	REAR FENDER LH SEALANT	Reviewing	0	30	NECESSARY	
	0	REAR FENDER RH SEALANT	Reviewing	0	30	NECESSARY	

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	REAR WINDSCREEN SEALANT	Reviewing	0	40	NECESSARY	
	0	FRONT LICENSE PLATE WITH HOLDER	Reviewing	0	45	DENTED	
	0	1 SET FRONT BUMPER CLIPS	Reviewing	0	40	NECESSARY	
	0	1 SET FRONT INSULATOR BOARD CLIPS	Reviewing	0	40	NECESSARY	
	0	1 BOTTLE COOLANT	Reviewing	0	30	NECESSARY	
	0	BOOT WEATHERSTRIP (\$165.10) (50%)	Reviewing	0	82.55	DENTED / CUT	



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Estimated Claim Amount	\$0.00	Adjusted Claim Amount	\$27,395.12
------------------------	--------	-----------------------	-------------

CATEGORY	ESTIMATE	ADJUSTED
Spare Parts	\$0.00	\$21,642.57
Labour	\$0.00	\$5,070.00
Miscellaneous	\$0.00	\$682.55

Submit for Review



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add		Approve		Deny		Submit All	
EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	FINAL LUMP SUM	Reviewing	0	21900		



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Estimated Claim Amount	\$0.00	Adjusted Claim Amount	\$21,900.00
------------------------	--------	-----------------------	-------------

CATEGORY	ESTIMATE	ADJUSTED
Miscellaneous	\$0.00	\$21,900.00

Submit for Review