



Exceptional Journeys

Surveyor : STEVE LKK
Claim : AIG OD
DOA : 02.04.2021
Emailed : 29.04.2021, 9.55am
Date Survey : 05.04.2021

VEHICLE NO : SMD 9367 H
MODEL : KIA CERATO 1.6 A SX
WIP : 31468

Table with 2 columns: Description and Amount. Rows include Material (\$4,414.40), Labour (\$4,040.00), Sub-Total (\$8,454.40), Less Excess (\$-), Total (\$8,454.40), GST 7% (\$591.81), Grand Total (\$9,046.21), and Finalise By/Date (LOI / 29/04/2021).

[X] REVERT BACK WITHIN 7 DAYS, OTHERWISE WILL PROCEED WITH INVOICING

[] SURVEYOR'S REPORT REQUIRED

[] REPAIR TOOK 0 WORKING DAYS + 0 Days (0) Weekends + 0 Days (0) Public Holiday
TOTAL DAYS REPAIR TOOK = 0

[] TP claim

[] Claim GIA / LTA fee

[] Claim Loss of [] Use / [] Rental

[] Claim Medical Fee / Others

[] Third Party Report -



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**PRO-FORMA INVOICE**

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 05/04/2021	Cust No/Name	/CHEE SHU HUI (ZHU SHUHUI)
	Reg No/Reg Date	SMD9367H*ECB / 12/09/2018
	Date In/Mileage	03/04/2021/ 40706
	Chassis/Package	KNAF3416MK501361E /#
	Engine No	G4FGJH703967
	Make/Model	KIA/CERATO 1.6 A SX G335
	Colour/Trim	SWP SNOW WHITE PEAR/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	28/04/2021/ 17:28	BLK	260 / AiTing	31468

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE DAMAGED PARTS, REPLACE REAR BUMPER, RH REAR FENDER, BOOT, REPAIR ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME				✓ 1400.00
E PNT98000 RESPRAY ON REAR BUMPER, BOOT, RH REAR FENDER, REAR END PANEL, AND ALL OTHER AFFECTED AREAS TO THE SAME				✓ 1400.00
E PNT88000 REMOVE & INSTALL REAR PARKING ASSIST TO FACILITATE REPAIR				✓ 80.00
E PNT88000 TRANSFER REAR BOOT ATTACHMENTS TO NEW PANEL				✓ 120.00
M SUNDRY PERFORM RUST PREVENTION ON AFFECTED AREAS				✓ 40.00
M SUNDRY APPLY BODY SEALANT ON AFFECTED AREAS				✓ 40.00
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				✓ 30.00
✓ A 10028901 CONDUCT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST AND CLEAR TROUBLE CODE				✓ 120.00
M SUNDRY SUPPLY C & C EMBLEM				✓ 40.00
M SUNDRY SUNDRIES				✓ 20.00
E PNT88000 REPLACE REAR END PANEL → Supp.				400.00
✓ E PNT98000 RESPRAY ON LH REAR FENDER → Supp.				350.00
X COVER-RR BUMPER	1.00	✓ 651.00	20.00	520.80
X COVER-RR BUMPER LWR	1.00	✓ 241.00	20.00	192.80
X COVER-RR BUMPER FOG LAMP,RH	1.00	✓ 19.00	20.00	15.20
X LAMP ASSY-SIDE T/SIGNAL,RH	1.00	✓ 181.00	20.00	144.80
✓ X BEAM-RR BUMPER	1.00	? 318.00	20.00	254.40
X EMBLEM-CERATO	1.00	✓ 28.00	20.00	22.40

This is not an official tax invoice.
 This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



PRO-FORMA INVOICE

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 05/04/2021	Cust No/Name	/CHEE SHU HUI (ZHU SHUHUI)
	Reg No/Reg Date	SMD9367H*ECB / 12/09/2018
	Date In/Mileage	03/04/2021/ 40706
	Chassis/Package	KNAF3416MK501361E /#
	Engine No	G4FGJH703967
	Make/Model	KIA/CERATO 1.6 A SX G335
	Colour/Trim	SWP SNOW WHITE PEAR/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	28/04/2021/ 17:28	BLK	260 / AiTing	31468

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X LOGO ASSY-KIA SUB	1.00	✓ 32.00	20.00	25.60
X W/STRIP-TRUNK LID OPNG	1.00	✓ 100.00	20.00	80.00
X LATCH ASSY-TRUNK LID	1.00	✓ 112.00	20.00	89.60
X PANEL ASSY-RR COMB LAMP HSG,RH	1.00	✓ 135.00	20.00	108.00
X PANEL ASSY-TRUNK LID	1.00	✓ 1297.00	20.00	1037.60
X PANEL ASSY-BACK	1.00	✓ 324.00	20.00	259.20
X HINGE ASSY-TRUNK LID,RH	1.00	✓ 97.00	20.00	77.60
X LAMP ASSY-CENTER GARNISH	1.00	✓ 690.00	20.00	552.00
X LAMP ASSY-REAR COMB INSIDE,RH	1.00	✓ 608.00	20.00	486.40
X LAMP ASSY-REAR COMB OUTSIDE,RH	1.00	✓ 675.00	20.00	540.00
X CLIP → Supp.	10.00	1.00	20.00	8.00
Z TEXT AIG OD CLAIM. DOA : 02.04.21 SURVEYOR STEVE LKK 05.04.21 POLICY NO: 1800108062-02				

Guarantee Your Warranty, Maintain with Cycle & Carriage!

Parts	4,414.40		Nett	8,454.40
Labour	3,900.00	7% GST on	8454.40	591.81
Standard Menu	0.00			
Specialist Job	0.00		Total Payable	9,046.21
Diagnostics Job	0.00			
Sundry/Others	140.00			
Total(w/o GST)	8,454.40			

This is not an official tax invoice.
 This is a computer generated document, no signature is required.



Exceptional Journeys

INSURANCE CO. : AIG

Supplementary Parts For Registration No.: SMD 9367 H

<u>Materials</u>		<u>Cost (\$)</u>
1	Clips (x10)	10.00 <i>nec</i>
Total Materials		10.00
Less 20% discount		2.00
Total after discount		8.00
<u>Labour</u>		<u>Cost (\$)</u>
1	Replace rear end panel	400.00 <i>/</i>
2	Respray on LH rear fender	350.00 <i>/</i>
Total labour		750.00
Total amount		758.00
7% GST		53.06
Grand total		\$ 811.06

Thank You,
Yours faithfully

LOI AI TING
SENIOR OFFICER - ADMIN
KIA SERVICE CENTRE
DID : 6568 4556 / 6568 4501
FAX : 6567 5258 / 6565 1240

CAR NO: SMD9367H

WIP: 31468

(ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	Panel ASSY - Back	? / SUPP		✓ - 00	
2	Panel - FRONT ASSY RR comb Hump H66	? / SUPP		✓ - 00	
3	Bumper clip 10	? / SUPP		✓ - RC	
4	BEAM - RR Bumper	? / SUPP		✓ - RR	
5	TRUNK Lock	? / SUPP		✓ - RT	Steve 7/4/21
6		? / SUPP			
7		? / SUPP			
8	renew Panel ASSY \$400	? / SUPP		✓	
9	Paint work part LNR Fender \$135	? / SUPP		✓	
10	Repair working box = 1 day	? / SUPP		✓	
11	Toluene day	? / SUPP			
12		? / SUPP			
13		? / SUPP			
14		? / SUPP			
15		? / SUPP			
16		? / SUPP			
17		? / SUPP			
18		? / SUPP			
19		? / SUPP			
20		? / SUPP			

DATE	TAKEN BY
7/4/21	Steve

MODEL: Cerato 1.6 SX

SURVEYOR: Steve - Nuk

PHOTO BEFORE PAINT

PHOTO AFTER PAINT

PHOTO OF MOUNT TO CELLETE BENCH

REMOVE AND INSTALL ENGINE

REMOVE AND INSTALL DASHBOARD

REMOVE & INSTALL FUEL TANK

PHOTO UNDERCARRIAGE PARTS



Fault Code Searching

Rescan

Erase All DTC

Go to DTC

Save



12/12

System	Status	Result
CLU	No Current DTC	Good
IBU-BC M	No Current DTC	Good
IBU-SM K	No Current DTC	Good
PSM	No Current DTC	Good
WPC	No Current DTC	Good
ICU	No Current DTC	Good

System	DTC	Description	State
No Current DTC			

S/W Ver. M-E-K-01-00-0243

VCI Ver. 02.51

ECU Ver. M-E-K-01-00-0184

OS Ver. Android 10