



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV10071/MR Lee Si Yang, Samuel Reg No/Reg Date SML8504T*KC17/ 07/06/201 Date In/Mileage 03/04/2021/ 0 Chassis No KNAF3416MK5044995 Engine No G4FGKH737946 Make/Model KIA/CERATO 1.6 A SR SX G335 Colour/Trim B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	05/04/2021/ 14:21	QUK	282 / Kevin Leong	31467

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE FRT BUMPER, BONNET, BOTH FRT FENDER, SUPPORT & AFFECTED AREA REPAIR ON FRT RH DOOR	2 1/2	X 400		1000 3600.00
E PNT98000 PAINT WORK ON FRT BUMPER, BONNET, BOTH FRT FENDER & FRT RH DOOR	5	X 350		1750.00
E PNT88000 REMOVE & INSTALL RADIATOR, CONDENSER FOR FACILITATE REPAIR				120.00
M SUNDRY TO TOP UP AIRCON GAS				80.00
M SUNDRY PERFORM RUST PREVENTION				120.00
A 33900099 REPLACE FRT UNDERCARRIAGE				400.00
A WHEELALIGNMENTBP To Conduct Computerize Full Wheel Alignment				120.00
M SUNDRY TO TRANSFER FRT RH RIM INCLUDING BALANCING				30.00
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				120.00
M SUNDRY TO APPLY ZERTONA COATING (pront Seller Agreed)				400.00
M SUNDRY SUNDRIES				90 50.00
M LAMP ASSY-HEAD, LH	1.00	2210.00	20.00	1768.00
M HORN ASSY-LOW PITCH	1.00	74.00	20.00	59.20
M PANEL ASSY-HOOD	1.00	1502.00	20.00	1201.60
M HINGE ASSY-HOOD, Rn	1.00	43.00	20.00	34.40
M HINGE ASSY-HOOD, LH	1.00	43.00	20.00	34.40
M PANEL-FENDER, LH	1.00	430.00	20.00	344.00
M INSULATOR-FENDER LH	1.00	27.00	20.00	21.60

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV10071/MR Lee Si Yang, Samuel Reg No/Reg Date SML8504T*KC17/ 07/06/201 Date In/Mileage 03/04/2021/ 0 Chassis No KNAF3416MK5044995 Engine No G4FGKH737946 Make/Model KIA/CERATO 1.6 A SR SX G335 Colour/Trim B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	05/04/2021/ 14:21	QUK	282 / Kevin Leong	31467			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	CARRIER ASSY-FRONT END MODULE	1.00	675.00	20.00	540.00			
M	ARM COMPLETE-FR LWR,LH	1.00	286.00	20.00	228.80			
M	KNUCKLE-FRONT AXLE,LH	1.00	350.00	20.00	280.00			
M	HUB ASSY-FR WHEEL	1.00	436.00	20.00	348.80			
M	GEAR ASSY-STEERING	1.00	770.00	20.00	616.00			
M	STRUT ASSY-FR,LH	1.00	280.00	20.00	224.00			
M	PAD-FRONT SPRING,UPR	1.00	11.00	20.00	8.80			
M	PAD-FRONT SPRING,LWR	1.00	23.00	20.00	18.40			
M	INSULATOR ASSY-STRUT	1.00	85.00	20.00	68.00			
M	BRACKET-FR BUMPER UPR SIDE MTG	1.00	22.00	20.00	17.60			
M	AIR DUCT-FR BUMPER,LH	1.00	14.00	20.00	11.20			
M	ABSORBER-FRONT BUMPER ENERGY	1.00	84.00	20.00	67.20			
M	LAMP ASSY-SIDE REPEATER,LH	1.00	143.00	20.00	114.40			
M	COVER-FR BUMPER	1.00	633.00	20.00	506.40			
M	GRILLE-FRONT BUMPER	1.00	485.00	20.00	388.00			
M	MOULDING-FRONT BUMPER,LH	1.00	216.00	20.00	172.80			
M	GUARD ASSY-FRONT WHEEL,LH	1.00	95.00	20.00	76.00			
M	ORNAMENT-KIA NO.115	1.00	32.00	20.00	25.60			
M	WHEEL ASSY-ALUMINIUM	1.00	926.00	20.00	740.80			
M	PANEL-FENDER,RH	1.00	430.00	20.00	344.00			

Steve CLKK) 00-164 AL
5/4/21, 3:30pm
Express - ?
PIP
My Bel Spy
11 & 4y

LKK Auto Consultants hence notify the Reparer of the following:
Confirm & accepted by
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
Authorized signatory and company stamp

Nett 15,080.00
7% GST on 15080.00 1055.60
Total Payable 16,135.60

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.